

Harwood CAO R1-2009-0128 Attachment

The following pictures and captions depict onsite conditions during the Regional Board 11/03 inspection.



Bare dirt in vicinity of settling ponds



Unimpeded flow of sediments from finished lumber storage yard into settling ponds



Settling ponds full of sediment



Equipment strewn throughout yard, some leaking oil



Poor housekeeping



Sediments and hydrocarbons discharging unimpeded into open drop inlets throughout site.



Scrap metal and rotting wood chip piles



Formerly interior drains now exposed due to fires



Buck Creek, tributary to Eel River, which bisects Harwood site



Sediment discharges into drop inlets in various locations onsite



Fire debris – All discharge either directly to Buck Creek or to settling ponds



Potential dioxin contamination due to fire



Drums containing unknown substances



Fire debris



Sediments discharging to culvert under sawmill