



Table of Contents

Contents	i
List of Figures	iii
List of Tables	viii
Introduction	
Foreword	ix
Author's Remarks	xiii
Closing Remarks	xiv
Chapter 1	
The Early Years (Pre 1975)	1.1
Much Discussion, But Little Action	1.1
The First Pumping and Treatment Facilities	1.7
Chapter 2	
Documenting the Problem (Mid/Late 1970's)	2.1
Water Quality Monitoring	2.1
Regional Board Monitoring Program	2.11
New River Posting	2.19
Chapter 3	
Water Quality Standards (Late 1970's, Mid-1980's)	3.1
Arguing for the Standards	3.1
Treaty Minute No. 261	3.9
Treaty Minute No. 264 (The Standards)	3.15
The Treaty Violations	3.17
Chapter 4	
Changing of the Guard (Mid 1980's)	4.1
An Unannounced Visit	4.1
The Binational New River Inspections	4.27
Chapter 5	
A Cooperative Approach (Late 1980's)	5.1
Minute No. 274 (Adding Pumping/Treatment Works)	5.1
Treaty Minute No. 288	5.27
Chapter 6	
A U.S./Mexico Partnership (Early/Mid 1990's)	6.1
Working Towards Problem Solution	6.1
The "Quick Fixes" Program	6.23



Chapter 7

The Road Ahead (Mid/Late 1990's)	7.1
The Industrial Discharges	7.1
Mexicali II	7.11
The Quick Fixes--Phase II?	7.21

Appendix A

Mexicali Wastewater Data	A.1
---	------------

Appendix B

New River Water Quality Data	B.1
---	------------

List of Figures

Figure I-1: Salton Sea Watershed.....	.xi
Figure I-2: Mexicali Metropolitan and Sewage Service Areas.....	.xiii
Figure 1: New River at International Boundary (1962).....	1.4
Figure 2: Pumping Plant No. 2 (Dec 1964).....	1.7
Figures 3- 6: Mexicali's sewage collection and treatment system (Jun 1969).....	1.10
Figures 7-11: Pumping Plant No. 1 (Jul 1970).....	1.13
Figure 12: Mexicali (Jul 1975).....	1.16
Figure 13: Slaughterhouse discharge into New River (Jul 1975).....	1.16
Figure 14: Discharge from Drain 134 into New River (Jul 1975).....	1.16
Figure 15: Discharge from North Collector into Drain 134 (Jul 1975).....	1.17
Figure 16: Sample of New River water at International Boundary (1975).....	2.1
Figure 17: Drain 134 (Aug 1975).....	2.1
Figure 18: Outhouse over the New River (Aug 1975).....	2.2
Figure 19: Raw sewage spill from North Collector (Aug 1975).....	2.2
Figures 20-22: Raw sewage spills into New River (Aug 1975).....	2.3
Figure 23: Discharge from a soap factory to New River (Aug 1975).....	2.4
Figures 24-27: Raw sewage from residential development (Aug 1975).....	2.7
Figures 28-31: Discharges of wastes into Drain 134 (Aug 1975).....	2.8
Figures 32-35: The Mexicali municipal dump (Aug 1975).....	2.9
Figure 36: New River emptying into Salton Sea (Aug 1977).....	2.11
Figure 37: Soap factory (Apr 1978).....	2.12
Figure 38: Overview of Mexicali's sewage treatment lagoon (Apr 1978).....	2.15
Figure 39: Discharge of industrial wastewater to Drain 134 (May 1978).....	2.15
Figure 40: Slug from soap factory (Aug 1975).....	2.20
Figure 41: Bypass from North Collector to Drain 134 (May 1978).....	3.1
Figures 42-43: Effluent from Mexicali's lagoons. (Apr 1978).....	3.4
Figure 44: Overflow of raw sewage into New River (May 1978).....	3.9
Figure 45: New River at International Boundary (May 1981).....	3.11
Figure 46: Gonzalez-Ortega sewage treatment plant (1982).....	3.15
Figure 47: Pumping Plant No. 1 (Mar 1982).....	3.17
Figure 48: Aerator units for Mexicali's sewage lagoons (Mar 1982).....	3.18
Figure 49: New River at International Boundary (Jul 1982).....	3.22
Figure 50: Conasupo plant (Nov 1982).....	4.1
Figure 51: Discharge from Conasupo plant (Nov 1982).....	4.1

LIST OF FIGURES

Figure 52: Water sample from New River (Aug 1978)	4.2
Figure 53: Mexicali Drain (Jul 1983)	4.3
Figure 54: Septage hauler (Jul 1983)	4.4
Figure 55: Discharge from septage hauler (Jul 1983)	4.4
Figure 56: Discharge from Quimica Organica (Jul 1983)	4.5
Figure 57: Fabrica de Papel San Francisco, SA de CV (Jul 1983)	4.6
Figure 58: Discharge from Fabrica de Papel San Francisco (Jul 1983)	4.6
Figure 59: Mexicali City dump (Jul 1983)	4.6
Figure 60: Drains tributary to New River (Jul 1983)	4.6
Figure 61: Discharge from Hog farm into New River tributary (Jul 1983)	4.7
Figure 62: Confined animal facilities by New River tributaries (Jul 1983)	4.7
Figure 63: Discharge from slaughterhouse (Jul 1983)	4.8
Figure 64: Discharge from Qumica Organica (Jul 1983)	4.9
Figures 65-66: A tributary of the Mexicali Drain (Jul 1983)	4.10
Figure 67: Discharge from Sociedad Coperativa LEA (1986)	4.19
Figures 68-69: Mexicali City dump (Jun 1986)	4.28
Figures 70-71: Cerro Prieto geothermal field (Jan 1986)	4.29
Figure 72-73: Wastewater from Cerro Prieto geothermal field (Jan 1986)	4.30
Figure 74: Effluent from Mexicali lagoons (Nov 1986)	4.30
Figure 75: Gonzalez-Ortega sewage treatment lagoons (Nov 1986)	5.1
Figure 76: Sesame seed processing facility (Nov 1986)	5.1
Figure 77: Discharge from City slaughterhouse (Nov 1986)	5.2
Figure 78: Pumping Plant No. 1 (Nov 1986)	5.2
Figure 79: Pumping Plant No. 2 (Mar 1987)	5.2
Figure 80: Effluent from Mexicali lagoons (Mar 1987)	5.3
Figure 81: Mexicali's lagoons (Mar 1987)	5.3
Figure 82: Sewage lagoon expansion at Gonzalez-Ortega (Jul 1987)	5.4
Figure 83: Discharge from Conasupo (Jul 1987)	5.4
Figure 84: Quimica Organica (Jul 1987)	5.5
Figure 85: Fabrica de Papel de S.F. (Jul 1987)	5.6
Figure 86: Discharge from Fabrica de Papel de S.F. (Feb 1988)	5.6
Figure 87: Conasupo plant (Apr 1988)	5.7
Figure 88: Discharge from Conasupo (Apr 1988)	5.7
Figure 89: Pumping Plant No. 1 (Feb 1988)	5.8
Figure 90: Effluent from Mexicali lagoons (Apr 1988)	5.8
Figure 91: Overflowing sewer manhole (Apr 1988)	5.8
Figure 92: Raw sewage bypassing at Pumping Plant No. 2 (Oct 1988)	5.9

LIST OF FIGURES

Figure 93: Raw sewage coursing through Mexicali streets (Oct 1988)5.9

Figures 94-95: North Collector sewer pipe replacement project (Jun 1988)5.10

Figure 96: Construction of Pumping Plant No. 1A (Oct 1988)5.10

Figure 97: New River at International Boundary (Oct 1988)5.11

Figures 98 and 99: Renovation of Pumping Plant No. 2 (Oct 1988)5.12

Figures 100 and 101: North Collector (Oct 1988)5.12

Figures 102-103: Raw sewage spill at the International Boundary (Mar 1988) ...5.13

Figure 104: Screen at Mexicali effluent outfall to New River (Jul 1989)5.14

Figures 105-106: Installation of new sewer pipeline by A. Reforma (Jul 1989) ..5.15

Figure 107: Construction of Pumping Plant No. 1A (Jul 1989)5.15

Figure 108: Discharge from City slaughterhouse (Nov 1990)5.17

Figure 109: Worn out pump motor at Pumping Plant No. 1 (Nov 1990)5.17

Figure 110: Mexicali Drain (Jul 1991)5.19

Figure 111: New River at International Boundary (Jul 1991)5.20

Figure 112: Discharge from Conasupo plant (Jul 1991)5.20

Figure 113: Discharge from Quimica Organica (Jul 1991)5.20

Figure 114: Effluent from Gonzalez-Ortega treatment lagoons (Jul 1991)5.20

Figure 115: Discharge from City slaughterhouse (Jul 1991)5.21

Figure 116: A New River tributary drain (Jul 1991)5.21

Figure 117: Effluent from treatment lagoons (Jul 1991)5.21

Figure 118: New River at Calexico (Jul 1991)5.21

Figure 119: Closure of the City dump in Mexicali Drain (Jul 1991)5.22

Figure 120: Mexicali Drain at San Luis Highway crossing (Aug 1992)5.23

Figures 121 through 124: Raw sewage spills into the New River (Aug 1992) ...5.24

Figure 125: A project to place section of pipe along Drain 134 (Aug 1992)5.25

Figure 126: Bypass from North Collector to Drain 134 (Aug 1992)5.25

Figure 127: Fish sampling of New River at International Boundary (Dec 1992) ..5.27

Figure 128: Discharge from Kenmex (Mar 1993)5.28

Figure 129: One of several discharge points from Vitromex (Mar 1993)5.28

Figure 130: Tour of Mexicali (Apr 1993)5.29

Figures 131-132: Drums of chemicals waste in Cierro Prieto area (May 1993) ...5.30

Figure 133: Pump repairs underway at Pumping Plant No. 1 (Apr 1994)6.3

Figure 134: Effluent from Mexicali lagoons (Apr 1994)6.4

Figure 135: Mexicali lagoons (Apr 1994)6.4

Figure 136: Terminus of newly constructed Mexicali II collector (Apr 1994)6.5

Figure 137: Gonzalez-Ortega Pumping Plant (Apr 1994)6.5

Figures 138 and 139: Pipe corrosion at Pumping Plant No.1 (Aug 1994)6.7

LIST OF FIGURES

Figure 140: Bypassing of raw sewage from South Collector (Apr 1994)	6.8
Figure 141: Bypass of raw sewage from Pumping Plant No. 1 (Aug 1994)	6.8
Figure 142: Bypass of raw sewage at Av. Reforma (Aug 1994)	6.8
Figure 143: Bypass of raw sewage from Gonzalez-Ortega (Aug 1994)	6.8
Figure 144: Bacteria slime and Mexicali Drain (Aug 1994)	6.9
Figure 145: Influent to Gonzalez-Ortega treatment facility (Aug 1994)	6.9
Figure 146: Mexicali Drain near confluence with New River (Aug 1994)	6.9
Figure 147: A primary treatment lagoon (Aug 1994)	6.9
Figure 148: Development in upper Mexicali Drain watershed (Oct 1994)	6.10
Figure 149: Fabrica de Papel de S.F. plant (Oct 1994)	6.10
Figure 150: Sludge disposal at Fabrica de Papel de S.F. plant (Oct 1994)	6.10
Figure 151: Siderurgica California plant (Oct 1994)	6.11
Figure 152: Discharge from Siderurgica California plant (Oct 1994)	6.11
Figure 153: Maseca plant (Oct 1994)	6.11
Figure 154: Discharge from Maseca plant (Oct 1994)	6.11
Figure 155: Cleanout of one of Mexicali's lagoons (Nov 1994)	6.12
Figure 156: Sewer cleanout underway at Av. Reforma (Nov 1994)	6.12
Figure 157: Repairs at Gonzalez-Ortega pumping station (Feb 1995)	6.12
Figure 158: Discharge from the Quipac facility (Feb 1995)	6.13
Figure 159: Mexicali Drain at San Felipe Highway crossing (Feb 1995)	6.13
Figure 160: Effluent from Mexicali lagoons (Feb 1995)	6.13
Figure 161: Outhouse discharging to Mexicali Drain (Feb 1995)	6.14
Figure 162: Discharge from Mexicali II Collector to Mexicali Drain (Mar 1995) ..	6.14
Figure 163: Discharge from Hidrogenadora Nacional (Mar 1995)	6.16
Figure 164: Effluent from Mexicali lagoons (Apr 1995)	6.17
Figure 165: Discharge of raw sewage near Pumping Plant No. 2 (Apr 1995)	6.19
Figure 166: Mexicali Drain at Highway 2 crossing (Apr 1995)	6.19
Figure 167: Discharge from Hidrogenadora Nacional (Apr 1995)	6.19
Figure 168: Gonzalez-Ortega lagoons (Apr 1995)	6.19
Figure 169: Bypass to New River by Pumping Plant No. 2 (Apr 1995)	6.19
Figure 170: Raw sewage discharging to New River via storm drain (May 1995) ..	6.20
Figure 171: Mexicali Drain at Highway 2 crossing (May 1995)	6.20
Figure 172: Raw sewage spill to New River (Jun 1995)	6.20
Figure 173: Discharge from Quipac facility (Jul 1995)	6.20
Figure 174: Sampling of New River at Calexico (Aug 1995)	6.21
Figure 175: Check valves and manifold for Pumping Plant No. 1A (May 1995) ..	6.23
Figure 176: Replacement of concrete pipe on the South Collector (Aug 1995) ..	6.24

LIST OF FIGURES

Figure 177: Sewer line cleanout for slip pipe installation (Aug 1995)6.25

Figure 178: Replacement of concrete pipe with PVC pipe (Apr 1995)6.26

Figure 179: PVC pipe being delivered for sewer line replacement (Apr 1995)6.26

Figure 180: Sewer cleaning unit provided for the Mexicali effort (Apr 1995)6.26

Figure 181: Repairs underway at Pumping Plant No. 1 (Apr 1995)6.26

Figure 182: Drain 134 emptying into New River (Aug 1995)6.27

Figure 183: Mexicali Drain at Highway 2 (Jan 1995)6.27

Figure 184: New River floodplain (Aug 1995)6.28

Figures 185-186: New sewer line for Mexicali II collection system (Oct 1996)6.29

Figure 187: Bypass at Pumping Plant No. 2 (Oct 1996)6.30

Figure 188: Replacement of concrete pipe on the South Collector (Jan 1997) .. .6.30

Figure 189: New River at International Boundary (Mar 1997)6.31

Figure 190: Mexicali II force main installation project (Aug 1997)6.32

Figure 191: Pumping Plant No. 1 (Aug 1997)6.30

Figure 192 - Tula West Drain downstream of Hidrogenadora Nacional (Jan 1998) .7.2

Figure 193 - New industry (Jan 1998)7.3

Figure 194 - Zaragoza lagoon (Jan 1998)7.8

Figure 195 - SewerVac Truck (Jul 1998)7.8

Figure 196 - Standby generator at Pumping Plant No. 1 (Mar 1998)7.9

Figure 197 - Pumping Plant No. 3 (new pump in gray) (Mar 1998)7.9

Figure 198 - Drain 134 discharging into the New River (Mar 1998)7.10

Figure 199 - Sewage force main for Mexicali II WWTF (Feb 1998)7.11

Figure 200 - Proposed site for Mexicali II WWTF (Oct 1997)7.12

Figure 201 - Discharge from Slaughterhouse (Oct 1997)7.12

Figure 202 - Pumping Plant No. 17.13

Figure 203 - Bypass from Lift Station into New River (Jan 1998)7.13

Figure 204 - Encasement of Tula West Drain (Jan 1998)7.14

Figure 205 - New River upstream of Drain 134 (Jan 1998).....7.14

Figure 206 - Alamo River weir (Jan 1998)7.15

Figure 207 - Discharge from Hidrogenadora Nacional (Mar 1998)7.16

Figure 208 - Gonzalez-Ortega primary lagoon (Mar 1998)7.17

Figure 209 - New River by Pumping Plant No. 2 (Jun 1998)7.18

Figure 210 - Construction of cistern at Pumping Plant No. 3 (Jul 1998)7.23

Figure Nos. 211 through 213: Pumping Plants No. 1, 2, and 3 (Jul 1998)7.24

Figure 214 - South Collector repairs underway (Jul 1998)7.24

Figure 215 - Trend Monitoring for Bacteria at International Boundary..... B.3

Figure 216 - Trend Monitoring for BOD at International Boundary..... B.3

List of Tables

Table 1 - Sewage Flows for Mexicali	7.5
Table 2 - Conventional Pollutant Concentrations in Raw Sewage	7.6
Table 3 - Zaragoza Effluent Acute Toxicity	7.6
Table 4 - Gonzalez-Ortega Effluent Acute Toxicity	7.6
Table A-1 - Zaragoza Influent Field Parameter Concentrations	A.3
Table A-2 - Zaragoza Influent Conventional Pollutant Concentrations	A.3
Table A-3 - Zaragoza Influent Metal Concentrations	A.4
Table A-4 - Zaragoza Influent Bacteria Concentrations	A.4
Table A-5 - Zaragoza Effluent Field Parameter Concentrations	A.4
Table A-6 - Zaragoza Effluent Conventional Pollutant Concentrations	A.5
Table A-7 - Zaragoza Effluent Metal Concentrations	A.5
Table A-8 - Zaragoza Effluent Bacteria Concentrations	A.6
Table A-9 - Gonzalez-Ortega Influent Field Parameter Concentrations	A.6
Table A-10 - Gonzalez-Ortega Influent Conventional Pollutant Concentrations	A.6
Table A-11 - Gonzalez-Ortega Influent Metal Concentrations	A.7
Table A-12 - Gonzalez-Ortega Influent Bacteria Concentrations	A.7
Table A-13 - Gonzalez-Ortega Effluent Field Parameter Concentrations	A.7
Table A-14 - Gonzalez-Ortega Effluent Conventional Pollutant Concentrations	A.8
Table A-15 - Gonzalez-Ortega Effluent Metal Concentrations	A.8
Table A-16 - Gonzalez-Ortega Effluent Bacteria Concentrations	A.9
Table A-17 - Xochimilco Drain Conventional Pollutant Concentrations	A.9
Table A-18 - Xochimilco Drain Metal Concentrations	A.10
Table A-19 - Xochimilco Drain Bacteria Concentrations	A.10
Table B-1 - Conventional Pollutants in New River at International Boundary	B.4
Table B-2 - Trace Metals in New River at International Boundary	B.4
Table B-3 - Turbidity in New River at International Boundary	B.5
Table B-4 - Bacteria in New River at International Boundary	B.5
Table B-5 - Volatile Organic Constituents in New River at International Boundary	B.6