

Photo Log for Greg Gearheart on January 13, 2010
San Leandro Plastics Facilities
San Leandro, CA



Figure 1 – Sampling near Northern Outfall on Neptune Drive



Figure 2 - General Area of Northern Outfall on Neptune Drive



Figure 3 - Plastic Pellets and Debris in the Tidal Area near Northern Outfall on Neptune Drive



Figure 4 - Sampling the Northern Outfall Area on Neptune Drive



Figure 5 - Plastic Pellets in the Pickleweed at Northern Outfall on Neptune Drive



Figure 6 - Plastic Pellets in the San Francisco Bay Water Near Northern Outfall on Neptune Drive



Figure 7 - Plastic Pellets on Paved Area Near Rail Siding West of Metro/Uni Poly Facility on Williams Street




Figure 8 - Plastic Pellets on Paved Area Near Rail Siding West of Metro/Uni Poly Facility on Williams Street



Figure 9 - Plastic Pellets on Paved Area Near Rail Siding West of Metro/Uni Poly Facility on Williams Street



Figure 10 - Plastic Pellets on Paved Area Near Rail Siding West of Metro/Uni Poly Facility on Williams Street



Figure 11 - Plastic Pellets under Hopper Car Valve on Rail Siding West of Metro/Uni Poly Facility on Williams Street




Figure 12 – Hose Assemblies and Hopper Car on Rail Siding West of Metro/Uni Poly Facility on Williams Street



Figure 13 - Plastic Pieces, Pellets and Debris Resting on Top of and Near Drain Inlet on Western Side of Metro/Uni Poly Facility on Williams Street



Figure 14 - Plastic Pieces, Pellets and Debris Rail Sidings North of Metro/Uni Poly Facility on Williams Street



Figure 15 -Plastic Pieces, Pellets and Debris Rail Sidings North of Metro/Uni Poly Facility on Williams Street



Figure 16 - Plastic Pieces, Pellets and Debris Rail Sidings North of Metro/Uni Poly Facility on Williams Street




Figure 17 - Debris and Litter on Loading Docks of Metro/Uni Poly Facility on Williams Street



Figure 18 - A Modified Valve Seal Used to Try and Control Plastic Pellet Losses from Valve on Hopper Cars in Rail Siding Area West of Metro/Uni Poly Facility on Williams Street



Figure 19 - Plastic Pellet Transfer from Hopper Cars to Internal Processes in Rail Siding Area West of Metro/Uni Poly Facility on Williams Street



Figure 20 - Loading Dock at Kaneka Facility on Pulverosa Drive



Figure 21 - Plastic Pellets Under Loading Dock at Kaneka Facility on Pulverosa Drive



Figure 22 -Plastic Pellets Under Loading Dock at Kaneka Facility on Pulverosa Drive



Figure 23 - Plastic Pellets in Drain Inlet and Storm Water in Parking Lot at Kaneka Facility on Pulverosa Drive