

1. Looking North-East, towards the northern lake's dam embankment. In this photo, the wooden dock is centered in front of the property line between lots 71 and 72.



11/13/2009

HLE EXHIBIT 41

2. Looking East, across lot 70 to lot 71. The wooden fence is on the property line between lots 71 and 72.




3. Looking North-East, across lot 70 to lot 71. The wooden fence is on the property line between lots 71 and 72.



11/13/2009

HLE EXHIBIT 41

4. Looking North-East, down the property line between lots 71 and 72
Lot 71 is on the left, lot 72 is on the right.



11/13/2009

HLE EXHIBIT 41

5. Looking North, across lot 72. The wooden fence is on the property line between lots 71 and 72.



11/13/2009

HLE EXHIBIT 41

6. Looking North, towards lot 72. The 15" culvert in the photo was installed as part of the original lake/dam construction. See "Improvement Plans for Hidden Lakes Unit No.2 Lake Construction & Details" Sheet 7 of 12 (Typical Section of Dam).



11/13/2009

HLE EXHIBIT 41

7. Looking South at the culvert opening on the northern lake's dam embankment, near the water's edge.



11/13/2009

HLE EXHIBIT 41

8. Looking South-East, up a meandering drainage easement (MDE) entering the northern lake from lot 81 and under Gina Lane.



9. Looking North from the Gina Lane common area towards the northern lake's dam embankment.



11/13/2009

HLE EXHIBIT 41


10. Looking South-West from the northern lake at the southern lake in the distance.



11/13/2009

HLE EXHIBIT 41

11. Looking North at the northern lake's overflow weir.



12. Looking North at the northern lake's overflow weir (close-up).



11/13/2009

HLE EXHIBIT 41

13. Looking South-West down the overflow creek from the northern lake to the southern lake.



14. Looking South-West at the southern lake. Access boxes in the ground are for the lake water feed solenoid valve and water meter.




11/13/2009

HLE EXHIBIT 41

15. Looking South-West at the southern lake. Access box is for the water level float switch that controls the lake water feed solenoid valve.




16. Looking inside the lake pumphouse. The circulation pump operates a few hours each day during the dry season to circulate water from the southern lake to the northern end of the northern lake. Water then overflows the northern lake's overflow weir and returns to the southern lake.



11/13/2009

HLE EXHIBIT 41

17. Looking South-West across the southern lake at the southern lake's overflow culvert inlet.



11/13/2009

HLE EXHIBIT 41


18. Looking South at the southern lake's overflow culvert inlet (close-up).



11/13/2009

HLE EXHIBIT 41

19. Looking East at the southern lake's overflow culvert outlet (close-up)



11/13/2009

20. Looking South-West down a drainage swale on lot 30 along the western side of Hidden Lakes Drive (this swale provides drainage for the southern lake's overflow culvert).



11/13/2009


21. Looking North across the southern lake, at the fountain. The fountain (recently re-paired) operates during daylight hours (photocell control).



12/28/2009

HLE EXHIBIT 41


22. Looking North on Hidden Lakes Drive East, from a point adjacent to lot 76.



11/13/2009

HLE EXHIBIT 41

23. Looking South-West on Lakes Drive East, at the property line retaining wall between lot 74 and lot 73.



11/13/2009


HLE EXHIBIT 41

24. Looking South-West on Lakes Drive East at lot 73 (note additional elevation changes).



11/13/2009

25. Looking North on Hidden Lakes Drive East, from a point adjacent to lot 73.



11/13/2009

HLE EXHIBIT 41

26. Looking South on Hidden Lakes Drive East, from the intersection of Jon Way, at the retaining wall between lot 73 and 72.



11/13/2009

HLE EXHIBIT 41


27. Looking South-West on Hidden Lakes Drive East (intersection of Jon Way) at the meandering drainage easement (MDE) coming from lot 72, along with a rock lined swale along the front edge of lot 72, joining together and entering a culvert going underneath the intersection. This drainage culvert is shown at this location on "Improvement Plans for Hidden Lakes Unit No.2" sheet 4 of 12.



11/13/2009

HLE EXHIBIT 41

28. Looking West on Hidden Lakes Drive East, from the intersection of Jon Way, at the meandering drainage easement (MDE) along the



29. Looking North on Hidden Lakes Drive East (intersection of Jon Way) at three water valve access boxes in the street. These valve boxes seep groundwater onto the street (typically from January thru July) and cause rust stains on the pavement.



11/13/2009

HLE EXHIBIT 41

30. Looking South on Hidden Lakes Drive East (intersection of Jon Way) at the property line between lot 71 and lot 72.



11/13/2009

HLE EXHIBIT 41

31. Looking South-East on Jon Way (intersection of Hidden Lakes Drive East) at the property line between lot 71 and lot 72. A drainage culvert is shown at this location on "Improvement Plans for Hidden Lakes Unit No.2" sheet 4 of 12.



11/13/2009

HLE EXHIBIT 41

32. Looking South-West on Jon Way (intersection of Hidden Lakes Drive East) at lot 71.



11/13/2009

HLE EXHIBIT 41

33. Looking South-West on Jon Way (near intersection of Hidden Lake Drive East) at the corner of lot 71.

