Figure 7: Fillmore WRP Process Flow Diagram (2 of 2)