



Figure 8: Site Map Showing Contamination Plumes

THUNDERBOLT WOOD TREATING CO., INC.
 3400 Patterson Road Riverbank, CA
 Site Map showing Monitoring Wells, Soil Borings,
 Extraction Well, Sumps and
 Total Dissolved Chromium in Unconfined Ground Water



- ⊕ Monitoring Well
- ⊙ Previous Soil Borings
- ⊙ Soil Borings, This Investigation
- ⊕ Soil Boring & Test Extraction Well
- ⊙ Background Monitoring Well
- ⊙ Sump with Pump
- 17.0 Total Dissolved Chrome (ppb)
- Approximate Total Chrome Contaminant Plume



Drawing Reference:
 August 2010 Report of
 Waste Discharge by WHF
 Inc., Figure 8

SITE MAP
 THUNDERBOLT WOOD TREATING COMPANY, INC.
 CLASS II SURFACE IMPOUNDMENT
 STANISLAUS COUNTY

