Final

November 18, 2011

Review of
Leaking Underground Storage Tank
Cases
Not in Cleanup Fund and Open Over 15
Years

City of Los Angeles, Local Implementing Agency (LIA)

Prepared as in-kind task as part of Cooperative Agreement LS-97952501-3 between U.S. EPA Region 9 and the California State Water Resources Control Board

Table of Contents

Section	Page
Executive Summary	1
Apparent Case Status: Initial and After	2
Aging Non-CUF Case Review Summary Table	4
Attachment 1: Case Review Power Point Slides from Draft Report	17
1. T0603702575 (ARCO #1680)	
2. T0603702407 (Chevron #9-9164)	
3. T10000001120 (Lula Washington Dance Studio	
4. T0603702323 (Southern CA RTD DIV 15)	
5. T0603702122 (Shell)	
6. T0603700001 (Clara Smith)	
7. T0603700064 (Sidewalk Tree Planter Hole)	
8. T0603701011 (Arroyo Seco Park)	
9. T0603700809 (Food for Life)	
10. T0603700098 (Howard Hughes Prop)	
11. T0603700424 (Mobil #11-GM4)	
12. T0603701599 (Mobil #11-MW6)	
13. T0603700025 (Richard Sterman)	
14. T0603701641 (San Pedro Municipal Building)	
15. T0603701178 (Thrifty)	
16. T0603700037 (Unnamed Site)	
17. T0603700578 (Harding Market Company)	
18. T0603700652 (Shell)	
19. T0603700099 (South East Maint Yard)	
20. T0603701063 (United Airlines)	
21. T0603700478 (Cardlock Fuel Systems)	
22. T0603701070 (FAA)	
23. T0603701066 (Frito-Lay Inc)	
24. T0603702231 (Hye Center Market)	
25. T0603700036 (Shell)	
26. T0603701077 (Terminal 6 LAX)	
27. T0603702556 (Chevron #9-2683)	
28. T0603788711 (Ace Beverage Company)	
29. T0603702096 (Exxon)	
30. T0603701642 (Harbor District Facilities)	
31. T0603701209 (Mar Vista Central Office)	
32. T0603776617 (National Car Sales) – Duplicate with T0603768170	
33. T0603700677 (Surface Protection Inc)	
34. T0603784210 (Chevron – James, Ronald B)	

Table of Contents (Continued)

- 35. T0603797352 (Orchard Supply Hardware)
- 36. T0603738449 (J Glover Mfg Inc)
- 37. T0603737823 (LAUSD)
- 38. T0603700825 (Soto Street Facility)
- 39. T0603764849 (Anchor)
- 40. T0603790746 (Auto Rite)
- 41. T0603770957 (Greyhound Lines Inc)
- 42. T0603713919 (Jean Pierre Products Inc)
- 43. T0603786425 (Unocal Abraham Roisman)
- 44. T0603702284 (ARCO #1097)
- 45. T0603751654 (Aramark Uniform Services)
- 46. T0603746763 (Box & Gear Transmissions)
- 47. T0603701075 (Terminal #1 LAX)
- 48. T0603736969 (Worldwide Flight Services)
- 49. T0603745855 (AAA Foreign Auto Parts and Salvage Inc)
- 50. T0603789252 (Fritz Hummel) Duplicate with T0603764257
- 51. T0603790000 (LA DWP Dept of Water & Power)
- 52. T0603744598 (LAFD Fire Station 54)
- 53. T0603712781 (LAUSD North Valley Occupational Center)
- 54. T0603788360 (LAUSD Safety Section Bus Div)
- 55. T0603712547 (Magness Petroleum Company)
- 56. T0603710593 (Mobil Cardenas, Richard)
- 57. T0603776777 (Reverest Rooding/Waterproofing Co)
- 58. T0603715897 (Salvation Army Thrift Store)
- 59. T0603702447 (Crown Cork & Seal Company Inc)
- 60. T0603740056 (J&S Precision Auto (FMR Arax Gas Station)
- 61. T0603745944 (LAFD Fire Station 80)
- 62. T0603740210 (Rent-a-Bin)
- 63. T0603790524 (Resort Rent a Car)
- 64. T0603700781 (Tune Up Masters Shop #10)
- 65. T0603786262 (Limousine Express Inc)
- 66. T0603790800 (Mission Hills Ford)
- 67. T0603799502 (Robertson Branch Library)
- 68. T0603700073 (South Bay Corp)
- 69. T0603759024 (Builders Sheet Metal Inc)
- 70. T0603769587 (California State University Facility)
- 71. T0603796838 (Darling-Delaware)
- 72. T0603700457 (Dept of Transportation)
- 73. T0603702450 (Gas S/S)
- 74. T0603794280 (LAFD Fire Station 95)
- 75. T0603721107 (Ray's Market)

Table of Contents (Continued)

- 76. T0603755343 (Rotocraft Support Inc)
- 77. T0603702409 (Chevron #9-2766)
- 78. T0603766799 (Dept of General Service of State)
- 79. T0603730842 (Dexol Industries)
- 80. T0603737703 (LAPD Hollenbeck Division)
- 81. T0603700534 (Piper Technical Center)
- 82. T0603746785 (Driz Knitting Mills)
- 83. T0603791363 (Matson Terminal)
- 84. T0603701315 (Mobil #11-GQG)
- 85. T0603729309 (Verizon Wireless)
- 86. T0603786190 (Texaco Keeble, Robert)
- 87. T0603743780 (Tierno's General Fabrication)
- 88. T0603739581 (F&S Auto Care)
- 89. T0603755288 (Normandie Plaza)
- 90. T0603700853 (Norris Cancer Hospital)
- 91. T0603782010 (Washington Mutual Bank)
- 92. T0603774420 (A-Abbey Metals International)
- 93. T0603705678 (California Target Station #49)
- 94. T0603741517 (Mendoza Service Inc)
- 95. T0603708034 (ARCO #5033)
- 96. T0603759109 (Auto Park 18)
- 97. T0603702241 (GVD Commercial Properties)
- 98. T0603705142 (LA Co FD Fire Station #046)
- 99. T0603727663 (Pan American World Airways, Inc)
- 100. T0603743170 (Penhall Company)
- 101. T0603700906 (Stolen Base Cleaners)
- 102. T0603781181 (Studio Services Inc)
- 103. T0603707597 (Sunshine Truck Stop Inc.)
- 104. T0603787881 (Tune-Ups Plus) Duplicate with T0603725845

Executive Summary

The Draft version of this report was submitted on October 22, 2010, with a request for a follow-up meeting and input from City of Los Angeles Local Implementing Agency (LA City) into the "Next Steps for Agency" column of the case cleanup status spreadsheet.

LA City met with Sullivan International Group, Inc. (Sullivan) staff in person on October 24 and 25, 2011 to discuss the draft report and their next steps for each case. Sullivan staff have been working with LA City cooperatively over the last few months to review their hard files, provide updates to LA City caseworkers, and upload important documents to GeoTracker. LA City has made great progress thus far with the aging Non-CUF cases. Since the review in October 2010, 15 cases have been closed, 21 cases are now on track, and 2 cases are on Track to be closed within a few months: Lula Washington Dance Studio (T10000001120) and FAA (T0603701070). Note that only a few administrative items remain before FAA can be closed. As part of the file review and GeoTracker data cleanup process, LA City has deleted eight (8) cases in GeoTracker that should have not been entered into GeoTracker in the first place. The current status for these cases are noted as "Erroneous Case/Deleted".

This task is still in progress and for that reason some of the aging Non-CUF cases are still not updated within this report. It is understood that LA City and Sullivan staff will continue to review these aging Non-CUF cases until all cases have been reviewed and updated. This final version of the document represents the status of the cases up until October 25, 2011. It is anticipated that a separate Non-CUF document will be submitted in the future that will capture all work that LA City and Sullivan has done.

City of Los Angeles LIA

Apparent Case Status: Initial and After

TOTAL NUMBER OF CASES REVIEWED = 104


NUMBER OF ACTIVE LUST CASES ON NOVEMBER 1, 2010 = 214 CASES


DRAFT REVIEW REPORT PREPARED AND SENT TO AGENCY ON OCTOBER 22, 2010

MEETING WITH AGENCY ON OCTOBER 24 and 25, 2011

APPARENT STATUS OF CASES REVIEWED - INITIAL REVIEW AND AFTER MEETING TO DISCUSS CASES

Apparent Case Status	Initial Assessment Number of Cases (10-22-2010)	Post Meeting Assessment Number of Cases (10-25-2011)
CASE CLOSED	0	15
Appears close to completion	3	2
Appears near completion within 1-year	0	0
Appears to be on track	0	21
Appears NOT to be on track	0	0
Appears to be stuck	1	0
Unable to determine (Insufficient information in GeoTracker)	100	53
NOT FEDERAL UST CASE	0	0
OTHERS –(Erroneous Case/ Deleted, Transferred to RWQCB)	0	13





ESTIMATED STATUS IN THE CLEANUP PIPELINE?	CHANGE IN STATUS IN THE CLEANUP PIPELINE (BASED ON 10/25/11	(CASE LEAD AGENCY: CITY OF LOS ANGELES - LOCAL	GI DB90T ID	CASEWORKER	PRIMARY COC (In Geotrace.	APPARENT TYPE OF RIP	RELEASE DATE	GEOTRACKER UPDATED?	DISCUSSION NOTES FROM METING (October 25, 2011)	NEXT STEP FOR AGENCY
Appears near completion within 1-year	Appears to be on track	ARCO #1680	Т0603702575	NEAL REITZELL	Gasoline	Z - Major Oil Company	10/10/1991	Yes	A letter requesting a Remedial Action Work Plan for additional remediation was sent to RP 4/12/11. A work plan dated 7/26/11 was received by LAFD and is under review. Caseworker will contact RP's consultant to upload to GeoTracker.	Push for new/additional remedial investigation (RI)/risk assessment
Appears near completion within 1-year	Completed-Case Closed	CHEVRON #9-9164	T0603702407	ELOY LUNA	Gasoline	Z - Major Oil Company	4/8/1993	Yes	Confirmed this case has been closed.	Not Applicable
Appears near completion within 1-year	Appears close to completion	LULA WASHINGTON DANCE STUDIO	T10000001120	ELOY LUNA	Unknown	U - Unknown	4/15/1995	Yes	The caseworker confirmed that closure report has been received and will be reviewed so that closure process can be completed.	Complete closure process in 1-year (includes well decommission)
Appears to be stuck	Appears to be on track	SOUTHERN CA RTD DIV 15	T0603702323	ELOY LUNA	Multiple	G - Government Entity (include School, Hospital, Utility)	4/24/1984	Yes	Uploaded NOV and work plan approval letter dated 5/25/09 to GeoTracker. Need to follow up with RP by calling and/or sending out new letter.	Push for new/additional remedial investigation (RI)/risk assessment
Unable to determine (Insufficient information in GeoTracker)	OTHERErroneous case, Deleted	SHELL	Т0603702122	TERRENCE PALMER	Gasoline	U - Unknown	5/28/1985	Yes	No case is open with LAFD. Deleted erroneous case in GT 10/27/11.	Not Applicable
(Insufficient information in	Unable to determine (Insufficient information in GeoTracker)	CLARA SMITH	T0603700001	Not defined in GeoTracker	ISolvent	O - Other (Individual, Homes etc)	3/6/1986	No	No case is open with LAFD. Need to determine if there is a physical file and review. Case may have been created erroneously created in GT, and if so, will be deleted.	Verify if the case is warranted (i.e., is a Federal UST case)
(Insufficient information in	Unable to determine (Insufficient information in GeoTracker)	SIDEWALK TREE PLANTER HOLE	T0603700064	Not defined in GeoTracker	l Gasoline	O - Other (Individual, Homes etc)	1/27/1986	No	No case is open with LAFD. Need to determine if there is a physical file and review. Case may have been created erroneously created in GT, and if so, will be deleted.	Verify if the case is warranted (i.e., is a Federal UST case)
Unable to determine (Insufficient information in GeoTracker)	OTHERErroneous case, Deleted	ARROYO SECO PARK	T0603701011	TERRENCE PALMER	lGasoline	O - Other (Individual, Homes etc)	5/8/1986	Yes	No case is open with LAFD. Deleted erroneous case in GT 10/27/11.	Not Applicable
Unable to determine (Insufficient information in GeoTracker)	Completed-Case Closed	FOOD FOR LIFE	T0603700809	Not defined in GeoTracker	Other	S - Small Private Business	10/28/1986	Yes	Confirmed this case has been closed.	Not Applicable

								/		1
ESTIMATED STATUS IN THE CLEANUP PIPELINE?	CHANGE IN STATUS IN THE CLEANUP PIPELINE (BASED ON 10/25/11	ICASE LEAD AGENCY: CITY OF LOS ANGELES - LOCAL	^G LОВАL _{ID}	CASEWORKER	PRIMARY COC (In Geotzaci	APPARENT TYPE OF RP	RELEASE DATE	GEOTRACKER UPDATED?	DISCUSSION NOTES FROM MEETING (October 25, 2011)	NEXT STEP FOR AGENCY
Unable to determine (Insufficient information in GeoTracker)	Unable to determine (Insufficient information in GeoTracker)		T0603700098	PATRICK KILLIAN	Other	O - Other (Individual, Homes etc)	11/24/1986	No	No case is open with LAFD. Need to determine if there is a physical file and review. Case may have been created erroneously created in GT, and if so, will be deleted.	Verify if the case is warranted (i.e., is a Federal UST case)
Unable to determine (Insufficient information in GeoTracker)	Unable to determine (Insufficient information in GeoTracker)	MOBIL #11-GM4	T0603700424	ELOY LUNA	Gasoline	Z - Major Oil Company	7/18/1986	No	No case is open with LAFD. Need to determine if there is a physical file and review. Case may have been created erroneously created in GT, and if so, will be deleted.	Verify if the case is warranted (i.e., is a Federal UST case)
Unable to determine (Insufficient information in GeoTracker)	Appears to be on track	MOBIL #11-MW6	T0603701599	TERRENCE PALMER	Other	Z - Major Oil Company	11/7/1986	Yes	Letter requesting additional information dated 1/14/09 was uploaded onto GeoTracker. Need to send follow up letter.	Push for new/additional remedial investigation (RI)/risk assessment
Unable to determine (Insufficient information in GeoTracker)	Unable to determine (Insufficient information in GeoTracker)	RICHARD STERMAN	T0603700025	Not defined in GeoTracker	IC)Ther	O - Other (Individual, Homes etc)	7/17/1986	No	No case is open with LAFD. Need to determine if there is a physical file and review. Case may have been created erroneously created in GT, and if so, will be deleted.	Verify if the case is warranted (i.e., is a Federal UST case)
Unable to determine (Insufficient information in GeoTracker)	Unable to determine (Insufficient information in GeoTracker)	SAN PEDRO MUNICIPAL BUILDING	T0603701641	ELOY LUNA		G - Government Entity (include School, Hospital, Utility)	8/21/1986	No	No case is open with LAFD. Need to determine if there is a physical file and review. Case may have been created erroneously created in GT, and if so, will be deleted.	Verify if the case is warranted (i.e., is a Federal UST case)
Unable to determine (Insufficient information in GeoTracker)	Appears to be on track	THRIFTY	T0603701178	Not defined in GeoTracker	Other	Z - Major Oil Company	7/14/1986	No	A physical file was located. The caseworker spoke with the RP 7/29/11 and requested information on the case. Need to review physical file and information from RP to determine current status. Most recent materials will also be uploaded to GeoTracker. Case is possibly	Update missing GT information (data, report, unassigned caseworker etc.)
Unable to determine (Insufficient information in GeoTracker)	OTHERErroneous case, Deleted	UNNAMED SITE	T0603700037	PATRICK KILLIAN	Gasoline	U - Unknown	11/13/1986	Yes	No case is open with LAFD. Deleted erroneous case in GT 10/21/11.	Not Applicable
	Unable to determine (Insufficient information in GeoTracker)	HARDING MARKET COMPANY	т0603700578	TERRENCE PALMER	Gasoline	S - Small Private Business	2/9/1986	No	Current status is unknown. Need to review physical file to determine current case status and upload most recent material to GT.	Update missing GT information (data, report, unassigned caseworker etc.)

ESTIMATED STATUS IN THE CLEANUP PIPELINE?	CHANGE IN STATUS IN THE CLEANUP PIPELINE (BASED ON 10/25/11	ICASE LEAD AGENCY: GIT ON OR LOS ANGELES - LOCAL	GLOBAL ID	CASEWORKER	PRINARY COC (In GeoTrack.)	APPARENT TYPE OF RP	RELEASE DATE	GEOTRACKER UPDATED?	DISCUSSION NOTES FROM MEETING (October 25, 2011)	NEXT STEP FOR AGENCY	
(Insufficient information in	Unable to determine (Insufficient information in GeoTracker)		T0603700652	TERRENCE PALMER	Other	Z - Major Oil Company	3/26/1987	No	Need to upload NFA letter dated 5/26/87 to GeoTracker. Also need to review physical file to determine current case status and 2000 soils report.	Update missing GT information (data, report, unassigned caseworker etc.)	
Unable to determine (Insufficient information in GeoTracker)	Completed-Case Closed	SOUTH EAST MAINT YARD	T0603700099	Not defined in GeoTracker	Gasoline	G - Government Entity (include School, Hospital, Utility)	12/8/1986	Yes	Confirmed this case has been closed.	Not Applicable	
Unable to determine (Insufficient information in GeoTracker)	OTHERErroneous case, Deleted	UNITED AIRLINES	T0603701063	TERRENCE PALMER	Other	I - Industry (Railroad, Steel etc)	3/17/1987	Yes	This is not an open case with LAFD. It has been a SLIC case with LARWQCB since 2004. Case was deleted in GT 10/21/11.	Not Applicable	
Unable to determine (Insufficient information in GeoTracker)	OTHERErroneous case, Deleted	CARDLOCK FUEL SYSTEMS	T0603700478	Not defined in GeoTracker	Gasoline	Z - Major Oil Company	4/1/1987	Yes	No case is open with LAFD. Deleted erroneous case in GT 10/18/11.	Not Applicable	
Unable to determine (Insufficient information in GeoTracker)	Appears close to completion	FAA	T0603701070	Not defined in GeoTracker		G - Government Entity (include School, Hospital, Utility)	6/17/1987	No	This case appears to have been closed in 1993. Need to upload NFA letter and close in GT.	Complete closure process in 1-year (includes well decommission)	
(Insufficient information in	Unable to determine (Insufficient information in GeoTracker)	FRITO-LAY, INC	T0603701066	TERRENCE PALMER	Diesel	S - Small Private Business	7/10/1987	No	Current status is unknown. Need to review physical file to determine current case status and upload most recent material to GT.	Update missing GT information (data, report, unassigned caseworker etc.)	
Unable to determine (Insufficient information in GeoTracker)	OTHERErroneous case, Deleted	HYE CENTER MARKET	T0603702231	Not defined in GeoTracker	Other	Z - Major Oil Company	6/24/1987	Yes	No case is open with LAFD. Deleted erroneous case in GT 9/7/11.	Not Applicable	

ESTIMATED STATUS IN THE CLEANUP PIPELINE?	CHANGE IN STATUS IN THE CLEANUP PIPELINE (BASED ON 10/25/11	ICASE LEAD AGENCY: CITY OF LOS ANGELES - LOCAL	GLOBAL ID	CASEWORKER	PRIMARY COC (In Geotr	APPARENT TYPE OF RP	RELEASE DATE	GEOTRACKER UPDATED?	DISCUSSION NOTES FROM MEETING (October 25, 2011)	NEXT STEP FOR AGENCY
Unable to determine (Insufficient information in GeoTracker)	Unable to determine (Insufficient information in GeoTracker)		T0603700036	TERRENCE PALMER	Gasoline	Z - Major Oil Company	7/17/1987	No	Case may be closeable. Need to review physical file to determine current case status and upload most recent material to GeoTracker.	Update missing GT information (data, report, unassigned caseworker etc.)
Unable to determine (Insufficient information in GeoTracker)	Appears to be on track	TERMINAL 6 LAX	T0603701077	MARCUS LOOK	Other	I - Industry (Railroad, Steel etc)	6/3/1987	Yes	Uploloaded 7/04 Soil Vapor Extraction Workplan to GeoTracker, which was prepared for LARWQCB. Conduct file review to determine whether case should be transferred to LARWQCB.	Push for new/additional remedial investigation (RI)/risk assessment
Unable to determine (Insufficient information in GeoTracker)	Completed-Case Closed	CHEVRON #9-2683	T0603702556	TERRENCE PALMER	Diesel	Z - Major Oil Company	1/17/1988	Yes	Confirmed this case has been closed.	Not Applicable
Unable to determine (Insufficient information in GeoTracker)	Appears to be on track	ACE BEVERAGE COMPANY	T0603788711	PATRICK KILLIAN	Gasoline	I - Industry (Railroad, Steel etc)	5/18/1988	Yes	Site assessment received in 2009. Review file and draft directive letter to be sent out.	Update missing GT information (data, report, unassigned caseworker etc.)
Unable to determine (Insufficient information in GeoTracker)	Unable to determine (Insufficient information in GeoTracker)	EXXON	T0603702096	TERRENCE PALMER	Gasoline	Z - Major Oil Company	5/5/1988	No		Update missing GT information (data, report, unassigned caseworker etc.)
Unable to determine (Insufficient information in GeoTracker)	Appears to be on track	HARBOR DISTRICT FACILITIES	T0603701642	ELOY LUNA	Other	G - Government Entity (include School, Hospital, Utility)	7/11/1988	Yes	Site under remediation. Reports from 2006 - 2011 have been uploaded by the RP.	Push for new/additional remedial investigation (RI)/risk assessment
Unable to determine (Insufficient information in GeoTracker)	OTHERErroneous case, Deleted	MAR VISTA CENTRAL OFFICE	T0603701209	Not defined in GeoTracker	Diesel	S - Small Private Business	5/11/1988	No	No open LUST case with LAFD. Erroneous case deleted in GT 10/24/11.	Not Applicable
Unable to determine (Insufficient information in GeoTracker)	Unable to determine (Insufficient information in GeoTracker)	NATIONAL CAR SALES - Duplicate with T0603768170	T0603776617	MARCUS LOOK	Gasoline	S - Small Private Business	9/21/1988	No	Duplicate erroneous case deleted in GT 10/24/11. Need to review physical file to determine current case status and upload most recent material to GT.	Update missing GT information (data, report, unassigned caseworker etc.)
Unable to determine (Insufficient information in GeoTracker)	Unable to determine (Insufficient information in GeoTracker)	SURFACE PROTECTION INC.	T0603700677	MONTE BUCKNER	Other	S - Small Private Business	5/5/1988	No	Current status is unknown. Need to review physical file to determine current case status and upload most recent material to GT.	Update missing GT information (data, report, unassigned caseworker etc.)

ESTIMATED STATUS IN THE CLEANUP PIPELINE?	CHANGE IN STATUS IN THE CLEANUP PIPELINE (BASED ON 10/25/11	ICASE LEAD AGENCY: GITY OF LOS ANGELES - LOCAL	GLOBAL ID	CASEWORKER	PRIMARY COC (In Geotra	APPARENT TYPE OF RP	RELEASE DATE	GEOTRACKER UPDATED?	DISCUSSION NOTES FROM MEETING (October 25, 2011)	NEXT STEP FOR AGENCY	
Unable to determine (Insufficient information in GeoTracker)	Completed-Case Closed	CHEVRON - JAMES, RONALD B	T0603784210	Not defined in GeoTracker	Gasoline	Z - Major Oil Company	2/21/1989	Yes	Confirmed this case has been closed.	Not Applicable	
	Unable to determine (Insufficient information in GeoTracker)	ORCHARD SUPPLY HARDWARE	T0603797352	Not defined in GeoTracker	Solvent	S - Small Private Business	2/1/1989	No	Current status is unknown. Need to review physical file to determine current case status and upload most recent material to GT.	Update missing GT information (data, report, unassigned caseworker etc.)	
	Unable to determine (Insufficient information in GeoTracker)	J GLOVER MFG INC	T0603738449	Not defined in GeoTracker	Other	I - Industry (Railroad, Steel etc)	9/18/1989	No	Current status is unknown. Need to review physical file to determine current case status and upload most recent material to GT.	Update missing GT information (data, report, unassigned caseworker etc.)	
Unable to determine (Insufficient information in GeoTracker)	OTHER-Transferred to LARWQCB	LAUSD	T0603737823	Not defined in GeoTracker	Gasoline	G - Government Entity (include School, Hospital, Utility)	2/7/1989	Yes	Case was transferred to the LARWQCB on 7/12/11.	Not Applicable	
Unable to determine (Insufficient information in GeoTracker)	OTHER-Transferred to LARWQCB	SOTO STREET FACILITY	T0603700825	Not defined in GeoTracker	Diesel	G - Government Entity (include School, Hospital, Utility)	7/10/1989	Yes	Case was transferred to the LARWQCB on 7/6/11.	Not Applicable	
Unable to determine (Insufficient information in GeoTracker)	Completed-Case Closed	ANCHOR	T0603764849	Not defined in GeoTracker	Gasoline	S - Small Private Business	1/24/1990	Yes	Case was transferred to the LARWQCB on 4/21/11. Case was closed 7/29/11.	Not Applicable	
Unable to determine (Insufficient information in GeoTracker)	Appears to be on track	AUTO RITE	T0603790746	PATRICK KILLIAN	Other	S - Small Private Business	8/11/1989	No	Case may be closeable. Need to review with new inspector and update GT.	Update missing GT information (data, report, unassigned caseworker etc.)	
Unable to determine (Insufficient information in GeoTracker)	Appears to be on track	GREYHOUND LINES INC	T0603770957	Not defined in GeoTracker	Diesel	S - Small Private Business	4/12/1990	No	Recently assigned to new inspector and review of site assessment reports is underway.	Update missing GT information (data, report, unassigned caseworker etc.)	

ESTIMATED STATUS IN THE CLEANUP PIPELINE?	CHANGE IN STATUS IN THE CLEANUP PIPELINE (BASED ON 10/25/11	ICASE LEAD AGENCY: CITY OF LOS ANGELES - LOCAL	GLOBAL ID	CASEWORKER	PRIMARY COC (In Geotte	APPARENT TYPE OF RP	RELEASE DATE	GEOTRACKER UPDATED?	DISCUSSION NOTES FROM MEETING (October 25, 2011)	NEXT STEP FOR AGENCY
Unable to determine (Insufficient information in GeoTracker)	OTHERErroneous case, Deleted	JEAN PIERRE PRODUCTS INC	T0603713919	TERRENCE PALMER	Gasoline	S - Small Private Business	4/2/1990	Yes	No case is open with LAFD. Deleted erroneous case in GT 10/27/11.	Not Applicable
(Insufficient information in	Unable to determine (Insufficient information in GeoTracker)	UNOCAL - ABRAHAM ROISMAN	T0603786425	NEAL REITZELL	Other	S - Small Private Business	9/6/1988	No	Need to review physical file to determine current case status and upload most recent material to GT. May be able to delete.	Update missing GT information (data, report, unassigned caseworker etc.)
(Insufficient information in	Unable to determine (Insufficient information in GeoTracker)	ARCO #1097	T0603702284	NEAL REITZELL	Solvent	Z - Major Oil Company	1/15/1991	No	Current status is unknown. Need to review physical file to determine current case status and upload most recent material to GT.	Update missing GT information (data, report, unassigned caseworker etc.)
	Unable to determine (Insufficient information in GeoTracker)	ARAMARK UNIFORM SERVICES	T0603751654	Not defined in GeoTracker	Gasoline	S - Small Private Business	5/7/1990	No	Current status is unknown. Need to review physical file to determine current case status and upload most recent material to GT.	Update missing GT information (data, report, unassigned caseworker etc.)
	Unable to determine (Insufficient information in GeoTracker)	BOX & GEAR TRANSMISSIONS	T0603746763	TERRENCE PALMER	Other	S - Small Private Business	10/12/1990	No	Possible closure. Need to review file and determine next step.	Update missing GT information (data, report, unassigned caseworker etc.)
(Insufficient information in	Unable to determine (Insufficient information in GeoTracker)	TERMINAL #1 LAX	T0603701075	PATRICK KILLIAN	Gasoline	I - Industry (Railroad, Steel etc)	11/6/1990	No	Current status is unknown. Need to review physical file to determine current case status and upload most recent material to GT.	Update missing GT information (data, report, unassigned caseworker etc.)
(Insufficient information in	Unable to determine (Insufficient information in GeoTracker)	WORLDWIDE FLIGHT SERVICES	T0603736969	Not defined in GeoTracker	Other	I - Industry (Railroad, Steel etc)	7/10/1990	No	Current status is unknown. Need to review physical file to determine current case status and upload most recent material to GT.	Update missing GT information (data, report, unassigned caseworker etc.)

ESTIMATED STATUS IN THE CLEANUP PIPELINE?	CHANGE IN STATUS IN THE CLEANUP PIPELINE (BASED ON 10/25/11	ICASE LEAD AGENCY: CITY OF LOS ANGELES - LOCAL	GlOBAL ID	CASEWORKER	PRIMARY COC (In GeoTrace.	APPARENT TYPE OF RP	RELEASE DATE	<i>GEOTRACKER UPDATED?</i>	DISCUSSION NOTES FROM MEETING (October 25, 2011)	NEXT STEP FOR AGENCY
Unable to determine (Insufficient information in GeoTracker)		AAA FOREIGN AUTO PARTS AND SALVAGE INC	T0603745855	Not defined in GeoTracker	Gasoline	S - Small Private Business	4/8/1991	Yes	File was reviewed and case summary drafted. NOV will be reissued.	Push for new/additional remedial investigation (RI)/risk assessment
(Insufficient information in	Unable to determine (Insufficient information in GeoTracker)	FRITZ HUMMEL - Duplicate with T0603764257	T0603789252	MARCUS LOOK	Gasoline	O - Other (Individual, Homes etc)	2/22/1990	No	Duplicate erroneous case deleted in GT 10/24/11. Possible referral to LARWQCB. Need to review physical file to determine current next step.	
Unable to determine (Insufficient information in GeoTracker)	Appears to be on track	LA DWP - DEPT OF WATER & POWER	T0603790000	PATRICK KILLIAN	Other	G - Government Entity (include School, Hospital, Utility)	2/3/1990	Yes	Geotracker was updated 08/04/11. File was reviewed and case summary drafted. Need to Issue NOV letter for not submitting additional info.	Push for new/additional remedial investigation (RI)/risk assessment
	Unable to determine (Insufficient information in GeoTracker)	LAFD - FIRE STATION 54	T0603744598	Not defined in GeoTracker	Diesel	G - Government Entity (include School, Hospital, Utility)	12/26/1990	No	Current status is unknown. Need to review physical file to determine current case status and upload most recent material to GT.	Update missing GT information (data, report, unassigned caseworker etc.)
(Insufficient information in	Unable to determine (Insufficient information in GeoTracker)	LAUSD - NORTH VALLEY OCCUPATIONAL CNTR	T0603712781	Not defined in GeoTracker	Gasoline	G - Government Entity (include School, Hospital, Utility)	4/10/1991	No	Current status is unknown. Need to review physical file to determine current case status and upload most recent material to GT.	Update missing GT information (data, report, unassigned caseworker etc.)
Unable to determine (Insufficient information in GeoTracker)	Completed-Case Closed	LAUSD - SAFETY SECTION BUS DIV	T0603788360	TERRENCE PALMER	Other	G - Government Entity (include School, Hospital, Utility)	2/20/1991	Yes	Confirmed this case has been closed.	Not Applicable
Unable to determine (Insufficient information in GeoTracker)	Appears to be on track	MAGNESS PETROLEUM COMPANY	T0603712547	Not defined in GeoTracker	Multiple	Z - Major Oil Company	3/27/1991	Yes	Need to follow up with RP to submit remediation report. Case may be transferred to LARWQCB	Push for new/additional remedial investigation (RI)/risk assessment

ESTIMATED STATUS IN THE CLEANUP PIPELINE?	CHANGE IN STATUS IN THE CLEANUP PIPELINE (BASED ON 10/25/11	ICASE LEAD AGENCY: CITY OF LOS ANGELES - LOCAL	GLOBAL ID	CASEWORKER	PRIMARY COC (In Geotrasi.	APPARENT TYPE OF RP	RELEASE DATE	GEOTRACKER UPDATED?	^{DIS} CUSSION NOTES FROM MEETING (October 25, 2011)	NEXT STEP FOR AGENCY
Unable to determine (Insufficient information in GeoTracker)		MOBIL - CARDENAS,RICHARD	T0603710593	TERRENCE PALMER	Gasoline	Z - Major Oil Company	1/14/1991	Yes	Confirmed this case has been closed.	Not Applicable
•		REYCREST ROOFING/WATERPROOFING CO	T0603776777	Not defined in GeoTracker	Multiple	S - Small Private Business	11/20/1990	No		Update missing GT information (data, report, unassigned caseworker etc.)
Unable to determine (Insufficient information in GeoTracker)	Illusufficient information in	SALVATION ARMY THRIFT STORE	T0603715897	Not defined in GeoTracker	Gasoline	S - Small Private Business	8/9/1990	No		Update missing GT information (data, report, unassigned caseworker etc.)
Unable to determine (Insufficient information in GeoTracker)		CROWN CORK & SEAL COMPANY INC	T0603702447	Not defined in GeoTracker	Solvent	S - Small Private Business	7/30/1991	Yes	Confirmed this case has been transferred.	Not Applicable
Unable to determine (Insufficient information in GeoTracker)	Unable to determine (Insufficient information in GeoTracker)	J & S PRECISION AUTO (FMR ARAX GAS STATION)	T0603740056	Not defined in GeoTracker	Gasoline	S - Small Private Business	9/11/1991	No		Update missing GT information (data, report, unassigned caseworker etc.)
Unable to determine (Insufficient information in GeoTracker)	Unable to determine (Insufficient information in GeoTracker)	LAFD - FIRE STATION 80	T0603745944	TERRENCE PALMER	Other	G - Government Entity (include School, Hospital, Utility)	2/11/1990	No		Update missing GT information (data, report, unassigned caseworker etc.)
	Unable to determine (Insufficient information in GeoTracker)	RENT-A-BIN	T0603740210	TERRENCE PALMER	Diesel	S - Small Private Business	6/27/1991	No		Update missing GT information (data, report, unassigned caseworker etc.)
Unable to determine (Insufficient information in GeoTracker)	Unable to determine (Insufficient information in GeoTracker)	RESORT RENT A CAR	T0603790524	Not defined in GeoTracker	Diesel	S - Small Private Business	5/8/1991	No		Update missing GT information (data, report, unassigned caseworker etc.)

ESTIMATED STATUS IN THE CLEANUP PIPELINE?	CHANGE IN STATUS IN THE CLEANUP PIPELINE (BASED ON 10/25/11	(CASE LEAD AGENCY: CITY OF LOS ANGELES - LOCAL	GLOBAL 1D	CASEWORKER	PRIMARY COC (In Gast	APPARENT TYPE OF RP	RELEASE DATE	GEOTRACKER UPDATED?	DISCUSSION NOTES FROM MEETING (October 25, 2011)	NEXT STEP FOR AGENCY
Unable to determine (Insufficient information in GeoTracker)	OTHER-Transferred to LARWQCB	TUNE UP MASTERS SHOP #10		TERRENCE PALMER	Other	S - Small Private Business	11/15/1991	Yes	Confirmed case transferred to LARWQCB 10/14/11.	Not Applicable
(Insufficient information in	Unable to determine (Insufficient information in GeoTracker)	LIMOUSINE EXPRESS INC	T0603786262	Not defined in GeoTracker	Diesel	S - Small Private Business	1/27/1992	No	Current status is unknown. Need to review physical file to determine current case status and upload most recent material to GT.	Update missing GT information (data, report, unassigned caseworker etc.)
	Unable to determine (Insufficient information in GeoTracker)	MISSION HILLS FORD	T0603790800	TERRENCE PALMER	Other	O - Other (Individual, Homes etc)	2/18/1992	No	Current status is unknown. Need to review physical file to determine current case status and upload most recent material to GT.	Update missing GT information (data, report, unassigned caseworker etc.)
Unable to determine (Insufficient information in GeoTracker)	Unable to determine (Insufficient information in GeoTracker)	ROBERTSON BRANCH LIBRARY	T0603799502	NEAL REITZELL	Solvent	G - Government Entity (include School, Hospital, Utility)	1/28/1992	No	Current status is unknown. Need to review physical file to determine current case status and upload most recent material to GT.	Update missing GT information (data, report, unassigned caseworker etc.)
Unable to determine (Insufficient information in GeoTracker)	Completed-Case Closed	SOUTH BAY CORP.	T0603700073	JOHN AWUJO	Diesel	S - Small Private Business	1/15/1992	Yes	Confirmed this case was closed.	Not Applicable
	Unable to determine (Insufficient information in GeoTracker)	BUILDERS SHEET METAL INC	T0603759024	NEAL REITZELL	Other	S - Small Private Business	7/30/1992	No	Case may be closeable. Need to review physical file to determine current case status and upload most recent material to GT.	Update missing GT information (data, report, unassigned caseworker etc.)
Unable to determine (Insufficient information in GeoTracker)	Appears to be on track	CALIFORNIA STATE UNIVERSITY FACILITY	T0603769587	Not defined in GeoTracker	Diesel	G - Government Entity (include School, Hospital, Utility)	8/12/1992	No	File was reviewed and case summary drafted. A new NOV is to be issued.	Push for new/additional remedial investigation (RI)/risk assessment
Unable to determine (Insufficient information in GeoTracker)	Unable to determine (Insufficient information in GeoTracker)	DARLING-DELAWARE	T0603796838	Not defined in GeoTracker	Unknown	S - Small Private Business	8/8/1992	No	Current status is unknown. Need to review physical file to determine current case status and upload most recent material to GT.	Update missing GT information (data, report, unassigned caseworker etc.)

ESTIMATED STATUS IN THE CLEANUP PIPELINE?	CHANGE IN STATUS IN THE CLEANUP PIPELINE (BASED ON 10/25/11	ICASE LEAD AGENCY: CITY OF LOS ANGELES - LOCAL	GLOBAL ID	CASEWORKER	PRIMARY COC (In Geotter)	APPARENT TYPE OF RP	RELEASE DATE	GEOTRACKER UPDATED?	DISCUSSION NOTES FROM MEETING (October 25, 2011)	NEXT STEP FOR AGENCY
(Insufficient information in	Unable to determine	DEPT OF TRANSPORTATION	T0603700457	ELOY LUNA	Diesel	U - Unknown	5/7/1992	No	Possible closure. Need to review file.	Update missing GT information (data, report, unassigned caseworker etc.)
(Insufficient information in	Unable to determine (Insufficient information in GeoTracker)	GAS S/S	Т0603702450	NEAL REITZELL	Gasoline	U - Unknown	5/15/1992	No	Need to find new owner address and reissue letter.	Update missing GT information (data, report, unassigned caseworker etc.)
(Insufficient information in	Unable to determine (Insufficient information in GeoTracker)	LAFD - FIRE STATION 95	T0603794280	NEAL REITZELL	Gasoline	G - Government Entity (include School, Hospital, Utility)	7/14/1992	No	Current status is unknown. Need to review physical file to determine current case status and upload most recent material to GT.	Update missing GT information (data, report, unassigned caseworker etc.)
Unable to determine (Insufficient information in GeoTracker)	Appears to be on track	RAY'S MARKET	T0603721107	Not defined in GeoTracker	Gasoline	S - Small Private Business	9/10/1992	Yes	File was reviewed. Letter to be issued requesting remediation closure report.	Push for new/additional remedial investigation (RI)/risk assessment
	Unable to determine (Insufficient information in GeoTracker)	ROTORCRAFT SUPPORT INC	T0603755343	Not defined in GeoTracker	Other	S - Small Private Business	9/24/1992	No	Current status is unknown. Need to review physical file to determine current case status and upload most recent material to GT.	Update missing GT information (data, report, unassigned caseworker etc.)
Unable to determine (Insufficient information in GeoTracker)	Completed-Case Closed	CHEVRON #9-2766	T0603702409	ELOY LUNA	Gasoline	Z - Major Oil Company	4/8/1993	Yes	Confirmed this case was closed.	Not Applicable
Unable to determine (Insufficient information in GeoTracker)	Completed-Case Closed	DEPT. OF GEN SERVICE OF STATE	T0603766799	Not defined in GeoTracker	Gasoline	G - Government Entity (include School, Hospital, Utility)	9/11/1991	Yes	Confirmed this case was closed.	Not Applicable
	Unable to determine (Insufficient information in GeoTracker)	DEXOL INDUSTRIES - Not Fed UST?	T0603730842	TERRENCE PALMER	Other	I - Industry (Railroad, Steel etc)	10/14/1992	No	Current status is unknown. Need to review physical file to determine current case status and upload most recent material to GT.	Update missing GT information (data, report, unassigned caseworker etc.)

ESTIMATED STATUS IN THE CLEANUP PIPELINE?	CHANGE IN STATUS IN THE CLEANUP PIPELINE (BASED ON 10/25/11	ICASE LEAD AGENCY: CITY OF LOS ANGELES - LOCAL	GLOBAL ID	CASEWORKER	PRIMARY COC (In George	APPARENT TYPE OF RP	RELEASE DATE	GEOTRACKER UPDATED?	DISCUSSION NOTES FROM METING (October 25, 2011)	NEXT STEP FOR AGENCY
(Insufficient information in	Unable to determine	LAPD - HOLLENBECK DIVISION	Т0603737703	Not defined in GeoTracker	Gasoline	G - Government Entity (include School, Hospital, Utility)	5/2/1990	No	Current status is unknown. Need to review physical file to determine current case status and upload most recent material to GT.	Update missing GT information (data, report, unassigned caseworker etc.)
Unable to determine (Insufficient information in GeoTracker)	OTHER-Transferred to LARWQCB	PIPER TECHNICAL CENTER	T0603700534	Not defined in GeoTracker	Other	G - Government Entity (include School, Hospital, Utility)	3/25/1993	Yes	Confirmed this case was transferred to LARWQCB 8/31/11.	Not Applicable
(Insufficient information in	Unable to determine (Insufficient information in GeoTracker)	DRIZ KNITTING MILLS	T0603746785	MARCUS LOOK	Other	S - Small Private Business	9/2/1993	No	This case was not discussed during meeting.	Update missing GT information (data, report, unassigned caseworker etc.)
Unable to determine (Insufficient information in GeoTracker)	Appears to be on track	MATSON TERMINAL	T0603791363	Not defined in GeoTracker	Diesel	G - Government Entity (include School, Hospital, Utility)	9/13/1993	Yes	File was reviewed and case summary drafted. Case to be transferred to LARWQCB.	Case to be referred to LARWQCB
Unable to determine (Insufficient information in GeoTracker)	Appears to be on track	MOBIL #11-GQG	T0603701315	ELOY LUNA	Gasoline	U - Unknown	9/23/1993	Yes	Approved pending reports on Geotracker 09/08/11.	Update missing GT information (data, report, unassigned caseworker etc.)
(Insufficient information in	Unable to determine (Insufficient information in GeoTracker)	VERIZON WIRELESS	T0603729309	TERRENCE PALMER	Other	S - Small Private Business	8/24/1993	No	Current status is unknown. Need to review physical file to determine current case status and upload most recent material to GT.	Update missing GT information (data, report, unassigned caseworker etc.)
Unable to determine (Insufficient information in GeoTracker)	Completed-Case Closed	TEXACO - KEEBLE, ROBERT	T0603786190	Not defined in GeoTracker	Gasoline	S - Small Private Business	2/10/1994	Yes	NFA letter was issued 4/26/10. NFA letter uploaded to GT and case closed in GT 10/24/11.	Not Applicable
(Insufficient information in		TIERNO'S GENERAL FABRICATION	T0603743780	Not defined in GeoTracker	Gasoline	S - Small Private Business	11/9/1993	No	Current status is unknown. Need to review physical file to determine current case status and upload most recent material to GT.	Update missing GT information (data, report, unassigned caseworker etc.)

ESTIMATED STATUS IN THE CLEANUP PIPELINE?	CHANGE IN STATUS IN THE CLEANUP PIPELINE (BASED ON 10/25/11	ICASE LEAD AGENCY: CITY OF LOS ANGELES - LOCAL	GI OBAL ID	CASEWORKER	PRINVARY COC (In GeoTrack.	APPARENT TYPE OF RP	RELEASE DATE	GEOTRACKER UPDATED?	DISCUSSION NOTES FROM MEETING (October 25, 2011)	NEXT STEP FOR AGENCY
	Unable to determine (Insufficient information in GeoTracker)		T0603739581	TERRENCE PALMER	Gasoline	S - Small Private Business	4/15/1994	No		Update missing GT information (data, report, unassigned caseworker etc.)
Unable to determine (Insufficient information in GeoTracker)	Unable to determine (Insufficient information in GeoTracker)	NORMANDIE PLAZA	T0603755288	TERRENCE PALMER	Other	Z - Major Oil Company	7/1/1989	No		Update missing GT information (data, report, unassigned caseworker etc.)
Unable to determine (Insufficient information in GeoTracker)	Completed-Case Closed	NORRIS CANCER HOSPITAL	T0603700853	Not defined in GeoTracker	Diesel	G - Government Entity (include School, Hospital, Utility)	6/2/1994	Yes	Confirmed this case was closed.	Not Applicable
Unable to determine (Insufficient information in GeoTracker)	Appears to be on track	WASHINGTON MUTUAL BANK	T0603782010	TERRENCE PALMER	Diesel	S - Small Private Business	5/25/1994	No	Soils analysis report was received in 2010. Need to contact consultant to upload most recent reports to GT.	Update missing GT information (data, report, unassigned caseworker etc.)
Unable to determine (Insufficient information in GeoTracker)	Appears to be on track	A-ABBEY METALS INTERNATIONAL	T0603774420	Not defined in GeoTracker	Gasoline	S - Small Private Business	12/5/1994	Yes	This case was recently transferred to new inspector. Need to send out follow up letter requesting additional site assessment and RAP.	Push for new/additional remedial investigation (RI)/risk assessment
Unable to determine (Insufficient information in GeoTracker)	Appears to be on track	CALIFORNIA TARGET STATION #49	T0603705678	NEAL REITZELL	Gasoline	S - Small Private Business	12/22/1994	Yes	File was reviewed and case summary drafted. Need to issue a letter requesting remediation closure report.	Push for new/additional remedial investigation (RI)/risk assessment
Unable to determine (Insufficient information in GeoTracker)	Unable to determine (Insufficient information in GeoTracker)	MENDOZA SERVICE INC	T0603741517	Not defined in GeoTracker	Other	S - Small Private Business	11/1194	No		Update missing GT information (data, report, unassigned caseworker etc.)
	Unable to determine (Insufficient information in GeoTracker)	ARCO #5033	T0603708034	TERRENCE PALMER	Gasoline	Z - Major Oil Company	8/31/1995	No		Update missing GT information (data, report, unassigned caseworker etc.)

ESTIMATED STATUS IN THE CLEANUP PIPELINE?	CHANGE IN STATUS IN THE CLEANUP PIPELINE (BASED ON 10/25/11	ICASE LEAD AGENCY: CITY OF LOS ANGELES - LOCAL	Gl08AL ID	САЅЕWОRKER	PRINJARY COC (In Geottage)	APPARENT TYPE OF RP	RELEASE DATE	GEOTRACKER UPDATED?	DISCUSSION NOTES FROM MEETING (October 25, 2011)	NEXT STEP FOR AGENCY
Unable to determine (Insufficient information in GeoTracker)	Unable to determine (Insufficient information in GeoTracker)		T0603759109	TERRENCE PALMER	Gasoline	S - Small Private Business	5/10/1995	No		Update missing GT information (data, report, unassigned caseworker etc.)
Unable to determine (Insufficient information in GeoTracker)	Unable to determine (Insufficient information in GeoTracker)	GVD COMMERCIAL PROPERTIES	T0603702241	Not defined in GeoTracker	Other	S - Small Private Business	7/1/1995	No	Current status is unknown. Need to review physical file to determine current case status and upload most recent material to GT.	Update missing GT information (data, report, unassigned caseworker etc.)
Unable to determine (Insufficient information in GeoTracker)	Unable to determine (Insufficient information in GeoTracker)	LA CO FD FIRE STATION #046	T0603705142	Not defined in GeoTracker	Other	U - Unknown	11/7/1995	No	Current status is unknown. Need to review physical file to determine current case status and upload most recent material to GT.	Update missing GT information (data, report, unassigned caseworker etc.)
Unable to determine (Insufficient information in GeoTracker)	Unable to determine (Insufficient information in GeoTracker)	PAN AMERICAN WORLD AIRWAYS, INC	T0603727663	TERRENCE PALMER	Multiple	I - Industry (Railroad, Steel etc)	6/1/1995	No	Current status is unknown. Need to review physical file to determine current case status and upload most recent material to GT.	Update missing GT information (data, report, unassigned caseworker etc.)
Unable to determine (Insufficient information in GeoTracker)	Appears to be on track	PENHALL COMPANY	T0603743170	TERRENCE PALMER	Diesel	S - Small Private Business	9/15/1995	Yes	The new property owner was contacted and an NOV was issued.	Push for new/additional remedial investigation (RI)/risk assessment
Unable to determine (Insufficient information in GeoTracker)	Completed-Case Closed	STOLEN BASE CLEANERS	T0603700906	TERRENCE PALMER	Other	S - Small Private Business	10/19/1985	Yes	Confirmed this case was closed.	Not Applicable
Unable to determine (Insufficient information in GeoTracker)	Completed-Case Closed	STUDIO SERVICES INC	T0603781181	TERRENCE PALMER	Gasoline	S - Small Private Business	8/23/1995	Yes	Confirmed this case was closed.	Not Applicable
Unable to determine (Insufficient information in GeoTracker)	Appears to be on track	SUNSHINE TRUCK STOP INC.	т0603707597	TERRENCE PALMER	Other	S - Small Private Business	7/21/1995	No	Referral letter has been drafted. Case to be referred to LARWQCB.	Case to be referred to LARWQCB
Unable to determine (Insufficient information in GeoTracker)	Unable to determine (Insufficient information in GeoTracker)	TUNE-UPS PLUS - Duplicate with T0603725845	T0603787881	Not defined in GeoTracker	Gasoline	S - Small Private Business	11/9/1994	No	I physical file to determine current case status and unioad most recent	Update missing GT information (data, report, unassigned caseworker etc.)

Attachment 1:

Case Review Power Point Slides from Draft Report

The contents of this attachment are provided in electronic format only.

ARCO #1680 (T0603702575)

5158 Laurel Canyon Blvd. Studio City, CA 91604



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1991 and 1998
- Multiple phases of investigation and active SVE remediation since 1998
- · Site might have been redeveloped

NOTE: Data queried from GeoTracker and reviewed in October 2010

Case Age: 19 years
Primary COC: Gasoline

RP Identified: Arco Products Co.
Potential Media Affected: Soil

Current land use: Commercial (In Yoga

Center)

Well Network: 11 SVE wells (0 gw wells)



CLEANUP OVERSIGHT AGENCIES LOS ANGELES, CITY OF (LEAD) CASEWORKER: NEAL REITZELL - SUPERVISOR: NONE SPECIFIED LOS ANGELES RWQCB (REGION 4) - CASE #: 916040452 CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE F	ILTER: Show All Activities
ACTION TYPE	<u>ACTION</u>	ACTION DATE
LEAK ACTION	Leak Discovery	10/10/1991
LEAK ACTION	Leak Reported	10/10/1991

Activities Conducted to Date Based on GeoTracker T0603702575

Assessment last 5 years

- RAP
- Additional investigation
- Water well search

Remediation last 5 years

- Piping replacement compliance sampling
- Temporary SVE events
- SVE system shut down

Assessment older than 5 years

- Multiple investigations
- SVE pilot test

Remediation older than 5 years

- Used oil UST removal
- SVE well installation
- Multiple USTs replaced
- Soil excavation and disposal

as reported by regulatory agency



Review Conclusions T0603702575

Review indicates:

- Multiple phases of investigation; soils only case
- Completed SVE well installation, pilot test, and operation
- System expanded over time, after significant mass removal the system was shut down

Discussion:

- Any remaining impediments to closure?
- RP and GeoTracker compliance
- Cleanup closure timeline

Potential closure candidate within 1 year

CHEVRON #9-9164 (T0603702407)

14850 Burbank Blvd. Van Nuys, CA 91401



Possible Reasons Why This Case Is So Old

- Appears little cleanup activity at site
- · Apparent lack of regulatory oversight and RP involvement
- No information on initial 1993 release in GeoTracker
- Multiple tanks removed over different periods

NOTE: Data queried from GeoTracker and reviewed in October 2010

Case Age: 17 years Primary COC: Gasoline RP Identified: Chevron USA Potential Media Affected: Soil Current land use: Residential

Well Network: None



LOS ANGELES, CITY OF (LEAD)

CASEWORKER: <u>ELOY LUMA</u> - <u>SUPERVISOR</u>: NONE SPECIFIED

LOS ANGELES RWQCB (REGION 4) - CASE #: 914010789

CASEWORKER: <u>YUE RONG</u> - <u>SUPERVISOR</u>: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE F	ILTER: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	4/9/1993
LEAK ACTION	Leak Discovery	4/8/1993
LEAK ACTION	Leak Stopped	4/8/1993

Activities Conducted to Date Based on GeoTracker T0603702407

Assessment last 5 years

- 2008, 2009: Quarterly **Status Report**
- One boring beneath former used oil UST

Remediation last 5 years

2003 Used oil and hydraulic lift removals

Assessment older than 5 years

Appears None

Remediation older than 5 years

as reported by regulatory agency



Review Conclusions T0603702407

Review indicates:

- Regulatory Activities indicates no work has occurred related to initial 1993 release
- Site Assessment Workplan (2008) indicated case closure was requested in 2003 and 2007, but denied due to need to analyze soil beneath former water-oil UST
- Recent single boring completed to address former used-oil UST
- Results (2009) indicated only low concentrations in soil at 15 feet;
 groundwater was not assessed

Discussion:

- Any additional case information available? (initial 1993 release)
- Any significant risk to GW?
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility

Potential case closure candidate within 1 year pending recent results

LULA WASHINGTON DANCE STUDIO (T10000001120)

3773 Crenshaw Blvd., Los Angeles, CA 90016



Case Age: 15 years
Primary COC: Gasoline

RP Identified: The Washingtons Potential Media Affected: Soil Current land use: Dance Theatre Well Network: N/A, soils only

Possible Reasons Why This Case Is So Old

- No activity initially, lots in past few years
- Site had brownfields grant for cleanup, Cleanup progressing, using EPA contractors
- Reports/data to be loaded in GeoTracker
- · Closure candidate within 1 year

NOTE: Data queried from GeoTracker and reviewed in October 2010



CLEANUP OVERSIGHT AGENCIES

LOS ANGELES, CITY OF (LEAD) - CASE #: 12625

CASEWORKER: ELOY LUNA - SUPERVISOR: NONE SPECIFIED

LOS ANGELES RWQCB (REGION 4)

ACTIVITIES REPORT	ACTIVITY TYPE FILTER:	Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	5/18/1995
LEAK ACTION	Leak Discovery	4/15/1995

Activities Conducted to Date Based on GeoTracker T10000001120

Assessment last 5 years

- Several phases, soils investigation and vapor extraction wells installed
- Indoor air and vapor study

Remediation last 5 years

 Vapor extraction operated last few years, almost all mass removed from beneath site.


Assessment older than 5 years

 Soil borings to ascertain extent of contamination

Remediation older than 5 years

 Removed tanks and excavated soils.

as reported by regulatory agency



Review Conclusions T10000001120

Review indicates:

- Primary contaminant release and media affected are gas in soil
- Regulatory Activities need to be addressed in GeoTracker
- Reports/data to be uploaded into GeoTracker for review
- Open Remediation as of 8/7/2007
- Site currently is a school (dance studio)

Discussion:

- Can data for case be uploaded into GeoTracker?
- Significant risk and source at the site appears to have been removed
- Remediation implemented has been effective
- RP and GeoTracker compliance need to be updated
- Next step → cleanup timeline closure possibility within 1 year

Case appears ready for closure within 1 year

SOUTHERN CA RTD DIV 15 (T0603702323)

11900 Branford St. Sun Valley, CA 91352



Possible Reasons Why This Case Is So Old

- Appears little cleanup activity at site
- Apparent lack of regulatory oversight
- No RP identified
- Government site
- Non-compliant sample analytic methods
- · Workplan submitted, not implemented

NOTE: Data gueried from GeoTracker and reviewed in October 2010

Case Age: 26 years Primary COC: Gasoline RP Identified: "BLANK" -Unclaimed in GeoTracker

Potential Media Affected: Soil

Current land use: Industrial (Hanover

Industrial Inc.) Well Network: N/A



CLEANUP OVERSIGHT AGENCIES

OS ANGELES, CITY OF (LEAD)

CASEWORKER: eloy luna - SUPERVISOR: NONE SPECIFIED

OS ANGELES RWQCB (REGION 4) - CASE #: 913522143

CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FILTER	Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	4/24/1984

Activities Conducted to Date Based on GeoTracker T0603702323

<u>Assessment last 5 years</u>

2008 Workplan submitted; work not reported if completed

Remediation last 5 years

Stoddard solvent & diesel **USTs** removed


Assessment older than 5 years

 UST removal compliance samples

Remediation older than 5 years

13 UST replacements

as reported by regulatory agency



Review Conclusions T0603702323

Review indicates:

- Regulatory Activities indicates no work has occurred
- No RP identified
- Only one Workplan was submitted and uploaded into GeoTracker (2008); unclear if work completed
- Workplan history describes numerous USTs, contents, and generations including a Stoddard solvent UST (focus of workplan)

Discussion:

- Was workplan implemented, results, detected chemicals of concern?
- Identify RP
- Age of case is 26 years → any significant risk at site?
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

Case appears to be stuck


SHELL (T0603702122)

22767 Vanowen St. West Hills, CA 91307



RP Identified: "BLANK" –
Unclaimed in GeoTracker
Potential Media Affected: Soil
Current land use: Mixed
commercial/residential
Well Network: N/A

Case Age: 25 years
Primary COC: Gasoline



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity conducted
- Apparent lack of regulatory oversight
- No RP identified
- No reports or data in GeoTracker
- Site has been redeveloped?

NOTE: Data queried from GeoTracker and reviewed in October 2010

CLEANUP OVERSIGHT AGENCIES LOS ANGELES, CITY OF (LEAD) CASEWORKER: TERRENCE PALMER - SUPERVISOR: NONE SPECIFIED LOS ANGELES RWQCB (REGION 4) - CASE #: 913070034 CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FILTER	Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	<u>Leak Reported</u>	5/28/1985

Activities Conducted to Date Based on GeoTracker T0603702122

Assessment last 5 years

Appears None

Remediation last 5 years


Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE T0603702122 as reported by regulatory agency



Review Conclusions T0603702122

Review indicates:

- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Site might have been redeveloped?
- No RP identified
- Cleanup Status History indicates "Site Assessment" in 1988 (no additional information available)

Discussion:

- Any case information available?
- Has groundwater been tested or at risk?
- Age of case is 25-years → any significant risk at site?
- Identify RP
- Next step → cleanup timeline or closure possibility ("soils only" criteria?)

Insufficient case information to determine case status

CLARA SMITH (T0603700001)

8475 Canoga Ave., Los Angeles, CA 91304



Case Age: 25 years

Primary COC: Stoddard Solvent / Mineral

Spirits / Distillates

RP Identified: Smith, Clara – Unclaimed in GeoTracker

Potential Media Affected: Under

Investigation

Current land use: Multiple tenant complex (residential/commercial)

Well Network: N/A



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1986 and present
- No local regulatory case worker assigned
- No apparent RP involvement
- No reports or data in GeoTracker

NOTE: Data gueried from GeoTracker and reviewed in October 2010

CLEANUP OVERSIGHT AGENCIES LOS ANGELES, CITY OF (LEAD) LOS ANGELES RWQCB (REGION 4) - CASE #: 000174 CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FILTE	R: Show All Activities	_
ACTION TYPE	ACTION	ACTION DATE	
LEAK ACTION	Leak Discovery	3/6/1986	
LEAK ACTION	Leak Reported	3/6/1986	
LEAK ACTION	Leak Stopped	3/6/1986	

Activities Conducted to Date Based on GeoTracker T0603700001

Assessment last 5 years

Appears None

Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE T0603700001 as reported by regulatory agency CLARA SMITH (T0603700001) - (MAP) 8475 CANOGA NET LOS ANGELES, CA 91304 LOS ANGELE

Review Conclusions T0603700001

Review indicates:

- No reports or data in GeoTracker to review
- Potential media affected is "Under Investigation"
- Regulatory activities indicates no work has occurred
- Potential contaminants of concern is "Stoddard Solvent/Mineral Spirits/Distillates" → Federal UST tank?
- Regulatory lead is not clear in GeoTracker no local case # or worker

Discussion:

- Any case information available?
- Assign local case worker
- Age of case is 24-years and site is residential → any significant risk at site?
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility

Insufficient case information to determine case status

SIDEWALK TREE PLANTER HOLE (T0603700064)

Huntington Dr. S., Los Angeles, CA 90032



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1986 and present
- No local regulatory case worker assigned
- · No RP identified
- No reports or data in GeoTracker
- · Exact location of site unclear

NOTE: Data queried from GeoTracker and reviewed in October 2010

Case Age: 25 years

Primary COC: Aviation

RP Identified: "BLANK" –

Unclaimed in GeoTracker

Potential Media Affected: Soil

Current land use: Residential-garden?

Well Network: N/A



CLEANUP OVERSIGHT AGENCIES
LOS ANGELES, CITY OF (LEAD)
LOS ANGELES RWQCB (REGION 4) - CASE #: 030389-10
CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPO	ORT ACTIVITY TYPE F	ILTER: Show All Activities
ACTION TYPE	<u>ACTION</u>	ACTION DATE
LEAK ACTION	Leak Reported	1/27/1986
LEAK ACTION	Leak Discovery	1/27/1986

Activities Conducted to Date Based on GeoTracker T0603700064

Assessment last 5 years

Appears None

Remediation last 5 years


Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE T0603700064 as reported by regulatory agency



Review Conclusions T0603700064

Review indicates:

- No reports or data in GeoTracker to review
- Regulatory Activities indicates no work has occurred
- Exact site address not defined
- Potential contaminants of concern is aviation
- Regulatory lead is not clear in GT no local case # or worker

Discussion:

- Any case information available?
- Age of case is 25-years → any significant risk at site?
- Local case # and worker information
- Identify RP
- Next step → cleanup timeline or closure possibility ("soils only"?)

Insufficient case information to determine case status

ARROYO SECO PARK (T0603701011)

5568 Via Marisol, Los Angeles, CA 90042



Case Age: 24 years Primary COC: Gasoline

RP Identified: O'Guinn, Kenneth A -

Unclaimed in GeoTracker

Potential Media Affected: Soil

Current land use: Recreation (Hermon

Well Network: N/A



CLEANUP OVERSIGHT AGENCIES LOS ANGELES, CITY OF (LEAD) CASEWORKER: TERRENCE PALMER - SUPERVISOR: NONE SPECIFIED LOS ANGELES RWQCB (REGION 4) - CASE #: 900420125

CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FI	LTER: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Discovery	5/8/1986
LEAK ACTION	Leak Reported	5/8/1986
LEAK ACTION	<u>Leak Stopped</u>	5/8/1986

Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1986 and present
- · Apparent lack of regulatory oversight and RP involvement
- No reports or data in GeoTracker

NOTE: Data queried from GeoTracker and reviewed in October 2010

Activities Conducted to Date Based on GeoTracker T0603701011

<u>Assessment last 5 years</u>

Appears None

Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

ARROYO SECO PARK (T0603701011) - (MAP) 5668 VA MARISOL LOS ANGELES, CA 90042 LOS ANGELES COUNTY LUST CLEANUP SITE Supply Cleanup Status History Regulatory Activities (Invironmental Data (ES)) Site Maps / Documents (Community Involvement) POTENTIAL CONTAINMANTS OF CONCERN GASOLINE FIRE LOCATION Site History No site history available

Review Conclusions T0603701011

Review indicates:

- Regulatory Activities indicates no work has occurred
- Cleanup Status: Site Assessment in 1986 and Open Inactive as of 5/14/2008
- No reports or data in GeoTracker to review
- Site is currently a recreation park

Discussion:

- Any case information available?
- Age of case is 25-years → any significant risk at site?
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

FOOD FOR LIFE (T0603700809)

3580 Pasadena Ave., Montecito Heights, CA 90031



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1986 and present
- No local regulatory case worker assigned
- No apparent RP involvement
- No reports or data in GeoTracker

NOTE: Data queried from GeoTracker and reviewed in October 2010

Case Age: 24 years
Primary COC: Aviation
RP Identified: Food for Life –
Unclaimed in GeoTracker

Potential Media Affected: Soil Current land use: Industrial (Flavor

Foods Inc.)

Well Network: N/A



CLEANUP OVERSIGHT AGENCIES

LOS ANGELES, CITY OF (LEAD)

CASEWORKER: TBD - SUPERVISOR: NONE SPECIFIED

LOS ANGELES RWQCB (REGION 4) - CASE #: 900310289

CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE F	ILTER: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Discovery	10/28/1986
LEAK ACTION	Leak Reported	10/28/1986
LEAK ACTION	Leak Stopped	10/28/1986

Activities Conducted to Date Based on GeoTracker T0603700809

Assessment last 5 years

Appears None

Remediation last 5 years


Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE T0603700809 as reported by regulatory agency



Review Conclusions T0603700809

Review indicates:

- Potential contaminants of concern is listed as aviation
- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Regulatory lead information not complete in GeoTracker no case worker or local case #

Discussion:

- Any case information available?
- Age of case is 25-years → any significant remaining risk at site?
- Assign local case worker?
- RP and GeoTracker compliance should be enforced
- Next step → cleanup timeline or closure possibility ("soils only"?)

HOWARD HUGHES PROP (T0603700098)

Jefferson Blvd., Marina Del Rey, CA 90291



Case Age: 24 years Primary COC: Aviation RP Identified: Howard

RP Identified: Howard Hughes Properties

Unclaimed in GeoTracker

Potential Media Affected: Other GW (Uses Other Than Drinking Water)
Current Land Use: Residential

Well Network: N/A



NOTE: Address is "Jefferson Way"? Possible Reasons Why This Case Is So Old

- Appears no activity between 1986 and present
- Apparent lack of regulatory oversight and RP involvement
- No reports or data in GeoTracker
- Exact site location unclear

NOTE: Data queried from GeoTracker and reviewed in October 2010

CLEANUP OVERSIGHT AGENCIES LOS ANGELES, CITY OF (LEAD) - CASE #: 1234 CASEWORKER: PATRICK KILLIAN - SUPERVISOR: NONE SPECIFIED LOS ANGELES RWQCB (REGION 4) - CASE #: 080008 CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FILTE	R: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Discovery	11/24/1986
LEAK ACTION	Leak Stopped	11/24/1986
LEAK ACTION	<u>Leak Reported</u>	11/24/1986

Activities Conducted to Date Based on GeoTracker T0603700098

Assessment last 5 years

Appears None


Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years



Review Conclusions T0603700098

Review indicates:

- Potential contaminants of concern is aviation.
- No reports or data in GeoTracker to review
- Regulatory Activities indicates no work has occurred

Discussion:

- Any case information available?
- Media affected involves GW → any evidence of significant risk?
- Exact location of the site
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility

MOBIL #11-GM4 (T0603700424)

7200 Avalon Blvd., Los Angeles, CA 90003



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1986 and present
- Apparent lack of regulatory oversight and RP involvement
- No reports or data in GeoTracker
- Site appears to have been redeveloped

NOTE: Data queried from GeoTracker and reviewed in October 2010

Case Age: 24 years
Primary COC: Gasoline

RP Identified: Mobil Oil Corp –

Unclaimed in GeoTracker

Potential Media Affected: Soil Current land use: Restaurant (Burger King)

Well Network: N/A



CLEANUP OVERSIGHT AGENCIES

LOS ANGELES, CITY OF (LEAD)

CASEWORKER: eloy lung - SUPERVISOR: NONE SPECIFIED

LOS ANGELES RWOGD (REGION 4) - CASE #: 900030161

CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FILTER	Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	7/22/1986
LEAK ACTION	<u>Leak Discovery</u>	7/18/1986

Activities Conducted to Date Based on GeoTracker T0603700424

Assessment last 5 years

Appears None


Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years



Review Conclusions T0603700424

Review indicates:

- No reports or data in GeoTracker to review
- Regulatory Activities indicates no work has occurred
- Case status: Open-Inactive 5/6/2008
- Site appears to have been redeveloped

Discussion:

- Any case information available?
- Age of case is 24-years and might have been redeveloped → any significant risk remains at site?
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

MOBIL #11-MW6 (T0603701599)

26650 Western Ave S., Harbor City, CA 90710



Potential Media Affected: Soil

Unclaimed in Geotracker

Hydraulic / Lubricating

Current land use: Strip Mall (Starbucks)

Primary COC: Waste Oil / Motor/

RP Identified: Mobil Oil Corp. -

Well Network: N/A

Case Age: 24 years



LOS ANGELES, CITY OF (LEAD)

LOS ANGELES, CITY OF (LEAD)

CASEWORKER: TERRENCE PALMER - SUPERVISOR: NONE SPECIFIED

LOS ANGELES RWQCB (REGION 4) - CASE #: 907100143

CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE F	ILTER: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	11/10/1986
LEAK ACTION	Leak Discovery	11/7/1986
LEAK ACTION	Leak Stopped	11/7/1986

Possible Reasons Why This Case Is So Old

- Appears no cleanup activity at site
- Apparent lack of regulatory oversight and RP involvement
- No reports or data in GeoTracker
- Cleanup Status: Open Inactive
- Site might have been redeveloped

NOTE: Data queried from GeoTracker and reviewed in October 2010

Activities Conducted to Date Based on GeoTracker T0603701599

<u>Assessment last 5 years</u>

Appears None


Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years



Review Conclusions T0603701599

Review indicates:

- Waste oil/ motor oil/ hydraulic/ lubricating release
- Cleanup Site History indicates "Site Assessment" in 1988
- No reports or data in GeoTracker to review
- Case Status: Open Inactive as of 5/20/2008
- Site appears to have been redeveloped

Discussion:

- Any case information available?
- "Open Inactive" case status?
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only" criteria?)

RICHARD STERMAN (T0603700025)

1955 Glenoaks Blvd., San Fernando, CA 91340



Case Age: 24 years
Primary COC: Aviation

RP Identified: Sterman, Richard -

Unclaimed in GeoTracker

Potential Media Affected: Soil

Current land use: (McDonald's Restaurant)

Well Network: N/A



CLEANUP OVERSIGHT AGENCIES LOS ANGELES, CITY OF (LEAD) LOS ANGELES RWQCB (REGION 4) - CASE #: 000780 CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FIL	TER: Show All Activities	•
ACTION TYPE	ACTION	ACTION DATE	
LEAK ACTION	<u>Leak Reported</u>	7/22/1986	

Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1986 and present
- No local regulatory case worker assigned
- No apparent RP involvement
- No reports or data in GeoTracker

NOTE: Data gueried from GeoTracker and reviewed in October 2010

Activities Conducted to Date Based on GeoTracker T0603700025

Assessment last 5 years

Appears None

Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years



Review Conclusions T0603700025

Review indicates:

- Aviation fuel release
- No reports or data in GeoTracker to review
- Regulatory activities indicates no work has occurred
- Regulatory lead contact info not in GT no local case # or worker

Discussion:

- Any case information available?
- Age of case is 24-years and site is a restaurant → any significant risk at site?
- Assign local case worker
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

SAN PEDRO MUNICIPAL BUILDING (T0603701641)

839 Beacon St. S., Terminal Island, CA 90731



Case Age: 24 years **Primary COC:** Gasoline

RP Identified: Treidler. Brooks -

Unclaimed in GeoTracker

Potential Media Affected: Soil **Current land use:** Multiple tenant

commercial complex Well Network: N/A



CLEANUP OVERSIGHT AGENCIES

LOS ANGELES, CITY OF (LEAD)

CASEWORKER: eloy lung - SUPERVISOR: NONE SPECIFIED

LOS ANGELES RWQCB (REGION 4) - CASE #: 907310352

CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE I	FILTER: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	8/29/1986
LEAK ACTION	Leak Discovery	8/21/1986
LEAK ACTION	Leak Stopped	8/21/1986

Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1986 and present
- Apparent lack of regulatory oversight and RP involvement
- No reports or data in GeoTracker
- Cleanup Status: Open Inactive
- Possible government site?

NOTE: Data queried from GeoTracker and reviewed in October 2010

Activities Conducted to Date Based on GeoTracker T0603701641

<u>Assessment last 5 years</u>

Appears None

Remediation last 5 years


Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE T0603701641 as reported by regulatory agency



Review Conclusions T0603701641

Review indicates:

- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Cleanup Status: Open Inactive as of 5/20/2008

Discussion:

- Any case information available?
- Cleanup Inactive status?
- RP and GeoTracker compliance
- Age of case is 24 years → any significant risk at site?
- Next step → cleanup timeline or closure possibility ("soils only" criteria?)

THRIFTY (T0603701178)

11526 Santa Monica Blvd. Rancho Park, CA 90064



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1986 and present
- No local regulatory case worker assigned
- No apparent RP involvement
- No reports or data in GeoTracker

NOTE: Data gueried from GeoTracker and reviewed in October 2010

Case Age: 24 years
Primary COC: Aviation

RP Identified: Thrifty Oil Company -

Unclaimed in GeoTracker

Potential Media Affected: Soil Current land use: Parking Garage

Well Network: N/A



CLEANUP OVERSIGHT AGENCIES
LOS ANGELES, CITY OF (LEAD)
CASEWORKER: TBD - SUPERVISOR: NONE SPECIFIED
LOS ANGELES RWQCB (REGION 4) - CASE #: 900640307
CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED
CASE TOTAL TOE HOTO SOI ENVISOR, NOILE OF EOH IED

ACTIVITIES REPORT	ACTIVITY TYPE F	ILTER: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Discovery	7/14/1986
LEAK ACTION	Leak Stopped	7/14/1986
LEAK ACTION	Leak Reported	7/14/1986

Activities Conducted to Date Based on GeoTracker T0603701178

Assessment last 5 years

Appears None

Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE T0603701178 as reported by regulatory agency THRIFTY (T0603701178) - (MAP) 11528 SANTA MONICA BLVD RANCHO PARK CA 90064 LOS ANGELES COUNTY LUST CLEANUP STRE Summany Cleanup Status History Regulatory Activities Environmental Data (St) Site Maps / Documents Community Involvement Summany Cleanup Status History Regulatory Activities Environmental Data (St) Site Maps / Documents Community Involvement Summany Cleanup Status History Regulatory Activities Environmental Data (St) Site Maps / Documents Community Involvement Summany Cleanup Status History POTENTIAL CONTAMINANTS OF CONCERN AVAILION POTENTIAL CONTAMINANTS OF CONCERN SOIL Site History No site history available

Review Conclusions T0603701178

Review indicates:

- Aviation fuel release
- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Cleanup Status History indicates "Open Site Assessment" (5/16/2007)
- Regulatory lead information not complete in GeoTracker no local case
 # or worker

Discussion:

- Any case information available?
- Site assessment conducted in 2007
- Age of case is 24-years → any significant risk at site?
- Assign local case worker
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

UNNAMED SITE (T0603700037)

Vermont Ave., Los Angeles, CA 90005



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1986 and present
- Apparent lack of regulatory oversight
- · No RP identified
- No reports or data in GeoTracker
- Exact location of site unclear

NOTE: Data queried from GeoTracker and reviewed in October 2010

Case Age: 24 years
Primary COC: Gasoline
RP Identified: "BLANK" –
Unclaimed in GeoTracker
Potential Media Affected: Soil
Current land use: Residential?

Well Network: N/A



CLEANUP OVERSIGHT AGENCIES

LOS ANGELES, CITY OF (LEAD) - CASE #: 123

CASEWORKER: PATRICK KILLIAN - SUPERVISOR: NONE SPECIFIED

LOS ANGELES RWQCB (REGION 4) - CASE #: 003008

CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FI	LTER: Show All Activities	•
ACTION TYPE	ACTION	ACTION DATE	
LEAK ACTION	Leak Reported	11/13/1986	
LEAK ACTION	<u>Leak Discovery</u>	11/13/1986	

Activities Conducted to Date Based on GeoTracker T0603700037

Assessment last 5 years

Appears None


Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years



Review Conclusions T0603700037

Review indicates:

- No reports or data in GeoTracker to review
- No RP identified
- Regulatory activities indicates no work has occurred
- Exact site name and location (address) not defined

Discussion:

- Any case information available?
- Age of case is 24-years → any significant risk at site?
- Identify RP
- Next step → is this an actual case? If yes, cleanup timeline or closure possibility ("soils only"?)

HARDING MARKET COMPANY (T0603700578)

3022 Cochran Ave. S., Los Angeles, CA 90016



Case Age: 24 years
Primary COC: Gasoline

RP Identified: Harding Market Company-

Unclaimed in GeoTracker

Potential Media Affected: Soil

Current land use: Commercial (Bakeries)

Well Network: N/A



CLEANUP OVERSIGHT AGENCIES
LOS ANGELES, CITY OF (LEAD)
CASEWORKER: TERRENCE PALMER - SUPERVISOR: NONE SPECIFIED
LOS ANGELES RWQCB (REGION 4) - CASE #: 900160289
CASEWORKER: YUÈ RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FILTER:	Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Stopped	12/19/1986
LEAK ACTION	Leak Reported	12/9/1986
LEAK ACTION	Leak Discovery	2/9/1986

Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1986 and present
- Apparent lack of regulatory oversight and RP involvement
- No reports or data in GeoTracker

NOTE: Data queried from GeoTracker and reviewed in October 2010

Activities Conducted to Date Based on GeoTracker T0603700578

Assessment last 5 years

Appears None

Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years



Review Conclusions T0603700578

Review indicates:

- No reports or data in GeoTracker to review
- Regulatory Activities indicates no work has occurred
- Cleanup Status History indicates "Open Site Assessment" in 1986 and 1987

Discussion:

- Any case information available?
- Age of case is 24-years → any significant risk at site?
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

SHELL (T0603700652)

1520 Santa Fe Ave., Los Angeles, CA 90021



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1987 and present
- Apparent lack of regulatory oversight and RP involvement
- No reports or data in GeoTracker

NOTE: Data queried from GeoTracker and reviewed in October 2010

Case Age: 24 years
Primary COC: Aviation

RP Identified: Fossati, Frank – Unclaimed

in GeoTracker

Potential Media Affected: Soil Current land use: Gas Station (Shell)

Well Network: N/A



CLEANUP OVERSIGHT AGENCIES

LOS ANGELES, CITY OF (LEAD)

CASEWORKER: TERRENCE PALMER - SUPERVISOR: NONE SPECIFIED

LOS ANGELES RWQCB (REGION 4) - CASE #: 900210125

CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE	FILTER: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	3/27/1987
LEAK ACTION	Leak Discovery	3/26/1987
LEAK ACTION	<u>Leak Stopped</u>	3/26/1987

Activities Conducted to Date Based on GeoTracker T0603700652

Assessment last 5 years

Appears None


Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years



Review Conclusions T0603700652

Review indicates:

- Aviation fuel leak (?)
- Site is currently an active gas station
- No reports or data in GeoTracker to review
- Cleanup Status History indicates Site Assessment in 1987 and 2003

Discussion:

- Any case information available?
- Age of case is 24-years and site is an active gas station → any significant risk at site? Potential GW contamination?
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility

SOUTH EAST MAINTENANCE YARD (T0603700099)

4206 Main St. S., Los Angeles, CA 90037



Possible Reasons Why This Case Is So Old

- Appears no activity between 1986 and present
- No local regulatory case worker assigned
- No apparent RP involvement
- No reports or data in GeoTracker
- Site is a government property?

NOTE: Data queried from GeoTracker and reviewed in October 2010

Case Age: 24 years
Primary COC: Gasoline

RP Identified: Treidler, Brooks -

Unclaimed in GeoTracker

Potential Media Affected: Soil Current land use: Commercial (Government Maintenance Yard)

Well Network: N/A



CLEANUP OVERSIGHT AGENCIES
LOS ANGELES, CITY OF (LEAD)
CASEWORKER: TBD - SUPERVISOR: NONE SPECIFIED
LOS ANGELES RWQCB (REGION 4) - CASE #: 080013
CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPO	RT ACTIVITY TYPE F	FILTER: Show All Activities	¥
ACTION TYPE	ACTION	ACTION DATE	
LEAK ACTION	Leak Discovery	12/8/1986	
LEAK ACTION	Leak Reported	12/8/1986	
LEAK ACTION	Leak Stopped	12/8/1986	

Activities Conducted to Date Based on GeoTracker T0603700099

Assessment last 5 years

Appears None


Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years



Review Conclusions T0603700099

Review indicates:

- No reports or data in GeoTracker to review
- Regulatory Activities indicates no work has occurred
- Regulatory lead is not clear in GT no case # or worker information

Discussion:

- Any case information available?
- Age of case is 23-years → any significant risk at site?
- Assign local case worker
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

UNITED AIRLINES (T0603701063)

6020 Avion Dr., Westchester, CA 90045



Case Age: 24 years
Primary COC: Aviation

RP Identified: United Airlines -

Unclaimed in GeoTracker

Potential Media Affected: Soil

Current land use: Commercial (Aircraft

Maintenance)
Well Network: N/A



CLEANUP OVERSIGHT AGENCIES

LOS ANGELES, CITY OF (LEAD)

CASEWORKER: TERRENCE PALMER - SUPERVISOR: NONE SPECIFIED

LOS ANGELES RWOCB (REGION 4) - CASE #: 900450407

CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE F	LTER: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Discovery	3/17/1987
LEAK ACTION	Leak Reported	3/17/1987
LEAK ACTION	Leak Stopped	3/17/1987

Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1987 and present
- Apparent lack of regulatory oversight and RP involvement
- No reports or data in GeoTracker

NOTE: Data gueried from GeoTracker and reviewed in October 2010

Activities Conducted to Date Based on GeoTracker T0603701063

Assessment last 5 years

Appears None


Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years



Review Conclusions T0603701063

Review indicates:

- Aviation fuel release
- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Cleanup Status History indicates "Site Assessment" in 1987

Discussion:

- Any case information available?
- Age of case is 24-years → any significant risk at site?
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

CARDLOCK FUEL SYSTEMS (T0603700478)

2655 Olympic Blvd. W, Los Angeles, CA 90006



Primary COC: Gasoline
RP Identified: Lee, Hong L –
Unclaimed in GeoTracker
Potential Media Affected: Soil
Current land use: Medical (New

Current land use: Medical (New Town

Medical Center)
Well Network: N/A

Case Age: 23 years



CLEANUP OVERSIGHT AGENCIES LOS ANGELES, CITY OF (LEAD) CASEWORKER: TBD - SUPERVISOR: NONE SPECIFIED CASEWORKER: TBD - SUPERVISOR: NONE SPECIFIED

CASEWORKER: <u>18D</u> - SUPERVISOR: NONE SPECIFIED

LOS ANGELES RWQCB (REGION 4) - CASE #: 900060098

CASEWORKER: <u>YUE RONG</u> - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPOR	T ACTIVITY TYPE F	ILTER: Show All Activities
ACTION TYPE	<u>ACTION</u>	ACTION DATE
LEAK ACTION	Leak Reported	6/26/1987
LEAK ACTION	Leak Discovery	4/1/1987

Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1987 and present
- No local regulatory case worker assigned
- No apparent RP involvement
- No reports or data in GeoTracker

NOTE: Data gueried from GeoTracker and reviewed in October 2010

Activities Conducted to Date Based on GeoTracker T0603700478

Assessment last 5 years

Appears None

Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE T0603700478 as reported by regulatory agency CARDLOCK FUEL SYSTEMS (T0603700478) - (MAP) 2655 OLYMPIC BLVD W LOS ANGELES, CA 90006 LOS ANGELES COUNTY LUST CLEANUP SITE Summary Cleanup Status History Regulatory Activities Environmental Data (SI) Site Mags / Documents Community Involvement Regulatory Profile CLEANUP STATUS OPEN - SITE ASSESSMENT AS OF 6/26/1987 POTENTIAL CONTAMINANTS OF CONCERN GASOLINE FILE LOCATION Site History No site history available

Review Conclusions T0603700478

Review indicates:

- Apparent diesel release
- No reports or data in GeoTracker to review
- Regulatory Activities indicates no work has occurred
- Regulatory lead information not complete in GT no local case worker or case #

Discussion:

- Any case information available?
- Age of case is 23-years → any significant risk at site?
- Assign local case worker
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

FAA (T0603701070)

5885 Imperial Hwy. W., Westchester, CA 90045



Case Age: 23 years
Primary COC: Aviation
RP Identified: FAA —
Unclaimed in GeoTracker

Potential Media Affected: Soil

Current land use: Government (US Gov Federal Aviation Administration Office

Well Network: N/A

LEAK ACTION



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1987 and present
- No local regulatory case worker assigned
- No apparent RP involvement
- No reports or data in GeoTracker
- RP is government entity

NOTE: Data queried from GeoTracker and reviewed in October 2010

CLEANUP OVERSIGHT AGENCIES LOS ANGELES, CITY OF (LEAD) CASEWORKER: TBD - SUPERVISOR: NONE SPECIFIED LOS ANGELES RWQCB (REGION 4) - CASE #: 900450543 CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED			
ACTIVITIES REPORT ACTIVITY TYPE FILTER: Show All Activities			
ACTION TYPE	ACTION	ACTION DATE	
LEAK ACTION	Leak Reported	6/19/1097	

6/17/1987

Leak Discovery

Activities Conducted to Date Based on GeoTracker T0603701070

Assessment last 5 years

Appears None

Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE T0603701070 as reported by regulatory agency FAA (T0603701070) - (MAP) 5885 IMPERIAL HWY W WESTCHESTER CA 90045 LOS ANGELES COUNTY LUST CLEANUP SITE Summary Cleanup Status History Regulatory Activities | Regulatory Acti

Review Conclusions T0603701070

Review indicates:

- Aviation fuel release
- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Cleanup Status: Open Remediation as of 1/11/1993
- Regulatory lead information not complete in GeoTracker no local case # worker info

Discussion:

- Any case information available?
- Has remediation been implemented, effectiveness?
- Assign local case worker
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

FRITO-LAY, INC (T0603701066)

8731 Bellanca Ave., West Chester, CA 90045



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1987 and present
- Apparent lack of regulatory oversight and RP involvement
- No reports or data in GeoTracker
- Cleanup Status: Open Inactive?

NOTE: Data queried from GeoTracker and reviewed in October 2010

Case Age: 23 years
Primary COC: Diesel

RP Identified: Frito-Lay, Inc –
Unclaimed in GeoTracker
Potential Media Affected: Soil
Current land use: Unknown

Well Network: N/A



CLEANUP OVERSIGHT AGENCIES	
CLEANUP OVERSIGHT AGENCIES	
LOS ANGELES, CITY OF (LEAD)	
CASEWORKER: TERRENCE PALMER - SUPERVISOR: NONE SPECIFI	IFD.
LOS ANGELES RWQCB (REGION 4) - CASE #: 900450507	
CASEWORKED, VIE DONG SUBERVISOR, NONE SPECIFIED	

ACTIVITIES REPORT	ACTIVITY TYPE F	ILTER: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Discovery	7/10/1987
LEAK ACTION	Leak Reported	7/10/1987
LEAK ACTION	Leak Stopped	7/10/1987

Activities Conducted to Date Based on GeoTracker T0603701066

Assessment last 5 years

Appears None

Remediation last 5 years


Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE T0603701066 as reported by regulatory agency



Review Conclusions T0603701066

Review indicates:

- Diesel fuel release
- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Cleanup Status: Open Inactive as of 5/14/2008

Discussion:

- Any case information available?
- Inactive case status
- Age of case is 23-years → any significant risk at site?
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

HYE CENTER MARKET (T0603702231)

7543 Tampa Ave., Los Angeles, CA 91335



Case Age: 23 years
Primary COC: Aviation

RP Identified: Mobil Oil Corp. -

Unclaimed in GeoTracker

Potential Media Affected: Other GW (Uses Other Than Drinking Water)
Current land use: Commercial (Tampa

Hardware)

Well Network: N/A



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1987 and present
- No local regulatory case worker assigned
- · No apparent RP involvement
- No reports or data in GeoTracker

NOTE: Data gueried from GeoTracker and reviewed in October 2010

CLEANUP OVERSIGHT AGENCIES
LOS ANGELES, CITY OF (LEAD)
CASEWORKER: TBD - SUPERVISOR: NONE SPECIFIED
LOS ANGELES RWQCB (REGION 4) - CASE #: 913350807
CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

		e i le i e i e i e i e i e i e i e i e i
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	<u>Leak Discovery</u>	6/24/1987
LEAK ACTION	Leak Reported	6/24/1987

Activities Conducted to Date Based on GeoTracker T0603702231

Assessment last 5 years

Appears None

Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

AS REPORTED BY REGULATORY AGENCIES LOS ANGELES, CA 91335 LOS ANGELES COUNTY LUST CLEANUP SITE Summary Cleanup Status History Regulatory Activities Toviromental Data (ES) Stor Maps / Documents Community Involved STATATUR - Determination OPEN - SITE ASSESSMENT AS OF 1/27/1992 POTENTIAL CONTAMINANTS OF CONCERN AVAITON FILE LOCATION Site History No site history available

Review Conclusions T0603702231

Review indicates:

- Aviation fuel release
- Regulatory Activities indicates no work has occurred
- Cleanup Status History indicates "Site Assessment" in 1992 (no additional information available)
- No reports or data in GeoTracker to review
- Media affected involves groundwater
- Regulatory lead information incomplete in GT no local case # or worker

Discussion:

- Any case information available?
- Age of case is 23-years → any significant GW contamination at site?
- Assign local case worker
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility

SHELL (T0603700036)

1550 Imperial Hwy., Los Angeles, CA 90047



Possible Reasons Why This Case Is So Old

- No documented cleanup activity between 1987 and present, but listed as in remediation in 1993
- No reports or data in GeoTracker
- Site apparently redeveloped

NOTE: Data queried from GeoTracker and reviewed in October 2010

Case Age: 23 years
Primary COC: Gasoline
RP Identified: Shell Oil –
Unclaimed in GeoTracker
Potential Media Affected: Soil
Current land use: Site use unclear



CLEANUD OVERSIGHT ACENCIES
CLEANUP OVERSIGHT AGENCIES
LOS ANGELES, CITY OF (LEAD)
CASEWORKER: TERRENCE PALMER - SUPERVISOR: NONE SPECIFIED
LOS ANGELES RWQCB (REGION 4) - CASE #: 003001
CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FILTER:	Show All Activities	▼
ACTION TYPE	ACTION	ACTION DATE	
LEAK ACTION	Leak Reported	7/17/1987	
LEAK ACTION	<u>Leak Discovery</u>	7/17/1987	

Activities Conducted to Date Based on GeoTracker T0603700036

Assessment last 5 years

Appears None

Remediation last 5 years


Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

 Appears None, but listed as Open/Remediation 1993



Review Conclusions T0603700036

Review indicates:

- No reports or data in GeoTracker to review
- Cleanup Status in GeoTracker: "Open Remediation" (10/21/1993)
- Site appears to have been redeveloped? → exact location of former Shell station unclear

Discussion:

- Any case information available?
- Age of case is 23-years → any significant risk at site?
- Has remediation been implemented, effectiveness?
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

TERMINAL 6 LAX (T0603701077)

600 World Way, Westchester, CA 90045



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1987 and present
- Apparent lack of regulatory oversight and RP involvement
- No reports or data in GeoTracker
- RP might be government entity?

NOTE: Data queried from GeoTracker and reviewed in October 2010

Case Age: 23 years
Primary COC: Aviation

RP Identified: Swinerton & Walbers
Contractor – Unclaimed in GeoTracker

Potential Media Affected: Soil Current land use: Airport (LA

International Airport)
Well Network: N/A



CLEANUP OVERSIGHT AGENCIES
LOS ANGELES, CITY OF (LEAD)
CASEWORKER: MARCUS LOOK - SUPERVISOR: NONE SPECIFIED
LOS ANGELES RWQCB (REGION 4) - CASE #: 900450616
CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FILTER:	Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Discovery	6/3/1987
LEAK ACTION	Leak Stopped	6/3/1987
LEAK ACTION	<u>Leak Reported</u>	6/3/1987

Activities Conducted to Date Based on GeoTracker T0603701077

Assessment last 5 years

Appears None

Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE T0603701077 as reported by regulatory agency



Review Conclusions T0603701077

Review indicates:

- Aviation fuel release
- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Regulatory lead information not complete in GeoTracker no local case #

Discussion:

- Any case information available?
- Age of case is 23-years → any significant risk at site?
- Check Primary RP listed in GT
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

CHEVRON #9-2683 (T0603702556)

11335 Magnolia Blvd. North Hollywood, CA 91601



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1988 and present
- Apparent lack of regulatory oversight and RP involvement
- No reports or data in GeoTracker
- Site might have been redeveloped?

NOTE: Data queried from GeoTracker and reviewed in October 2010

Case Age: 23 years
Primary COC: Diesel

RP Identified: Chevron USA
Potential Media Affected: Soil
Current land use: Multiple tenant
complex (Tossolini Claudia DDS,

Organic MC)

Well Network: N/A



CLEANUP OVERSIGHT AGENCIES
LOS ANGELES, CITY OF (LEAD)
CASEWORKER: TERRENCE PALMER - SUPERVISOR: NONE SPECIFIED
LOS ANGELES RWQCB (REGION 4) - CASE #: 916011043
CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	<u>Leak Discovery</u>	1/18/1988
LEAK ACTION	<u>Leak Reported</u>	1/17/1988

Activities Conducted to Date Based on GeoTracker T0603701642

Assessment last 5 years

Appears None

Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

as reported by regulatory agency



Review Conclusions T0603702556

Review indicates:

- Diesel fuel release
- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Site might have been redeveloped

Discussion:

- Any case information available?
- Has site been redeveloped?
- Age of case is 23-years → any significant risk at site?
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

ACE BEVERAGE COMPANY (T0603788711)

3616 Noakes St., Los Angeles, CA 90023



Possible Reasons Why This Case Is So Old

- Appears no activity between 1988 and present
- Apparent lack of regulatory oversight and RP involvement
- No reports or data in GeoTracker

NOTE: Data queried from GeoTracker and reviewed in October 2010

Case Age: 22 years
Primary COC: Gasoline

RP Identified: Tan Roosevelt Noakes,

LLC – Unclaimed in GeoTracker Potential Media Affected: Soil Current land use: Industrial (Dial

Industries, Inc.)
Well Network: N/A



CLEANUP OVERSIGHT AGENCIES
LOS ANGELES, CITY OF (LEAD) - CASE #: 59704
CASEWORKER: PATRICK KILLIAN - SUPERVISOR: NONE SPECIFIED
LOS ANGELES RWQCB (REGION 4)
CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE	FILTER: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	9/20/1988
LEAK ACTION	Leak Discovery	5/18/1988
LEAK ACTION	Leak Began	1/1/1965

Activities Conducted to Date Based on GeoTracker T0603788711

Assessment last 5 years

Appears None

Remediation last 5 years


Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE T0603788711 as reported by regulatory agency



Review Conclusions T0603788711

Review indicates:

- Regulatory Activities indicates no work has occurred
- Cleanup Status History indicates Site Assessment in 2008 (no additional information available)
- No reports or data in GeoTracker to review

Discussion:

- Any case information available?
- Age of case is 22-years → any significant risk at site?
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

EXXON (T0603702096)

7215 Canoga Ave., Canoga Park, CA 91303



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1988 and present
- Apparent lack of regulatory oversight and RP involvement
- No reports or data in GeoTracker

NOTE: Data queried from GeoTracker and reviewed in October 2010

Case Age: 22 years
Primary COC: Gasoline

RP Identified: Chatteron, Bill – Unclaimed in GeoTracker

Potential Media Affected: Soil

Current land use: Gas Station (Chevron)

Well Network: N/A



CLEANUP OVERSIGHT AGENCIES

LOS ANGELES, CITY OF (LEAD)

CASEWORKER: TERRENCE PALMER - SUPERVISOR: NONE SPECIFIED

LOS ANGELES RWQCB (REGION 4) - CASE #: 913030916

CASEWORKER: VIJE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT ACTIVITY		ILTER: Show All Activities
ACTION TYPE	<u>ACTION</u>	ACTION DATE
LEAK ACTION	<u>Leak Discovery</u>	5/5/1988
LEAK ACTION	Leak Reported	5/5/1988

Activities Conducted to Date Based on GeoTracker T0603702096

Assessment last 5 years

Appears None

Remediation last 5 years


Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

as reported by regulatory agency



Review Conclusions T0603702096

Review indicates:

- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Site is currently an active gas station
- Contamination was discovered during tank closure in 1988
- Cleanup Status indicates "Site Assessment" in 1988 (no additional information available)

Discussion:

- Any case information available?
- Has groundwater been tested or at risk?
- Age of case is 22-years → any significant risk at site?
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only" criteria?)

HARBOR DISTRICT FACILITIES (T0603701642)

1400 Gaffey St N. Terminal Island, CA 90731



Case Age: 22 years
Primary COC: Aviation

RP Identified: Treidler, E. Brooks Potential Media Affected: Soil

Current land use: Public Service (Gaffey

Street SAFE Collection Center)

Well Network: N/A

CLEANUP OVERSIGHT AGENCIES
LOS ANGELES, CITY OF (LEAD)
CASEWORKER: ELOY LUNA - SUPERVISOR: NONE SPECIFIED
LOS ANGELES RWQCB (REGION 4) - CASE #: 907310361
CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

Possible Reasons Why This Case Is So Old

- · Appears no cleanup activity between 1988 and present
- Apparent lack of regulatory oversight and RP involvement
- No reports or data in GeoTracker
- Case was closed/reopened. New release?
- Possible government site?

NOTE: Data queried from GeoTracker and reviewed in October 2010

Cleanup Status History	
DATE	<u>STATUS</u>
12/20/2007	Open - Remediation
12/19/2007	Open - Reopen Case
7/16/1997	Completed - Case Closed
9/20/1988	Open - Site Assessment
7/11/1988	Open - Case Begin Date
	DATE 12/20/2007 12/19/2007 7/16/1997 9/20/1988

ACTIVITIES REPORT	ACTIVITY TYPE FILTE	R: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	7/14/1988
LEAK ACTION	Leak Discovery	7/11/1988

Activities Conducted to Date Based on GeoTracker T0603701642

Assessment last 5 years

Appears None

Remediation last 5 years


Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

as reported by regulatory agency



Review Conclusions T0603701642

Review indicates:

- Regulatory Activities indicates no work has occurred
- Potential contaminants of concern is aviation fuel
- No reports or data in GeoTracker to review
- Case was closed in 1997 and reopened in 2007. New release?
- Cleanup Status: Open Remediation as of 12/20/2007

Discussion:

- Any case information available?
- Has remediation been implemented, effectiveness?
- RP and GeoTracker compliance
- Reason for reopening this case → any significant risk at site?
- Next step → cleanup timeline or closure possibility ("soils only" criteria?)

MAR VISTA CENTRAL OFFICE (T0603701209)

4121 Grand View Blvd., Mar Vista, CA 90066



Case Age: 22 years Primary COC: Diesel RP Identified: GTE –

Unclaimed in GeoTracker

Potential Media Affected: Soil

Current land use: Commercial (store

fronts)

Well Network: N/A

Street View not available

Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1988 and present
- No local regulatory case worker assigned
- No apparent RP involvement
- No reports or data in GeoTracker

NOTE: Data queried from GeoTracker and reviewed in October 2010

CLEANUP OVERSIGHT AGENCIES
LOS ANGELES, CITY OF (LEAD)
LOS ANGELES RWQCB (REGION 4) - CASE #: 900660116
CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPOR	T ACTIVITY TYPE F	ILTER: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	6/24/1988
LEAK ACTION	Leak Discovery	5/11/1988
LEAK ACTION	Leak Stopped	5/11/1988

Activities Conducted to Date Based on GeoTracker T0603701209

Assessment last 5 years

Appears None

Remediation last 5 years


Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

as reported by regulatory agency



Review Conclusions T0603701209

Review indicates:

- Diesel fuel release
- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Cleanup Status History indicates "Open Site Assessment" (7/3/1989)
- Regulatory lead information not complete in GeoTacker no local case # or worker

Discussion:

- Any case information available?
- Assign local case worker
- RP and GeoTracker compliance
- Age of case is 22-years → any significant risk at site?
- Next step → cleanup timeline or closure possibility ("soils only"?)

NATIONAL CAR SALES (T0603776617 & T06037068170)

9204 S. Airport Blvd., Los Angeles, CA



Case Age: 22 years
Primary COC: Gasoline

RP Identified: National Car Rental

(Incorrectly listed in GT) – Unclaimed in

GeoTracker

Potential Media Affected: Soil

Current land use: Car Rental (Sunrise

Rent-A-Car)

Well Network:

N/A



CLEANUP OVERSIGHT AGENCIES

LOS ANGELES, CITY OF (LEAD) - CASE #: XS0000439

CASEWORKER: MARCUS LOOK - SUPERVISOR: NONE SPECIFIED

LOS ANGELES RWQCB (REGION 4)

CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

 ACTIVITIES REPORT
 ACTIVITY TYPE FILTER: Show All Activities

 ACTION TYPE
 ACTION
 ACTION DATE

 LEAK ACTION
 Leak Reported
 10/4/1988

 LEAK ACTION
 Leak Discovery
 9/21/1988

 LEAK ACTION
 Leak Began
 1/1/1965

DUPLICATE: T0603768170

Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1988 and present
- Apparent lack of regulatory oversight and RP involvement
- No reports or data in GeoTracker

NOTE: Data gueried from GeoTracker and reviewed in October 2010

Activities Conducted to Date Based on GeoTracker T0603776617

Assessment last 5 years

Appears None

Remediation last 5 years


Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE T0603776617 as reported by regulatory agency



Review Conclusions T0603776617

Review indicates:

- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Primary RP is incorrectly listed in GeoTracker as "RPRP1ORG"
- Cleanup Status: Open Remediation as of 12/4/1990

Discussion:

- Any case information available?
- Has remediation been implemented, effectiveness?
- Age of case is 22-years and site use remains the same → any significant risk and source at site?
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

SURFACE PROTECTION INC. (T0603700677)

3411 015th St., E. Los Angeles, CA 90023



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1988 and present
- Apparent lack of regulatory oversight and RP involvement
- No reports or data in GeoTracker

NOTE: Data queried from GeoTracker and reviewed in October 2010

Case Age: 22 years
Primary COC: Aviation

RP Identified: Davidson Robert -

Unclaimed in GeoTracker

Potential Media Affected: Soil

Current land use: Mixed (DJ 4Life Academy)

Well Network: N/A



CLEANUP OVERSIGHT AGENCIES LOS ANGELES, CITY OF (LEAD)
CASEWORKER: MONTE BUCKNER - SUPERVISOR: NONE SPECIFIED
LOS ANGELES RWQCB (REGION 4) - CASE #: 900230261 CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FIL	TER: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	<u>Leak Reported</u>	5/5/1988

Activities Conducted to Date Based on GeoTracker T0603700677

Assessment last 5 years

Appears None

Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE T0603700677 as reported by regulatory agency



Review Conclusions T0603700677

Review indicates:

- Aviation fuel leak
- Regulatory Activities indicates no work has occurred
- Cleanup Status History idicates: Site Assessment in 1989 and 2000, and Remediation as of 4/1/2001
- No reports or data in GeoTracker to review

Discussion:

- Any case information available?
- Has remediation been implemented, effectiveness?
- Age of case is 22-years → any significant risk at site?
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

CHEVRON JAMES, RONALD B (T0603784210)

8055 N. Van Nuys Blvd., Sherman Oaks, CA 91403



Case Age: 22 years Primary COC: Gasoline

RP Identified: Chevron USA Inc -

Unclaimed in GeoTracker

Potential Media Affected: Soil

Current land use: Restaurant (Togo's)

Well Network: N/A



CLEANUP OVERSIGHT AGENCIES

LOS ANGELES, CITY OF (LEAD) - CASE #: XS0000483

CASEWORKER: TBD - SUPERVISOR: NONE SPECIFIED

LOS ANGELES RWQCB (REGION 4)

CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FILTER:	Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	2/24/1989
LEAK ACTION	<u>Leak Discovery</u>	2/21/1989
LEAK ACTION	<u>Leak Began</u>	1/1/1965

Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1989 and present
- No local regulatory case worker assigned
- No apparent RP involvement
- No reports or data in GeoTracker
- Site redeveloped?

NOTE: Data gueried from GeoTracker and reviewed in October 2010

Activities Conducted to Date Based on GeoTracker T0603784210

Assessment last 5 years

Appears None


Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years



Review Conclusions T0603784210

Review indicates:

- Regulatory Activities indicates no work has occurred
- Cleanup Status History indicates Site Assessment in 1991
- No reports or data in GeoTracker to review
- Site is currently a restaurant site appears to have been redeveloped
- Regulatory lead information not complete in GT no local case worker information

Discussion:

- Any case information available?
- Site might have been redeveloped → any significant risk and source at the site?
- Assign a local case worker
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

ORCHARD SUPPLY HARDWARE (T0603797352)

5960 N Sepulveda Blvd. Van Nuys, CA 91411



Case Age: 22 years

Primary COC: Other solvent or non-

petroleum hydrocarbon

RP Identified: Builders Emporium -

Unclaimed in GeoTracker

Potential Media Affected: Soil

Current land use: Commercial (OSH)

Well Network: N/A



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1989 and present
- No local regulatory case worker assigned
- No apparent RP involvement
- No reports or data in GeoTracker

NOTE: Data gueried from GeoTracker and reviewed in October 2010

CLEANUP OVERSIGHT AGENCIES LOS ANGELES, CITY OF (LEAD) - CASE #: XS0000613 CASEWORKER: TBD - SUPERVISOR: NONE SPECIFIED LOS ANGELES RWQCB (REGION 4) CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPOR	RT ACTIVITY TYPE	FILTER: Show All Activities
ACTION TYPE	<u>ACTION</u>	ACTION DATE
LEAK ACTION	Leak Reported	3/31/1989
LEAK ACTION	Leak Discovery	2/1/1989
LEAK ACTION	<u>Leak Began</u>	1/1/1965

Activities Conducted to Date Based on GeoTracker T0603797352

Assessment last 5 years

Appears None


Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years



Review Conclusions T0603797352

Review indicates:

- Other solvent or non-petroleum hydrocarbon release (Federal UST case?)
- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Regulatory lead information not complete in GT no local case worker information

Discussion:

- Any case information available?
- Age of case is 22-years and current land use → any significant risk and source at site?
- Assign a local case worker
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

J GLOVER MFG INC (T0603738449)

15226 W. Stagg St., Van Nuys, CA 91405



Case Age: 21 years

Primary COC: Other solvent or non-

petroleum hydrocarbon

RP Identified: Neumann, Andy (Marine 88 Inc.) – Unclaimed in GeoTracker Potential Media Affected: Soil Current land use: Industrial (Glover

Well Network: N/A



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1989 and present
- No local regulatory case worker assigned
- No apparent RP involvement
- No reports or data in GeoTracker

NOTE: Data queried from GeoTracker and reviewed in October 2010

CLEANUP OVERSIGHT AGENCIES LOS ANGELES, CITY OF (LEAD) - CASE #: XS0000421 CASEWORKER: TBD - SUPERVISOR: NONE SPECIFIED OS ANGELES RWQCB (REGION 4) CASEWORKER: YUE RONG - 1 SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE	FILTER: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	9/28/1989
LEAK ACTION	Leak Discovery	9/18/1989
LEAK ACTION	<u>Leak Began</u>	1/1/1965

Activities Conducted to Date Based on GeoTracker T0603738449

<u>Assessment last 5 years</u>

Appears None


Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years



Review Conclusions T0603738449

Review indicates:

- Other solvents or non-petroleum hydrocarbon release (Federal LUST case?)
- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Cleanup Status History indicates: Site Assessment in 1992 and Remediation as of 10/15/92
- Regulatory lead information not complete in GT no local case worker information

Discussion:

- Any case information available?
- Has remediation been implemented, effectiveness?
- Assign a local case worker
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

LAUSD (T0603737823)

2151 N. Soto St., Los Angeles, CA 90032



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1989 and present
- No local regulatory case worker assigned
- No apparent RP involvement
- No reports or data in GeoTracker
- Site is a school, funding issues?

NOTE: Data queried from GeoTracker and reviewed in October 2010

Case Age: 21 years
Primary COC: Gasoline

RP Identified: Silva, Armando (LAUSD) -

Unclaimed in GeoTracker

Potential Media Affected: Soil Current land use: School (LAUSD)

Well Network: N/A



CLEANUP OVERSIGHT AGENCIES

LOS ANGELES, CITY OF (LEAD) - CASE #: XS0000576

CASEWORKER: TED - SUPERVISOR: NONE SPECIFIED

LOS ANGELES RWQCB (REGION 4)

CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FILTER:	Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	<u>Leak Reported</u>	11/20/1989
LEAK ACTION	Leak Discovery	2/7/1989
LEAK ACTION	<u>Leak Began</u>	1/1/1965

Activities Conducted to Date Based on GeoTracker T0603737823

Assessment last 5 years

Appears None


Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years



Review Conclusions T0603737823

Review indicates:

- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Cleanup Status History indicates: Site Assessment in 1989 and Verification Monitoring as of 10/31/90
- Regulatory lead information not complete in GT no local case worker information

Discussion:

- Any case information available?
- What media monitoring is being verified, ongoing?
- Site is a school → any significant risk and source at site? Funding issues?
- Assign a local case worker
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

SOTO STREET FACILITY (T0603700825)

2100 Soto St., N. Los Angeles, CA 90032



Case Age: 21 years Primary COC: Diesel

RP Identified: Metropolitan Water District

Unclaimed in GeoTracker

Potential Media Affected: Soil

Current land use: Municipal (Metropolitan Water District of Southern California)

Well Network: N/A





CASEWORKER: TED - SUPERVISOR: NONE SPECIFIED

LOS ANGELES RWQCB (REGION 4) - CASE #: 900320125

CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES RE	PORT ACTIVI	TY TYPE FILTER: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	7/18/1989
LEAK ACTION	Leak Discovery	7/10/1989

Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1989 and present
- No local regulatory case worker assigned
- No apparent RP involvement
- No reports or data in GeoTracker
- RP is government agency, funding issues?

NOTE: Data queried from GeoTracker and reviewed in October 2010

Activities Conducted to Date Based on GeoTracker T0603700825

Assessment last 5 years

Appears None

Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE T0603700825 as reported by regulatory agency SOTO STREET FACILITY (T0603700825) - (MAP) 2909 SOTO STN LISAMIP OVERSIGHT AGENCIES LOS ANGELES CO 90032 LOS ANGELES COUNTY LUST CLEANUP SITE CLEANUP STATUS D'ENTABLE AND STATUS D'ENTABLE AND STATUS D'ENTABLE CONTAMINANTS OF CONCERN D'ENSEL POTENTIAL CONTAMINANTS OF CONCERN D'ESEL SITE HISTORY No site history available

Review Conclusions T0603700825

Review indicates:

- Diesel fuel release
- Regulatory Activities indicates no work has occurred
- Cleanup Status: Open Remediation as of 5/31/91
- No reports or data in GeoTracker to review
- Regulatory lead information not complete in GeoTracker no case worker or local case #

Discussion:

- Any case information available?
- Has remediation been implemented; effectiveness?
- Assign local case worker
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

ANCHOR (T0603764849)

6616 N. Reseda Blvd., Reseda, CA 91335



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1990 and present
- No local regulatory case worker assigned
- No apparent RP involvement
- No reports or data in GeoTracker

NOTE: Data queried from GeoTracker and reviewed in October 2010

Case Age: 21 years
Primary COC: Gasoline

RP Identified: Brown, Jeff (The Anchor)

Potential Media Affected: Soil Current land use: Commercial (The

Anchor)

Well Network: N/A



CLEANUP OVERSIGHT AGENCIES

LOS ANGELES, CITY OF (LEAD) - CASE #: XS0000546
CASEWORKER: TED - SUPERVISOR: NONE SPECIFIED
LOS ANGELES RWQCB (REGION 4)
CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPOR	T ACTIVITY TYPE FILTER:	Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	3/15/1990
LEAK ACTION	Leak Discovery	1/24/1990
LEAK ACTION	<u>Leak Began</u>	1/1/1965

Activities Conducted to Date Based on GeoTracker T0603764849

Assessment last 5 years

Appears None

Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

ANCHOR (T0603764849) - (MAP) RRIGH RESEDA, CA 91335 LOS ANGELES COUNTY LUST CLEANUP STATUS - Regulatory Activities | Environmental Data (ES) | Site Maps / Documents | Community Involvement | CLEANUP STATUS - Regulatory Activities | Environmental Data (ES) | Site Maps / Documents | Community Involvement | CLEANUP STATUS - Regulatory Activities | Environmental Data (ES) | Site Maps / Documents | Community Involvement | CLEANUP STATUS - Regulatory Activities | Environmental Data (ES) | Site Maps / Documents | Community Involvement | CLEANUP STATUS - Regulatory Activities | Environmental Data (ES) | Site Maps / Documents | CLEANUP STATUS - Regulatory Activities | Environmental Data (ES) | Site Maps / Documents | CLEANUP STATUS - Regulatory Activities | Environmental Data (ES) | Site Maps / Documents | CLEANUP STATUS - Regulatory Activities | Environmental Data (ES) | Site Maps / Documents | CLEANUP STATUS - Regulatory Activities | CLE

Review Conclusions T0603764849

Review indicates:

- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Regulatory lead information not complete in GT no local case worker information

Discussion:

- Any case information available?
- Age of case is 21-years → any significant risk and source at site?
- Assign a local case worker
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

AUTO RITE (T0603790746)

20952 W Sherman Way. Canoga Park, CA 91303



Case Age: 21 years

Primary COC: Other Solvent or Non-Petroleum Hydrocarbon RP Identified: Auto Rite – Unclaimed in GeoTracker Potential Media Affected: Soil Current land use: Commercial

(Dealer's Auto Center)
Well Network: N/A

Possible Reasons Why This Case Is So Old

- No activity between 1989 and present
- Apparent lack of regulatory oversight and RP involvement
- No reports or data in GeoTracker

NOTE: Data queried from GeoTracker and reviewed in October 2010

CLEANUP OVERSIGHT AGENCIES
LOS ANGELES, CITY OF (LEAD) - CASE #: XS0000412
CASEWORKER: PATRICK KILLIAN - SUPERVISOR: NONE SPECIFIED
LOS ANGELES RWQCB (REGION 4)
CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE I	FILTER: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	12/28/1989
LEAK ACTION	Leak Discovery	8/11/1989
LEAK ACTION	<u>Leak Began</u>	1/1/1965

Activities Conducted to Date Based on GeoTracker T0603790746

Assessment last 5 years

Appears None

Remediation last 5 years


Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

as reported by regulatory agency



Review Conclusions T0603790746

Review indicates:

- Solvent or other non-petroleum release (Federal UST case?)
- Regulatory Activities indicates no work has occurred
- Cleanup Status History indicates Site Assessment in 2007
- No reports or data in GeoTracker to review

Discussion:

- Any case information available?
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

GREYHOUND LINES INC (T0603770957)

1614 E. 7th St., Los Angeles, CA 90021



Case Age: 21 years
Primary COC: Diesel

RP Identified: Greyhound Lines, Inc. -

Unclaimed in GeoTracker
Potential Media Affected: Soil
Current land use: Transportation

(Greyhound Lines)
Well Network: N/A



CLEANUP OVERSIGHT AGENCIES LOS ANGELES, CITY OF (LEAD) CASEWORKER: TBD - SUPERVISOR: NONE SPECIFIED LOS ANGELES RWQCB (REGION 4) CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE F	ILTER: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Discovery	4/12/1990
LEAK ACTION	Leak Reported	4/12/1990
LEAK ACTION	<u>Leak Began</u>	1/1/1965

Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1990 and present
- No local regulatory case worker assigned
- No apparent RP involvement
- No reports or data in GeoTracker
- On going source? (bus terminal)

NOTE: Data queried from GeoTracker and reviewed in October 2010

Activities Conducted to Date Based on GeoTracker T0603770957

Assessment last 5 years

Appears None


Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years



Review Conclusions T0603770957

Review indicates:

- Diesel fuel release
- Regulatory Activities indicates no work has occurred
- Cleanup Status History indicates Site Assessment in 2004
- No reports or data in GeoTracker to review
- Site is a Greyhound Bus Terminal
- Regulatory lead information not complete in GT no local case # or worker information

Discussion:

- Any case information available?
- Current land use → any significant risk and source at site?
- Assign a local case worker
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

JEAN PIERRE PRODUCTS INC (T0603713919)

19750 Magellan Dr S., Torrance, CA 90502



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1990 and present
- Apparent lack of regulatory oversight and RP involvement
- No reports or data in GeoTracker

NOTE: Data queried from GeoTracker and reviewed in October 2010

Case Age: 21 years
Primary COC: Gasoline
RP Identified: Dong Kuk Co. –
Unclaimed in GeoTracker

Potential Media Affected: Soil Current land use: Industrial (Dongkuk

International Inc)
Well Network: N/A



CLEANUP OVERSIGHT AGENCIES

LOS ANGELES, CITY OF (LEAD) - CASE #: XS0001459

CASEWORKER: TERRENCE PALMER - SUPERVISOR: NONE SPECIFIED

LOS ANGELES RWQCB (REGION 4)

CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE F	ILTER: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	4/9/1990
LEAK ACTION	Leak Discovery	4/2/1990
LEAK ACTION	<u>Leak Began</u>	1/1/1965

Activities Conducted to Date Based on GeoTracker T0603713919

Assessment last 5 years

Appears None

Remediation last 5 years


Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE T0603713919 as reported by regulatory agency



Review Conclusions T0603713919

Review indicates:

- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Cleanup Status History indicates Site Assessment in 1999 (no additional information available)
- Site currently appears to be an industrial area

Discussion:

- Any case information available?
- Age of case is 21-years → any significant risk at site?
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

UNOCAL – ABRAHAM ROISMAN (T0603786425)

10831 W. Pico Blvd., Los Angeles, CA 90064



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1988 and present
- Apparent lack of regulatory oversight and RP involvement
- No reports or data in GeoTracker
- Site redeveloped?

NOTE: Data queried from GeoTracker and reviewed in October 2010

Case Age: 21 years

Primary COC: Other solvent or non-petroleum hydrocarbon **RP Identified:** Terra Vac Corp. –

Unclaimed in GeoTracker

Potential Media Affected: Soil

Current land use: Commercial (Guitar

Center)

Well Network: N/A



CLEANUP OVERSIGHT AGENCIES
LOS ANGELES, CITY OF (LEAD)
CASEWORKER: NEAL REITZELL
LOS ANGELES RWQCB (REGION 4)
CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FILTE	R: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	3/1/1990
LEAK ACTION	Leak Discovery	9/6/1988
LEAK ACTION	<u>Leak Began</u>	1/1/1965

Activities Conducted to Date Based on GeoTracker T0603786425

Assessment last 5 years

Appears None

Remediation last 5 years


Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

as reported by regulatory agency



Review Conclusions T0603786425

Review indicates:

- Other solvent or non-petroleum hydrocarbon release (Federal UST case?)
- Regulatory Activities indicates no work has occurred
- Cleanup Status: Open Remediation as of 9/16/1989
- No reports or data in GeoTracker to review
- Site is currently a commercial area appears to have been redeveloped?

Discussion:

- Any case information available?
- Has remediation been implemented, effectiveness?
- Current site use → any significant risk and source at site?
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

ARCO #1097 (T0603702284)

15350 Nordhoff St., North Hills, CA 91343



Possible Reasons Why This Case Is So Old

- · Appears little activity between 1987 and
- Apparent lack of regulatory oversight and RP involvement
- No reports in GeoTracker
- Site might have been redeveloped
- Site closure requested in 2003?

NOTE: Data queried from GeoTracker and reviewed in October 2010

Case Age: 20 years

Primary COC: Other Solvent or Non-

Petroleum Hydrocarbon

RP Identified: Arco Products Co. -

Unclaimed in GeoTracker

Potential Media Affected: Soil

Current land use: Commercial (Mall

Outlet)

Well Network: N/A



CLEANUP OVERSIGHT AGENCIES

LOS ANGELES, CITY OF (LEAD)

CASEWORKER: NEAL REITZELL
- SUPERVISOR: NONE SPECIFIED

LOS ANGELES RWQCB (REGION 4) - CASE #: 913430443

CASEWORKER: YUE RONG
- SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FILTER:	Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	<u>Leak Reported</u>	1/18/1991
LEAK ACTION	Leak Discovery	1/15/1991

Activities Conducted to Date Based on GeoTracker T0603702284

Assessment last 5 years

- UST removal compliance samples; no report available
- Site assessment soil samples; no report available
- Site closure request; no documents available

Assessment older than 5 years


Appears None

Remediation last 5 years

Appears None

Remediation older than 5 years

as reported by regulatory agency



Review Conclusions T0603702284

Review indicates:

- Other solvent or non-petroleum fuel release (Federal UST case?)
- Regulatory Activities indicates no work has occurred
- No recent reports in GeoTracker to review
- Cleanup Status: Open Verification Monitoring as of 2/6/2003
- Site appears to have been redeveloped
- Site Assessment Report and Closure Request (2002) in GeoTracker under data – soil sampling results in moderate values

Discussion:

- Any recent case information available?
- Soil sample results from 2002
- RP and GeoTracker compliance
- Next step → cleanup closure timeline or closure possibility ("soils only"?)

Unable to ascertain Case status, no documents to review

ARAMARK UNIFORM SERVICES (T0603751654)

15372 W. Colbalt St., Los Angeles, CA 91342



Uniform Services)

Current land use: Commercial (Aramark Well Network: N/A

Unclaimed in GeoTracker Potential Media Affected: Soil

Case Age: 20 years **Primary COC:** Gasoline

Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1990 and present
- No local regulatory case worker assigned
- No apparent RP involvement
- No reports or data in GeoTracker

NOTE: Data queried from GeoTracker and reviewed in October 2010

RP Identified: Overhead Door Corp. -

CLEANUP OVERSIGHT AGENCIES

CITY OF (LEAD) - CASE #: XS0000636 LOS ANGELES, CITY OF (LEAD) - CASE #: XS0000636 CASEWORKER: TBD - SUPERVISOR: NONE SPECIFIED LOS ANGELES RWOOGB (REGION 4)

CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE F	FILTER: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	5/29/1990
LEAK ACTION	Leak Discovery	5/7/1990
LEAK ACTION	<u>Leak Began</u>	1/1/1965

Activities Conducted to Date Based on GeoTracker T0603751654

<u>Assessment last 5 years</u>

Appears None


Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years



Review Conclusions T0603751654

Review indicates:

- Regulatory Activities indicates no work has occurred
- Cleanup Status History indicates: Site Assessment in 1990 and 1991, and Remediation in 1991
- No reports or data in GeoTracker to review
- Regulatory lead information not complete in GT no local case worker information

Discussion:

- Any case information available?
- Has remediation been implemented, effectiveness?
- Assign a local case worker
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

BOX & GEAR TRANSMISSIONS (T0603746763)

7755 N. Sepulveda Blvd., Van Nuys, CA 91405



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1990 and present
- Apparent lack of regulatory oversight and RP involvement
- No reports or data in GeoTracker

NOTE: Data queried from GeoTracker and reviewed in October 2010

Case Age: 20 years

Primary COC: Other Solvent or Non-Petroleum Hydrocarbon

RP Identified: Aspen Development -

Unclaimed in GeoTracker

Potential Media Affected: Soil

Current land use: Strip mall (Auto body

shop)

Well Network: N/A



CLEANUP OVERSIGHT AGENCIES
LOS ANGELES, CITY OF (LEAD) - CASE #: XS0000767
CASEWORKER: TERRENCE PALMER - SUPERVISOR: NONE SPECIFIED
LOS ANGELES RWQCB (REGION 4)
CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE F	ILTER: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Discovery	10/12/1990
LEAK ACTION	Leak Reported	10/12/1990
LEAK ACTION	<u>Leak Began</u>	1/1/1965

Activities Conducted to Date Based on GeoTracker T0603746763

Assessment last 5 years

Appears None

Remediation last 5 years


Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE T0603746763 as reported by regulatory agency



Review Conclusions T0603746763

Review indicates:

- Other solvent or non-petroleum hydrocarbon release (Federal UST case?)
- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Cleanup Status History: Site Assessment in 1991 and Remediation as of 1/22/1991

Discussion:

- Any case information available?
- Has remediation been implemented, effectiveness?
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

TERMINAL #1 LAX (T0603701075)

100 World Way, Westchester, CA 90045



• Appears no cleanup activity between 1990 and present

Possible Reasons Why This Case Is So Old

- Apparent lack of regulatory oversight and RP involvement
- No reports or data in GeoTracker
- RP is government entity?

NOTE: Data queried from GeoTracker and reviewed in October 2010

Case Age: 20 years Primary COC: Gasoline RP Identified: US Air -**Unclaimed in GeoTracker**

Potential Media Affected: Soil Current land use: Parking Lot (LA International Airport Parking Lot)

Well Network: N/A



CLEANUP OVERSIGHT AGENCIES LOS ANGELES, CITY OF (LEAD)

CASEWORKER: PATRICK KILLIAN - SUPERVISOR: NONE SPECIFIED

LOS ANGELES RWQCB (REGION 4) - CASE #: 900450598 CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FILTER:	Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	<u>Leak Discovery</u>	11/6/1990
LEAK ACTION	Leak Stopped	11/6/1990
LEAK ACTION	Leak Reported	11/6/1990

Activities Conducted to Date Based on GeoTracker T0603701075

<u>Assessment last 5 years</u>

Appears None

Remediation last 5 years


Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE T0603701075 as reported by regulatory agency



Review Conclusions T0603701075

Review indicates:

- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Cleanup Status History indicates "Open Site Assessment" (12/3/2002)
- Site appears to be an airline terminal parking lot

Discussion:

- Any case information available?
- Information on site assessment conducted in 2002
- Age of case is 20-years → any significant risk at site?
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

WORLDWIDE FLIGHT SERVICES (T0603736969)

7000 World Way W., Los Angeles, CA



Case Age: 20 years
Primary COC: Aviation

RP Identified: American Airlines -

Unclaimed in GeoTracker
Potential Media Affected: Soil
Current land use: Commercial

Well Network: N/A



CLEANUP OVERSIGHT AGENCIES
LOS ANGELES, CITY OF (LEAD) - CASE #: XS0000596
CASEWORKER: TBD - SUPERVISOR: NONE SPECIFIED
LOS ANGELES RWQCB (REGION 4)
CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPO	RT ACTIVITY TYPE I	FILTER: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	8/24/1990
LEAK ACTION	Leak Discovery	7/10/1990
LEAK ACTION	<u>Leak Began</u>	1/1/1965

Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1990 and present
- No local regulatory case worker assigned
- No apparent RP involvement
- No reports or data in GeoTracker
- Site is an airport

NOTE: Data gueried from GeoTracker and reviewed in October 2010

Activities Conducted to Date Based on GeoTracker T0603736969

Assessment last 5 years

Appears None

Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE T0603736969 as reported by regulatory agency WORLDWIDE FLIGHT SERVICES (T0603736969) - (MAP) 7000 WORLD W/ W 1.05 ANGELES CA LOS ANGELES CA LOS ANGELES COUNTY LUST CLEANUP SITE CLEANUP STATUS - represented CLEANUP

Review Conclusions T0603736969

Review indicates:

- Aviation fuel release
- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Cleanup Status History indicates Site Assessment in 1993 (no additional information available)
- Regulatory lead information not complete in GT no local case worker information

Discussion:

- Any case information available?
- Site is an airport → any significant risk and source at site?
- Assign local case worker
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

AAA FOREIGN AUTO PARTS AND SALVAGE INC (T0603745855)

9101 N. Glenoaks Blvd., Sun Valley, CA 91352



Case Age: 20 years Primary COC: Gasoline

RP Identified: AAA Foreign Auto Parts -

Unclaimed in GeoTracker Potential Media Affected: Soil

Current land use: Auto Service (Royal

Auto Dismantling Inc)

Well Network:

N/A



LOS ANGELES, CITY OF (LEAD) - CASE #: XS0000663

CASEWORKER: TBD - SUPERVISOR: NONE SPECIFIED OS ANGELES RWQCB (REGION 4)

CASEWORKER: YUE RONG

ACTIVITIES REPORT	ACTIVITY TYPE FILTER:	Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	4/12/1991
LEAK ACTION	Leak Discovery	4/8/1991
LEAK ACTION	<u>Leak Began</u>	1/1/1965

Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1991 and present
- No local regulatory case worker assigned
- No apparent RP involvement
- No reports or data in GeoTracker

NOTE: Data queried from GeoTracker and reviewed in October 2010

Activities Conducted to Date Based on GeoTracker T0603745855

<u>Assessment last 5 years</u>

Appears None


Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years



Review Conclusions T0603745855

Review indicates:

- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Regulatory lead information not complete in GT no local case worker information

Discussion:

- Any case information available?
- Any significant risk and source at site?
- Assign a local case worker
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

FRITZ HUMMEL (T0603789252 & T0603764257)

4707-34 Huntington Dr. Los Angeles, CA



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1990 and present
- Apparent lack of regulatory oversight and RP involvement
- No reports or data in GeoTracker
- Site has been redeveloped?

NOTE: Data queried from GeoTracker and reviewed in October 2010

Case Age: 20 years
Primary COC: Gasoline

RP Identified: Hummel, Timothy -

Unclaimed in GeoTracker

Potential Media Affected: Soil Current land use: Vacant Lot

Well Network: N/A

DUPLICATE: same as T0603764257



CLEANUP OVERSIGHT AGENCIES

LOS ANGELES, CITY OF (LEAD) - CASE #: XS0000017 CASEWORKER: MARCUS LOOK - SUPERVISOR: NONE SPECIFIED

LOS ANGELES RWQCB (REGION 4)

CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FILTE	R: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	<u>Leak Reported</u>	1/29/1991
LEAK ACTION	Leak Discovery	2/22/1990
LEAK ACTION	<u>Leak Began</u>	1/1/1965

Activities Conducted to Date Based on GeoTracker T0603789252

Assessment last 5 years

Appears None

Remediation last 5 years


Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

as reported by regulatory agency



Review Conclusions T0603789252

Review indicates:

- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Site is currently a vacant lot
- Appears to be a duplicate in GeoTracker with case T0603764257

Discussion:

- Any case information available?
- Check duplicate case
- Vacant lot → any significant risk at site?
- RP and GeoTracker compliance including duplicate case #
- Next step → cleanup timeline or closure possibility ("soils only"?)

LA DWP - DEPT OF WATER & POWER (T0603790000)

1324 S. Wall St., Los Angeles, CA 90015



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1990 and present
- Apparent lack of regulatory oversight and RP involvement
- No reports or data in GeoTracker
- RP is government entity, funding issues?

NOTE: Data queried from GeoTracker and reviewed in October 2010

Case Age: 20 years

Primary COC: Toluene, Xylene

RP Identified: LA Dept. of Water and Power – Unclaimed in GeoTracker Potential Media Affected: Soil

Current land use: Residential (Street

Intersection)

Well Network: N/A



CLEANUP OVERSIGHT AGENCIES

LOS ANGELES, CITY OF (LEAD) - CASE #: XS0000740

CASEWORKER: PATRICK KILLIAN - SUPERVISOR: NONE SPECIFIED

LOS ANGELES RWQCB (REGION 4)

CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE F	ILTER: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	3/7/1991
LEAK ACTION	Leak Discovery	12/3/1990
LEAK ACTION	<u>Leak Began</u>	1/1/1965

Activities Conducted to Date Based on GeoTracker T0603790000

Assessment last 5 years

Appears None

Remediation last 5 years


Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

as reported by regulatory agency



Review Conclusions T0603790000

Review indicates:

- Xylene and toluene release
- Regulatory Activities indicates no work has occurred
- Cleanup Status History indicates Site Assessment in 2007, was an investigation performed? Results available to upload to GT?
- No reports or data in GeoTracker to review

Discussion:

- Any case information available?
- Site appears to be a residential area → any significant risk at site?
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

LAFD – FIRE STATION 54 (T0603744598)

5730 S. Crenshaw Blvd., Los Angeles, CA 90043



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1990 and present
- No local regulatory case worker assigned
- No apparent RP involvement
- No reports or data in GeoTracker
- RP is a government entity, funding issues?
- Site redeveloped?

NOTE: Data queried from GeoTracker and reviewed in October 2010

Case Age: 20 years
Primary COC: Diesel

RP Identified: City of LA Bureau of Engineers – **Unclaimed in GeoTracker**

Potential Media Affected: Soil Current land use: Unknown

Well Network: N/A



CLEANUP OVERSIGHT AGENCIES

LOS ANGELES, CITY OF (LEAD) - CASE #: XS0000617

CASEWORKER: TBD - SUPERVISOR: NONE SPECIFIED

LOS ANGELES RWQCB (REGION 4)

CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE F	ILTER: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	1/24/1991
LEAK ACTION	Leak Discovery	12/26/1990
LEAK ACTION	<u>Leak Began</u>	1/1/1965

Activities Conducted to Date Based on GeoTracker T0603744598

Assessment last 5 years

Appears None


Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years



Review Conclusions T0603744598

Review indicates:


- Diesel fuel release
- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Current site use is unclear might have been redeveloped
- Regulatory lead information not complete in GT no local case worker information

Discussion:

- Any case information available?
- Current land use → any significant risk and source at site?
- Assign a local case worker
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

LAUSD - NORTH VALLEY OCCUPATIONAL CENTER (T0603712781)

11450 N Sharp Ave., Mission Hills, CA 91345



Case Age: 20 years **Primary COC:** Gasoline

RP Identified: Silva, Armando (LAUSD) -

Unclaimed in GeoTracker

Potential Media Affected: Soil

Current land use: School (North Valley

Occupational) Well Network: N/A



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1990 and present
- No local regulatory case worker assigned
- No apparent RP involvement
- No reports or data in GeoTracker
- Government site? Funding issues?

NOTE: Data queried from GeoTracker and reviewed in October 2010

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES, CITY OF (LEAD) - CASE #: XS0000629

CASEWORKER: TBD - SUPERVISOR: NONE SPECIFIED LOS ANGELES RWQCB (REGION 4)

CASEWORKER: YUE RONG - 5 SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FIL	TER: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	12/15/1990
LEAK ACTION	Leak Discovery	4/10/1990
LEAK ACTION	<u>Leak Began</u>	1/1/1965

Activities Conducted to Date Based on GeoTracker T0603712781

<u>Assessment last 5 years</u>

Appears None

Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE T0603712781 as reported by regulatory agency LAUSD - NORTH VALLEY OCCUPATIONAL CNTR (T0603712781) - (MAP) 11450 N SHARP AVE MISSION HILLS, CA 91345 LOS ANGELES COUNTY LUST CLEANUP SITE Summary Genup Status History Regulatory Activities Environmental Data (53) Site Maps / Documents Community Involvement Summary Genup Status - Geraticus - Geraticus OPEN - STEE ASSESSMENT AS OF 1/16/1991 POTENTIAL CONTAMINANTS OF CONCERN GASOLINE FILE LOCATION Site History No site history available

Review Conclusions T0603712781

Review indicates:


- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Site is currently a school
- Cleanup Status History indicates Site Assessment in 1991

Discussion:

- Any case information available?
- Site is a school → any significant risk at site?
- Assign a local case worker
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

LAUSD – SAFETY SECTION BUS DIV (T0603788360)

1425 S San Pedro St., Los Angeles, CA 90014



Case Age: 20 years

Primary COC: Other Solvent or Non-

Petroleum Hydrocarbon

RP Identified: Silva, Armando (LAUSD) -

Unclaimed in GeoTracker

Potential Media Affected: Soil

Current land use: School (City of Angels)

Well Network: N/A



CLEANUP OVERSIGHT AGENCIES
LOS ANGELES, CITY OF (LEAD) - CASE #: XS0000953
CASEWORKER: TERRENCE PALMER - SUPERVISOR: NONE SPECIFIED
LOS ANGELES RWQCB (REGION 4)
CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE F	ILTER: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	3/19/1991
LEAK ACTION	Leak Discovery	2/20/1991
LEAK ACTION	<u>Leak Began</u>	1/1/1965

Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1991 and present
- Apparent lack of regulatory oversight and RP involvement
- No reports or data in GeoTracker
- RP is government entity, funding issues?

NOTE: Data queried from GeoTracker and reviewed in October 2010

Activities Conducted to Date Based on GeoTracker T0603788360

Assessment last 5 years

Appears None

Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

as reported by regulatory agency



Review Conclusions T0603788360

Review indicates:

- Potential contaminants of concern is other solvent or non-petroleum hydrocarbon (Federal UST case?)
- Regulatory Activities indicates no work has occurred
- Cleanup Status History indicates Site Assessment and Remediation in 1995
- No reports or data in GeoTracker to review

Discussion:

- Any case information available?
- Has remediation been implemented, effectiveness?
- Site is a school → any significant risk at site?
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

MAGNESS PETROLEUM CO (T0603712547)

625 E Anaheim St., Los Angeles, CA 90744



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1991 and present
- No local regulatory case worker assigned
- No apparent RP involvement
- No reports or data in GeoTracker
- Site might have been redeveloped?

NOTE: Data queried from GeoTracker and reviewed in October 2010

Case Age: 20 years

Primary COC: Waste Oil / Motor /

Hydraulic / Lubricating

RP Identified: Exxon Company USA -

Unclaimed in GeoTracker

Potential Media Affected: Soil

Current land use: Wilmington Industrial

Park

Well Network: N/A



CLEANUP OVERSIGHT AGENCIES

LOS ANGELES, CITY OF (LEAD) - CASE #: XS0000662

CASEWORKER: TBD - SUPERVISOR: NONE SPECIFIED

LOS ANGELES RWQCB (REGION 4)

ACTIVITIES REPORT	ACTIVITY TYPE FILTER:	Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	4/18/1991
LEAK ACTION	Leak Discovery	3/27/1991
LEAK ACTION	<u>Leak Began</u>	1/1/1965

Activities Conducted to Date Based on GeoTracker T0603712547

Assessment last 5 years

Appears None

Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE T0603712547 as reported by regulatory agency MAGNESS PETROLEUM COMPANY (T0603712547) - (MAP) 625 E ANAHEM ST LOS ANGELES, CA 90744 LOS ANGELES COUNTY LUST OLEANUP SITE Someony Cleamy Status History Regulatory Activities Someony Cleamy Status History POTENTIAL CONTAMINATIONS of CONCERN WASTE OIL MOTOR HYDRAULIC / LUBRICATING PLE LOCATION Site History No site history available

Review Conclusions T0603712547

Review indicates:

- Waste oil / motor / hydraulic / lubricating release
- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Cleanup Status History indicates: Site Assessment and Remediation in 1991 (no additional information available)
- Site appears to have been redeveloped

Discussion:

- Any case information available?
- Assign a local case worker
- Has remediation been implemented, effectiveness?
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

MOBIL - CARDENAS, RICHARD (T0603710593)

2829 Main St. N., Los Angeles, CA 90031



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1991 and present
- Apparent lack of regulatory oversight and RP involvement
- No reports or data in GeoTracker
- Site might have been redeveloped

NOTE: Data queried from GeoTracker and reviewed in October 2010

Case Age: 20 years
Primary COC: Gasoline

RP Identified: Pals Associates -

Unclaimed in GeoTracker

Potential Media Affected: Soil

Current land use: Auto Service (North

Main Services)
Well Network: N/A



CLEANUP OVERSIGHT AGENCIES
LOS ANGELES, CITY OF (LEAD) - CASE #: XS0000624
CASEWORKER: TERRENCE PALMER - SUPERVISOR: NONE SPECIFIED
LOS ANGELES RWQCB (REGION 4)
CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	1/25/1991
LEAK ACTION	Leak Discovery	1/14/1991
LEAK ACTION	<u>Leak Began</u>	1/1/1965

Activities Conducted to Date Based on GeoTracker T0603710593

Assessment last 5 years

Appears None

Remediation last 5 years


Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

as reported by regulatory agency



Review Conclusions T0603710593

Review indicates:

- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Site might have been redeveloped

Discussion:

- Any case information available?
- Has site been redeveloped? → any significant risk or source at site?
- RP and GeoTracker compliance issues to be resolved
- Next step → cleanup timeline or closure possibility ("soils only"?)

REYCREST ROOFING/WATERPROOFING CO (T0603776777)

3065 N. Verdugo Rd., Los Angeles, CA 90065



Case Age: 20 years

Primary COC: Diesel, other solvent or

non-petroleum hydrocarbon **RP Identified:** Reverest Roofing & Waterproofing - Unclaimed in

GeoTracker

Potential Media Affected: Soil Current land use: Unclear

Well Network: N/A



LOS ANGELES, CITY OF (LEAD) - CASE #: XS0000671

CASEWORKER: TBD - SUPERVISOR: NONE SPECIFIED
LOS ANGELES RWQCB (REGION 4)

CASEWORKER: YUE RONG -

ACTIVITIES REPORT	ACTIVITY TYPE FILTE	Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	11/28/1990
LEAK ACTION	<u>Leak Discovery</u>	11/20/1990
LEAK ACTION	<u>Leak Began</u>	1/1/1965

Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1990 and present
- No local regulatory case worker assigned
- No apparent RP involvement
- No reports or data in GeoTracker
- Exact location unclear

NOTE: Data queried from GeoTracker and reviewed in October 2010

Activities Conducted to Date Based on GeoTracker T0603776777

<u>Assessment last 5 years</u>

Appears None

Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE T0603776777 as reported by regulatory agency REYCREST ROOFING/WATERPROOFING CO (T0603776777) - (MAP) 2006 NVFRINGO RD 1005 ANGELES CA 90065 1005 ANGELES CO 1007 (LEAN) OVERSIGHT AGENCIES 1005 ANGELES CO 1007 (LEAN) OVERSIGHT AGENCIES

Review Conclusions T0603776777

Review indicates:

- Diesel, other solvent or non-petroleum hydrocarbon release
- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Exact location and current land use unclear

Discussion:

- Any case information available?
- Check site location/address
- Any significant risk and source at site?
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

SALVATION ARMY THRIFT STORE (T0603715897)

6059 N Van Nuys Blvd. Van Nuys, CA 91401



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1990 and present
- No local regulatory case worker assigned
- No apparent RP involvement
- No reports or data in GeoTracker

NOTE: Data queried from GeoTracker and reviewed in October 2010

Case Age: 20 years
Primary COC: Gasoline

RP Identified: Salvation Army Thrift Store – Unclaimed in GeoTracker Potential Media Affected: Soil Current land use: Commercial

(Smart & Final)
Well Network: N/A



CLEANUP OVERSIGHT AGENCIES
LOS ANGELES, CITY OF (LEAD) - CASE #: XS0000786
CASEWORKER: TBD - SUPERVISOR: NONE SPECIFIED
LOS ANGELES RWQCB (REGION 4)
CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FIL	TER: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	2/22/1991
LEAK ACTION	Leak Discovery	8/9/1990
LEAK ACTION	<u>Leak Began</u>	1/1/1965

Activities Conducted to Date Based on GeoTracker T0603715897

Assessment last 5 years

Appears None


Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years



Review Conclusions T0603715897

Review indicates:

- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Cleanup Status History indicates "Open Remediation" as of 1/18/1994
- Regulatory lead information not complete in GT no local case worker information

Discussion:

- Any case information available?
- Has remediation been implemented, effectiveness?
- Assign a local case worker
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

CROWN CORK & SEAL COMPANY INC (T0603702447)

8201 Woodley Ave., Van Nuys, CA 91406



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1991 and present
- No local regulatory case worker assigned
- No apparent RP involvement
- No reports or data in GeoTracker

NOTE: Data gueried from GeoTracker and reviewed in October 2010

Case Age: 19 years
Primary COC: Solvents

RP Identified: Crown Cork & Seal Co.,

Inc. - Unclaimed in GeoTracker

Potential Media Affected: Other GW (Uses Other Than Drinking Water)
Current land use: Commercial (Micro

Solutions Enterprises)
Well Network: N/A



CLEANUP OVERSIGHT AGENCIES LOS ANGELES, CITY OF (LEAD) CASEWORKER: TBD - SUPERVISOR: NONE SPECIFIED

LOS ANGELES RWQCB (REGION 4) - CASE #: 914061707

CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE	FILTER: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	7/30/1991

Activities Conducted to Date Based on GeoTracker T0603702447

Assessment last 5 years

Appears None

Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years



Review Conclusions T0603702447

Review indicates:

- Solvent release (is it a petroleum LUST?)
- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Regulatory lead information not complete in GT no local case worker assigned

Discussion:

- Any case information available?
- Potential Media Affected is "Other GW" → any significant risk?
- Assign local case worker
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility

J&S PRECISION AUTO (FMR ARAX STATION GAS STATION) (T0603740056)

110 S. Lincoln Blvd., Venice, CA 90291



Case Age: 19 years
Primary COC: Gasoline

RP Identified: Gevelkian, Steve (J&S Precision Auto) – Unclaimed in

GeoTracker

Potential Media Affected: Soil

Current land use: Commercial (West Side

Motor Sports)
Well Network:

N/A



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1991 and present
- No local regulatory case worker assigned
- No apparent RP involvement
- No reports or data in GeoTracker

NOTE: Data queried from GeoTracker and reviewed in October 2010

CLEANUP OVERSIGHT AGENCIES LOS ANGELES, CITY OF (LEAD) - CASE #: XS0000872 CASEWORKER: TBD - SUPERVISOR: NONE SPECIFIED LOS ANGELES RWQCB (REGION 4) CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FILTER:	Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	11/12/1991
LEAK ACTION	<u>Leak Discovery</u>	9/11/1991
LEAK ACTION	<u>Leak Began</u>	1/1/1965

Activities Conducted to Date Based on GeoTracker T0603740056

Assessment last 5 years

Appears None


Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years



Review Conclusions T0603740056

Review indicates:

- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Cleanup Status: Open Remediation as of 1/23/1992
- Site might have been redeveloped
- Regulatory lead information not complete in GT no local case worker information

Discussion:

- Any case information available?
- Has remediation been implemented, effectiveness?
- Assign a local case worker
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

LAFD – FIRE STATION 80 (T0603745944)

6911 W. World Wy., Los Angeles, CA 90045



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1990 and present
- Apparent lack of regulatory oversight and RP involvement
- No reports or data in GeoTracker
- RP is a government entity, funding issues?
- Site redeveloped?

NOTE: Data queried from GeoTracker and reviewed in October 2010

Case Age: 19 years

Primary COC: Other solvent or non-petroleum hydrocarbon

RP Identified: Bureau of Engineering, City of LA – Unclaimed in GeoTracker

Potential Media Affected: Soil Current land use: Parking garage

Well Network: N/A



CLEANUP OVERSIGHT AGENCIES
LOS ANGELES, CITY OF (LEAD) - CASE #: XS0000728
CASEWORKER: TERRENCE PALMER - SUPERVISOR: NONE SPECIFIED
LOS ANCELES DIVIOCE (DECION 4)

SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	5/23/1991
LEAK ACTION	Leak Discovery	2/11/1990
LEAK ACTION	<u>Leak Began</u>	1/1/1965

Activities Conducted to Date Based on GeoTracker T0603745944

Assessment last 5 years

Appears None

Remediation last 5 years


Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE T0603745944 as reported by regulatory agency



Review Conclusions T0603745944

Review indicates:

- Other solvent or non-petroleum hydrocarbon release (Federal UST case?)
- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Site currently a parking garage was site redeveloped?
- Cleanup Status: Open Verification Monitoring as of 12/3/2002

Discussion:

- Any case information available?
- What media monitoring is being verified, ongoing?
- Any significant risk and source at the site?
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

RENT-A-BIN (T0603740210)

9643 N. Cozycroft Ave., Chatsworth, CA 91311



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1991 and present
- Apparent lack of regulatory oversight and RP involvement
- No reports or data in GeoTracker

NOTE: Data gueried from GeoTracker and reviewed in October 2010

Case Age: 19 years
Primary COC: Diesel

RP Identified: Randall, Howard -

Unclaimed in GeoTracker

Potential Media Affected: Soil

Current land use: Commercial (Rent-A-Bin)

Well Network: N/A



CLEANUP OVERSIGHT AGENCIES
LOS ANGELES, CITY OF (LEAD) - CASE #: XS0000898
CASEWORKER: TERRENCE PALMER - SUPERVISOR: NONE SPECIFIED
LOS ANGELES RWQCB (REGION 4)
CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	7/10/1991
LEAK ACTION	Leak Discovery	6/27/1991
LEAK ACTION	<u>Leak Began</u>	1/1/1965

Activities Conducted to Date Based on GeoTracker T0603740210

Assessment last 5 years

Appears None


Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years



Review Conclusions T0603740210

Review indicates:

- Diesel fuel release
- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review

Discussion:

- Any case information available?
- Any significant risk and source at the site?
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

RESORT RENT A CAR (T0603790524)

6151 W 98th St., Los Angeles, CA 90045



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1991 and present
- No local regulatory case worker assigned
- No apparent RP involvement
- No reports or data in GeoTracker

NOTE: Data queried from GeoTracker and reviewed in October 2010

Case Age: 19 years
Primary COC: Diesel

RP Identified: Thrifty Rent-A-Car -

Unclaimed in GeoTracker

Potential Media Affected: Soil **Current land use:** Parking Lot

Well Network: N/A



CLEANUP OVERSIGHT AGENCIES

LOS ANGELES, CITY OF (LEAD)

CASEWORKER: TBD - SUPERVISOR: NONE SPECIFIED

LOS ANGELES RWQCB (REGION 4)

CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FILTER:	Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	<u>Leak Reported</u>	5/29/1991
LEAK ACTION	Leak Discovery	5/8/1991
LEAK ACTION	<u>Leak Began</u>	1/1/1965

Activities Conducted to Date Based on GeoTracker T0603790524

Assessment last 5 years

Appears None


Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years



Review Conclusions T0603790524

Review indicates:

- Diesel fuel release
- Regulatory Activities indicates no work has occurred
- Site Status History indicates Site Assessment in 1991
- No reports or data in GeoTracker to review
- Site currently appears to be a parking lot
- Regulatory lead information not complete in GT no local case # or worker

Discussion:

- Any case information available?
- Parking lot → any significant risk at site?
- Assign a local case worker
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

TUNE UP MASTERS SHOP #10 (T0603700781)

4421 Melrose Ave., Los Angeles, CA 90029



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1991 and present
- Apparent lack of regulatory oversight
- · No RP identified
- No reports or data in GeoTracker

NOTE: Data gueried from GeoTracker and reviewed in October 2010

Case Age: 19 years

Primary COC: Other Solvent or Non-Petroleum Hydrocarbon

RP Identified: BLANK – Unclaimed in GeoTracker

Potential Media Affected: Soil Current land use: Auto Service

(T A Auto Service)
Well Network: N/A



CLEANUP OVERSIGHT AGENCIES
LOS ANGELES, CITY OF (LEAD)
CASEWORKER: TERRENCE PALMER - SUPERVISOR: NONE SPECIFIED
LOS ANGELES RWOCB (REGION 4) - CASE # .900290189
CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYP	E FILTER: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	<u>Leak Reported</u>	11/15/1991

Activities Conducted to Date Based on GeoTracker T0603700781

Assessment last 5 years

Appears None

Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE T0603700781 as reported by regulatory agency TUNE UP MASTERS SHOP #10 (T0603700781) - (MAP) 4421 MELROSE AVE LOS ANGELES, CA 90029 LOS ANGELES COUNTY LUST CLEANUP SITE Sommy Cleanup Status History Regulatory Activities Environmental Data (ES) Site Mags / Decuments Community Involvem Regulatory Profile Regulatory Regulato

Review Conclusions T0603700781

Review indicates:

- Other solvent or non-petroleum hydrocarbon release (Federal UST site?)
- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Regulatory lead information not complete in GeoTracker no local case #

Discussion:

- Any case information available?
- Federal UST case?
- Any significant risk at site?
- Identify RP
- Next step → cleanup timeline or closure possibility ("soils only"?)

LIMOUSINE EXPRESS INC (T0603786262)

260 E. 6th St., Los Angeles, CA 90014



Case Age: 18 years
Primary COC: Diesel

RP Identified: El Paso La Limousine -

Unclaimed in GeoTracker

Potential Media Affected: Soil Current land use: Commercial (Los

Limousines)

Well Network: N/A

Possible Reasons Why This Case Is So Old

- Appears no activity between 1992 and present
- No local regulatory case worker assigned
- No apparent RP involvement
- No reports or data in GeoTracker

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES, CITY OF (LEAD) - CASE #: XS0001109

CASEWORKER: TBD - SUPERVISOR: NONE SPECIFIED

LOS ANGELES RWQCB (REGION 4)

CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FILTE	R: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	<u>Leak Reported</u>	4/1/1992
LEAK ACTION	Leak Discovery	1/27/1992
LEAK ACTION	<u>Leak Began</u>	1/1/1965

NOTE: Data gueried from GeoTracker and reviewed in October 2010

Activities Conducted to Date Based on GeoTracker T0603786262

Assessment last 5 years

Appears None

Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years



Review Conclusions T0603786262

Review indicates:

- Diesel fuel release
- Regulatory Activities indicates no work has occurred
- Cleanup Status History indicates: Site Assessment, Remediation and Verification Monitoring in 1992
- No reports or data in GeoTracker to review
- Regulatory lead information not complete in GT no local case worker information

Discussion:

- Any case information available?
- What media monitoring is being verified, ongoing?
- Assign a local case worker
- Any significant risk and source at site?
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

MISSION HILLS FORD (T0603790800)

11151 N Laurel Canyon Blvd. San Fernando, CA 91340



Case Age: 19 years

Primary COC: Waste Oil / Motor /

Hydraulic / Lubricating

RP Identified: Saunders, Julian -

Unclaimed in GeoTracker

Potential Media Affected: Soil **Current land use:** Multiple-tenant

complex (Canyon Plaza) Well Network: N/A



CLEANUP OVERSIGHT AGENCIES

LOS ANGELES, CITY OF (LEAD) - CASE #: XS0000851

CASEWORKER: TERRENCE PALMER - SUPERVISOR: NONE SPECIFIED

CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED		
ACTIVITIES REPORT	ACTIVITY TYPE FI	LTER: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	3/26/1992
LEAK ACTION	Leak Discovery	2/18/1992
LEAK ACTION	<u>Leak Began</u>	1/1/1965

Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1992 and present
- Apparent lack of regulatory oversight and RP involvement
- No reports or data in GeoTracker

NOTE: Data queried from GeoTracker and reviewed in October 2010

Activities Conducted to Date Based on GeoTracker T0603790800

<u>Assessment last 5 years</u>

Appears None


Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years



Review Conclusions T0603790800

Review indicates:

- Waste oil / motor / hydraulic / lubricating release
- Regulatory Activities indicates no work has occurred
- Cleanup Status History indicates: Site Assessment in 1992 and Remediation as of 7/17/1992
- No reports or data in GeoTracker to review

Discussion:

- Any case information available?
- Has remediation been implemented, effectiveness?
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

ROBERTSON BRANCH LIBRARY (T0603799502)

1719 S Robertson Blvd. Los Angeles, CA



Case Age: 19 years

Primary COC: Other Solvent or Non-

Petroleum Hydrocarbon

RP Identified: Robertson Branch Library -

Unclaimed in GeoTracker Potential Media Affected: Soil

Current land use: Library (Robertson

Well Network: N/A

Possible Reasons Why This Case Is So Old

- No activity between 1992 and present
- Apparent lack of regulatory oversight and RP involvement
- No reports or data in GeoTracker

NOTE: Data queried from GeoTracker and reviewed in October 2010

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES, CITY OF (LEAD) - CASE #: XS0001013

CASEWORKER: NEAL REITZELL - SUPERVISOR: NONE SPECIFIED

LOS ANGELES RWQCB (REGION 4)

CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FILT	TER: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	1/31/1992
LEAK ACTION	Leak Discovery	1/28/1992
LEAK ACTION	<u>Leak Began</u>	1/1/1965

Activities Conducted to Date Based on GeoTracker T0603799502

<u>Assessment last 5 years</u>

Appears None


Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years



Review Conclusions T0603799502

Review indicates:

- Other solvent or non-petroleum hydrocarbon release (Federal UST case?)
- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Site is currently a library

Discussion:

- Any case information available?
- Age of case is 18-years and a library → any significant risk or source at site?
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

SOUTH BAY CORP (T0603700073)

1411 190th St., W. Rosewood, CA 90248



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1992 and present
- · Apparent lack of regulatory oversight
- · No RP identified
- No reports or data in GeoTracker

NOTE: Data queried from GeoTracker and reviewed in October 2010

Case Age: 19 years
Primary COC: Diesel
RP Identified: "BLANK" –
Unclaimed in GeoTracker
Potential Media Affected: Soil

Current land use: Mixed commercial

Well Network: N/A



CLEANUP OVERSIGHT AGENCIES
LOS ANGELES, CITY OF (LEAD) - CASE #: 041592-04
LOS ANGELES COUNTY
CASEWORKER: JOHN AWUJO - SUPERVISOR: MANUEL R REGALADO
LOS ANGELES RWQCB (REGION 4) - CASE #: 041592-04
CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE	FILTER: Show All Activities
ACTION TYPE	<u>ACTION</u>	ACTION DATE
LEAK ACTION	Leak Reported	1/17/1992
LEAK ACTION	Leak Discovery	1/15/1992

Activities Conducted to Date Based on GeoTracker T0603700073

Assessment last 5 years

Appears None

Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE T0603700073 as reported by regulatory agency



Review Conclusions T0603700073

Review indicates:

- Diesel fuel release
- No reports or data in GeoTracker to review
- No RP identified
- Regulatory Activities indicates no work has occurred

Discussion:

- Any case information available?
- Any significant risk at the site?
- Identify RP
- Next step → cleanup timeline or closure possibility ("soils only"?)

BUILDERS SHEET METAL INC (T0603759024)

7640 N. Gloria Ave., Van Nuys, CA 91406



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1992 and present
- Apparent lack of regulatory oversight and RP involvement
- No reports or data in GeoTracker

NOTE: Data queried from GeoTracker and reviewed in October 2010

Case Age: 18 years
Primary COC: Lead

RP Identified: Builders Sheet Metal -

Unclaimed in GeoTracker

Potential Media Affected: Soil

Current land use: Industrial (Aaronson

Manufacturing)
Well Network: N/A



CLEANUP OVERSIGHT AGENCIES
LOS ANGELES, CITY OF (LEAD) - CASE #: XS0000525
CASEWORKER: NEAL REITZELL - SUPERVISOR: NONE SPECIFIED
LOS ANGELES RWQCB (REGION 4)
CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE F	ILTER: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	8/24/1992
LEAK ACTION	Leak Discovery	7/30/1992
LEAK ACTION	Leak Began	1/1/1965

Activities Conducted to Date Based on GeoTracker T0603759024

Assessment last 5 years

Appears None


Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years



Review Conclusions T0603759024

Review indicates:


- Lead contamination in soil
- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Cleanup Status History indicates: Site Assessment in 1992 and Verification Monitoring as of 10/12/1992

Discussion:

- Any case information available?
- What media monitoring is being verified, ongoing?
- Any significant risk and source at site?
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

CALIFORNIA STATE UNIVERSITY FACILITY (T0603769587)

5151 E. State University Dr., Los Angeles, CA 90032



Primary COC: Diesel

Case Age: 18 years

RP Identified: California State University

LA - Unclaimed in GeoTracker Potential Media Affected: Soil

Current land use: State Government (California State University, Los Angeles)

Well Network: N/A



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1992 and present
- No local regulatory case worker assigned
- No apparent RP involvement
- No reports or data in GeoTracker
- Site is a college (government entity)

NOTE: Data queried from GeoTracker and reviewed in October 2010

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES, CITY OF (LEAD) - CASE #: XS0000943 CASEWORKER: TBD - SUPERVISOR: NONE SPECIFIED

LOS ANGELES RWQCB (REGION 4)

CASEWORKER: YUE RONG -

ACTIVITIES REPORT	ACTIVITY TYPE I	FILTER: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	9/24/1992
LEAK ACTION	Leak Discovery	8/12/1992
LEAK ACTION	<u>Leak Began</u>	1/1/1965

Activities Conducted to Date Based on GeoTracker T0603769587

<u>Assessment last 5 years</u>

Appears None


Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years



Review Conclusions T0603769587

Review indicates:

- Diesel fuel release
- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Cleanup Status History indicates: Site Assessment in 2002 and Verification Monitoring as of 10/1/2002
- Site is currently a college campus
- Regulatory lead information not complete in GT no local case worker information

Discussion:

- Any case information available?
- What media monitoring is being verified, ongoing?
- Assign a local case worker
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

DARLING-DELAWARE (T0603796838)

2626 E. 25th St., Los Angeles, CA 90058



Case Age: 18 years

Primary COC: Stode

Primary COC: Stoddard Solvent / Mineral

Sprits / Distillates

RP Identified: Darling-Delaware Co. Inc. -

Unclaimed in GeoTracker

Potential Media Affected: Soil

Current land use: Industrial (Darling

International Inc.)
Well Network: N/A



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1992 and present
- No local regulatory case worker assigned
- No apparent RP involvement
- No reports or data in GeoTracker

NOTE: Data queried from GeoTracker and reviewed in October 2010

CLEANUP OVERSIGHT AGENCIES LOS ANGELES, CITY OF (LEAD) - CASE #: XS0000820 CASEWORKER: TBD - SUPERVISOR: NONE SPECIFIED LOS ANGELES RWQCB (REGION 4) CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FILTER:	Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	8/20/1992
LEAK ACTION	Leak Discovery	8/18/1992
LEAK ACTION	<u>Leak Began</u>	1/1/1965

Activities Conducted to Date Based on GeoTracker T0603796838

Assessment last 5 years

Appears None


Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years



Review Conclusions T0603796838

Review indicates:

- Stoddard solvent / mineral spirits/ distillates release (Federal UST case?)
- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Cleanup Status History indicates: Site Assessment in 1992 and Verification Monitoring as of 2/26/1993
- Regulatory lead information not complete in GT no local case work information

Discussion:

- Any case information available?
- What monitored media is being verified, ongoing?
- Assign a local case worker
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

DEPT OF TRANSPORTATION (T0603700457)

411 Vermont Ave., N. Los Angeles, CA 90004



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1992 and present
- Apparent lack of regulatory oversight
- · No RP identified
- No reports or data in GeoTracker
- Government property? Funding issues?

NOTE: Data queried from GeoTracker and reviewed in October 2010

Case Age: 18 years
Primary COC: Diesel

RP Identified: "Active Leak Testing" -

Unclaimed in GeoTracker
Potential Media Affected: Soil
Current land use: Government (Los
Angeles Department of Transportation)

Well Network: N/A



CLEANUD OVERSIGHT ACENCIES
CLEANUP OVERSIGHT AGENCIES
LOS ANGELES, CITY OF (LEAD)
· · · · · · · · · · · · · · · · · · ·
CASEWORKER: ELOY LUNA - SUPERVISOR: NONE SPECIFIED
LOS ANGELES RWQCB (REGION 4) - CASE #: 900040361
CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED
CASEVUKKEK: YUE KUNG - SUPEKVISUK: NUNE SPEUIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FIL	TER: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Discovery	5/7/1992
LEAK ACTION	Leak Reported	5/7/1992
LEAK ACTION	<u>Leak Stopped</u>	5/7/1992

Activities Conducted to Date Based on GeoTracker T0603700457

Assessment last 5 years

Appears None


Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years



Review Conclusions T0603700457

Review indicates:

- Diesel release
- No reports or data in GeoTracker to review
- Regulatory Activities indicates no work has occurred
- Regulatory lead information not complete in GT no local case #
- Error in RP listing in GeoTracker: Primary RP is "Active Leak Testing"

Discussion:

- Any case information available?
- Identify RP
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

GAS S/S (T0603702450)

14106 Burbank Blvd., Van Nuys, CA 91406



Primary COC: Gasoline RP Identified: "BLANK" -**Unclaimed in GeoTracker** Potential Media Affected: Soil

Current land use: Gas Station (ARCO)

Well Network: N/A

Case Age: 18 years



CLEANUP OVERSIGHT AGENCIES

LOS ANGELES, CITY OF (LEAD)

CASEWORKER: NEAL REITZELL - SUPERVISOR: NONE SPECIFIED

LOS ANGELES RWQCB (REGION 4) - CASE #: 914061734

CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FILTER	Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	5/16/1992
LEAK ACTION	<u>Leak Discovery</u>	5/15/1992

Possible Reasons Why This Case Is So Old

- Appears no activity between 1992 and present
- Apparent lack of regulatory oversight
- · No RP identified
- No reports or data in GeoTracker

NOTE: Data queried from GeoTracker and reviewed in October 2010

Activities Conducted to Date Based on GeoTracker T0603702450

Assessment last 5 years

Appears None

Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years



Review Conclusions T0603702450

Review indicates:


- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Cleanup Status History indicates Site Assessment in 1992 and 1998
- Site is currently an active gas station
- No RP identified, soils only case

Discussion:

- Any case information available?
- Site is a gas station → any significant risk at site?
- Identify RP
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only" ?)

LAFD - FIRE STATION 95 (T0603794280)

10010 S International Rd. Los Angeles, CA 90045



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1992 and present
- Apparent lack of regulatory oversight and RP involvement
- No reports or data in GeoTracker
- RP is a government entity, funding issues?

NOTE: Data queried from GeoTracker and reviewed in October 2010

Case Age: 18 years
Primary COC: Gasoline

RP Identified: City of LA Dep. of Gen. Serv. - Unclaimed in GeoTracker Potential Media Affected: Soil

Current land use: Utilities (Los Angeles

Fire Department)
Well Network: N/A



CLEANUP OVERSIGHT AGENCIES
LOS ANGELES, CITY OF (LEAD) - CASE #: XS0000857

CASEWORKER: NEAL REITZELL - SUPERVISOR: NONE SPECIFIED
LOS ANGELES RWQCB (REGION 4)

CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FILTER:	Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	10/2/1992
LEAK ACTION	Leak Discovery	7/14/1992
LEAK ACTION	<u>Leak Began</u>	1/1/1965

Activities Conducted to Date Based on GeoTracker T0603794280

Assessment last 5 years

Appears None


Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years



Review Conclusions T0603794280

Review indicates:


- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Cleanup Status History indicates: Site Assessment in 1994 and Verification Monitoring as of 9/15/1994

Discussion:

- Any case information available?
- What monitored media is being verified, ongoing?
- Any significant risk at site?
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

RAY'S MARKET (T0603721107)

9727 S Figueroa St., Los Angeles, CA 90012



Case Age: 18 years Primary COC: Gasoline RP Identified: Ho Suk Han -**Unclaimed in GeoTracker** Potential Media Affected: Soil

Current land use: Commercial (Ray

Market)

Well Network: N/A



LOS ANGELES, CITY OF (LEAD) - CASE #: XS0000827

CASEWORKER: TBD - SUPERVISOR: NONE SPECIFIED

LOS ANGELES RWQCB (REGION 4)

CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FILTER:	Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	<u>Leak Reported</u>	10/21/1992
LEAK ACTION	Leak Discovery	9/10/1992
LEAK ACTION	<u>Leak Began</u>	1/1/1965

Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1992 and present
- No local regulatory case worker assigned
- No apparent RP involvement
- No reports or data in GeoTracker

NOTE: Data queried from GeoTracker and reviewed in October 2010

Activities Conducted to Date Based on GeoTracker T0603721107

<u>Assessment last 5 years</u>

Appears None


Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years



Review Conclusions T0603721107

Review indicates:

- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Cleanup Status History indicates: Site Assessment in 1992 and 1993, and Remediation as of 9/16/93
- Regulatory lead information not complete in GT no local case worker information

Discussion:

- Any case information available?
- Has remediation been implemented, effectiveness?
- Assign a local case worker
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

ROTOCRAFT SUPPORT INC (T0603755343)

16425 W. Hart St., Van Nuys, CA 91406



Case Age: 18 years

Primary COC: Waste Oil / Motor /

Hydraulic / Lubricating

RP Identified: Skytrails Aviating -


Unclaimed in GeoTracker

Potential Media Affected: Soil

Current land use: Commercial (Group 3

Aviation)

Well Network: N/A



- Appears no cleanup activity between 1992 and present
- No local regulatory case worker assigned
- No apparent RP involvement
- No reports or data in GeoTracker

NOTE: Data gueried from GeoTracker and reviewed in October 2010



CLEANUP OVERSIGHT AGENCIES

LOS ANGELES, CITY OF (LEAD) - CASE #: XS0001010

CASEWORKER: TED - SUPERVISOR: NONE SPECIFIED

LOS ANGELES RWQCB (REGION 4)

CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FILTE	R: Show All Activities
ACTION TYPE	<u>ACTION</u>	ACTION DATE
LEAK ACTION	Leak Reported	10/8/1992
LEAK ACTION	Leak Discovery	9/24/1992
LEAK ACTION	<u>Leak Began</u>	1/1/1965

Activities Conducted to Date Based on GeoTracker T0603755343

Assessment last 5 years

Appears None


Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years



Review Conclusions T0603755343

Review indicates:

- Waste / motor / hydraulic / lubricating oil release
- Regulatory Activities indicates no work has occurred
- Cleanup Status History indicates Site Assessment in 1994
- No reports or data in GeoTracker to review
- Regulatory lead information not complete in GT no local case worker information

Discussion:

- Any case information available?
- Any significant risk and source at site?
- Assign a local case worker
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

CHEVRON #9-2766 (T0603702409)

5600 Sepulveda Blvd. Van Nuys, CA 91401



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1993 and present
- Apparent lack of regulatory oversight and RP involvement
- No reports or data in GeoTracker

NOTE: Data queried from GeoTracker and reviewed in October 2010

Case Age: 18 years Primary COC: Gasoline

RP Identified: Chevron USA -**Unclaimed in GeoTracker**

Potential Media Affected: Soil **Current land use:** Gas Station

(Chevron)

Well Network: N/A



CLEANUP OVERSIGHT AGENCIES

LOS ANGELES, CITY OF (LEAD)

CASEWORKER: ELOY LUNA - SUPERVISOR: NONE SPECIFIED LOS ANGELES RWQCB (REGION 4) - CASE #: 914010807 CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPOR	T ACTIVITY TYPE F	FILTER: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	4/9/1993
LEAK ACTION	Leak Discovery	4/8/1993
LEAK ACTION	Leak Stopped	4/8/1993

Activities Conducted to Date Based on GeoTracker T0603702409

<u>Assessment last 5 years</u>

Appears None

Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years



Review Conclusions T0603702409

Review indicates:


- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Site is currently an active gas station
- Soil only case, is it closeable?

Discussion:

- Any case information available?
- Any significant risk at site?
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only" ?)

DEPT. OF GEN SERVICE OF STATE (T0603766799)

1525 S. Broadway, Los Angeles, CA 90037



Case Age: 18 years
Primary COC: Diesel

RP Identified: State of California -

Unclaimed in GeoTracker

Potential Media Affected: Soil

Current land use: Industrial (Neman

Brothers)

Well Network: N/A



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1993 and present
- No local regulatory case worker assigned
- No apparent RP involvement
- No reports or data in GeoTracker
- RP is a government entity, funding issues?

NOTE: Data queried from GeoTracker and reviewed in October 2010

CLEANUP OVERSIGHT AGENCIES
LOS ANGELES, CITY OF (LEAD) - CASE #: XS0000306
CASEWORKER: TBD - SUPERVISOR: NONE SPECIFIED
LOS ANGELES RWQCB (REGION 4)
CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FILTER:	Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	3/22/1993
LEAK ACTION	Leak Discovery	3/10/1993
LEAK ACTION	<u>Leak Began</u>	1/1/1965

Activities Conducted to Date Based on GeoTracker T0603766799

Assessment last 5 years

Appears None


Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years



Review Conclusions T0603766799

Review indicates:

- Diesel fuel release
- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Cleanup Status History indicates: Site Assessment in 1993 and Verification Monitoring as of 11/18/1993
- Regulatory lead information not complete in GT no local case worker information

Discussion:

- Any case information available?
- What media monitoring is being verified, ongoing?
- Assign a local case worker
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

DEXOL INDUSTRIES (T0603730842)

1450 W. 228th St., Torrance, CA 90501



Case Age: 18 years

Primary COC: Heating Oil / Fuel Oil -

Not a Federal LUST Case?

RP Identified: Dexol Industries, Inc. -

Unclaimed in GeoTracker
Potential Media Affected: Soil
Current land use: Commercial?

Well Network: N/A



CLEANUP OVERSIGHT AGENCIES LOS ANGELES, CITY OF (LEAD) CASEWORKER: TERRENCE PALMER - SUPERVISOR: NONE SPECIFIED

LOS ANGELES RWQCB (REGION 4)

CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE	FILTER: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	12/30/1992
LEAK ACTION	Leak Discovery	10/14/1992
LEAK ACTION	<u>Leak Began</u>	1/1/1965

Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1992 and present
- Apparent lack of regulatory oversight and RP involvement
- No reports or data in GeoTracker
- A non-Federal LUST case? (heating oil)

NOTE: Data gueried from GeoTracker and reviewed in October 2010

Activities Conducted to Date Based on GeoTracker T0603730842

Assessment last 5 years

Appears None


Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years



Review Conclusions T0603730842

Review indicates:

- Heating oil / Fuel Oil NOT FEDERAL LUST CASE?
- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Cleanup Status: Open Verification Monitoring as of 10/19/1993

Discussion:

- Any case information available?
- What media monitoring is being verified, ongoing?
- Any significant risk and source at the site?
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

LAPD HOLLENBECK DIVISION (T0603737703)

2111 E. 1st St., Los Angeles, CA 90033



Case Age: 18 years
Primary COC: Gasoline

RP Identified: City of LA, General Services – Unclaimed in GeoTracker Potential Media Affected: Soil Current land use: Commercial (Los

Angeles Police Department)

Well Network: N/A



Possible Reasons Why This Case Is So Old

- No activity between 1990 and present
- No local regulatory case worker assigned
- No apparent RP involvement
- No reports or data in GeoTracker
- RP is government entity, funding issues?

NOTE: Data queried from GeoTracker and reviewed in October 2010

CLEANUP OVERSIGHT AGENCIES LOS ANGELES, CITY OF (LEAD) CASEWORKER: TBD SUPERVISOR: NONE SPECIFIED LOS ANGELES RWQCB (REGION 4) CASEWORKER: YUE RONG SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE	FILTER: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	3/30/1993
LEAK ACTION	Leak Discovery	5/2/1990
LEAK ACTION	<u>Leak Began</u>	1/1/1965

Activities Conducted to Date Based on GeoTracker T0603737703

Assessment last 5 years

Appears None

Remediation last 5 years


Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

as reported by regulatory agency



Review Conclusions T0603737703

Review indicates:

- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Cleanup Status History indicates Site Assessment in 1993 (no additional information available)
- Regulatory lead information not complete in GT no local case # or worker information

Discussion:

- Any case information available?
- Any significant risk at site?
- Assign a local case worker
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

PIPER TECHNICAL CENTER (T0603700534)

555 Ramirez St., Los Angeles, CA 9012



Case Age: 18 years

Primary COC: Other Solvent or Non-Petroleum Hydrocarbon RP Identified: City of Los Angeles –

Unclaimed in GeoTracker

Potential Media Affected: Soil Current land use: Commercial (Erwin Piper Technical Center)

Well Network: N/A



CLEANUP OVERSIGHT AGENCIES

LOS ANGELES, CITY OF (LEAD)

CASEWORKER: TBD - SUPERVISOR: NONE SPECIFIED

LOS ANGELES RWQCB (REGION 4) - CASE #: 900120398

CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

 ACTIVITIES REPORT
 ACTIVITY TYPE FILTER:
 Show All Activities

 ACTION TYPE
 ACTION
 ACTION DATE

 LEAK ACTION
 Leak Discovery
 3/25/1993

 LEAK ACTION
 Leak Reported
 3/25/1993

 LEAK ACTION
 Leak Stopped
 3/25/1993

Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1993 and present
- No local regulatory case worker assigned
- No apparent RP involvement
- No reports or data in GeoTracker
- RP is Government entity, funding issues?

NOTE: Data queried from GeoTracker and reviewed in October 2010

Activities Conducted to Date Based on GeoTracker T0603700534

Assessment last 5 years

Appears None

Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE T0603700534 as reported by regulatory agency PIPER TECHNICAL CENTER (T0603700534) - (MAP) 555 RAMREZ ST LOS ANSELES, CA 9012 LOS ANSELES, CA 9012 LOS ANSELES COUNTY LUST CLEANUP SITE Segulatory Regulatory Activities (Invironmental Data (ES)) Site Mays / Documents (Community Involvemental CASEWORRE: INC. ROSSWORRE: INC. RO

Review Conclusions T0603700534

Review indicates:

- Other solvent or non-petroleum hydrocarbon release (Federal UST case?)
- No reports or data in GeoTracker to review
- Regulatory Activities indicates no work has occurred
- RP is government entity → City of Los Angeles
- Regulatory lead information not complete in GT no local case worker or local case #

Discussion:

- Any case information available?
- Assign local case worker
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

DRIZ KNITTING MILLS (T0603746785)

3000 S. Central Ave., Los Angeles, CA



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1993 and present
- Apparent lack of regulatory oversight and RP involvement
- No reports or data in GeoTracker

NOTE: Data queried from GeoTracker and reviewed in October 2010

Case Age: 17 years

Primary COC: Fuel oxygenates **RP Identified:** Bank of America –

Unclaimed in GeoTracker

Potential Media Affected: Soil

Current land use: Industrial (Cotton L.A.)

Well Network: N/A



CLEANUP OVERSIGHT AGENCIES

LOS ANGELES, CITY OF (LEAD) - CASE #: XS0000030

CASEWORKER: MARCUS LOOK - SUPERVISOR: NONE SPECIFIED

LOS ANGELES RWQCB (REGION 4)

CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE	FILTER: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	11/17/1993
LEAK ACTION	Leak Discovery	9/2/1993
LEAK ACTION	Leak Began	1/1/1965

Activities Conducted to Date Based on GeoTracker T0603746785

Assessment last 5 years

Appears None

Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE T0603746785 as reported by regulatory agency



Review Conclusions T0603746785

Review indicates:


- Fuel oxygenate release (Federal UST case?)
- Regulatory Activities indicates no work has occurred
- Cleanup Status History indicates Site Assessment in 1995
- No reports or data in GeoTracker to review

Discussion:

- Any case information available?
- Any MtBE present? → Significant of risk at site?
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

MATSON TERMINAL (T0603791363)

950 New Dock St., Los Angeles, CA



Case Age: 17 years
Primary COC: Diesel

RP Identified: LA Harbor Dept. Potential Media Affected: Soil

Current land use: Unknown (Terminal

Island)

Well Network: N/A



Possible Reasons Why This Case Is So Old

- No activity between 1993 and present
- No local regulatory case worker assigned
- No apparent RP involvement
- No reports or data in GeoTracker
- RP is a government entity, funding issues?

NOTE: Data gueried from GeoTracker and reviewed in October 2010

CLEANUP OVERSIGHT AGENCIES LOS ANGELES, CITY OF (LEAD) - CASE #: XS0000824 CASEWORKER: TED - SUPERVISOR: NONE SPECIFIED LOS ANGELES RWQCB (REGION 4) CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE	FILTER: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	9/28/1993
LEAK ACTION	Leak Discovery	9/13/1993
LEAK ACTION	<u>Leak Began</u>	1/1/1965

Activities Conducted to Date Based on GeoTracker T0603791363

Assessment last 5 years

Appears None


Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years



Review Conclusions T0603791363

Review indicates:

- Diesel fuel release
- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Regulatory lead information not complete in GT no local case worker

Discussion:

- Any case information available?
- Current land use, age of case and diesel contamination → any significant risk at site?
- Assign a local case worker
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

MOBIL #11-GQG (T0603701315)

15281 Sunset Blvd. Pacific Palisades, CA 90272



Case Age: 17 years **Primary COC:** Gasoline RP Identified: "Customer"? Potential Media Affected: Soil **Current land use:** Gasoline Station

Well Network: N/A

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES, CITY OF (LEAD)

CASEWORKER: eloy luna - SUPERVISOR: NONE SPECIFIED

LOS ANGELES RWQCB (REGION 4) - CASE #: 902720098

CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

Cleanup Status History	
<u>DATE</u>	<u>STATUS</u>
5/10/2005	Open - Site Assessment
9/24/1993	Open - Site Assessment
9/23/1993	Open - Reopen Case
9/21/1989	Open - Case Begin Date
9/21/1989	Completed - Case Closed

ACTIVITIES REPORT	ACTIVITY TYPE F	ILTER: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Discovery	9/24/1993
LEAK ACTION	Leak Reported	9/24/1993

Possible Reasons Why This Case Is So Old

- Appears limited activity between 1993 and present
- Apparent lack of regulatory oversight
- Unknown RP? (Case claimed in GT)
- Reopened case

NOTE: Data queried from GeoTracker and reviewed in October 2010

Activities Conducted to Date Based on GeoTracker T0603701315

<u>Assessment last 5 years</u>

- Attempt to obtain historical soil sampling report; no reports to review
- 2005 GWM report indicates a site assessment workplan will be submitted; no report to review

Assessment older than 5 years


Appears None

Remediation last 5 years

Appears None

Remediation older than 5 years

as reported by regulatory agency



Review Conclusions T0603701315

Review indicates:

- Regulatory Activities indicates no work has occurred
- Only 2 Status Reports uploaded to GeoTracker
- Status report indicates a workplan was to be submitted in 2005
- Cleanup Status History indicates "Site Assessment" in 1993 and 2005
- Site is currently an active gas station
- RP not identified (but case is claimed in GeoTracker)
- Case was closed in 1989 and reopened in 1993

Discussion:

- Any case information available?
- Reason to reopen case in 1993 → any significant risk?
- Identify RP
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

VERIZON WIRELESS (T0603729309)

21000 W. Plummer St., Chatsworth, CA 91311



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1993 and present
- Apparent lack of regulatory oversight and RP involvement
- No reports or data in GeoTracker

NOTE: Data queried from GeoTracker and reviewed in October 2010

Case Age: 17 years Primary COC: Lead

RP Identified: Blaney, J., Neal (Rancho San Antonio) – Unclaimed in GeoTracker

Potential Media Affected: Soil

Current land use: Other (Rancho San

Antonio)

Well Network: N/A



CLEANUP OVERSIGHT AGENCIES

LOS ANGELES, CITY OF (LEAD) - CASE #: XS0000915

CASEWORKER: TERRENCE PALMER - SUPERVISOR: NONE SPECIFIED

LOS ANGELES RWQCB (REGION 4)

CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE F	ILTER: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	10/18/1993
LEAK ACTION	Leak Discovery	8/24/1993
LEAK ACTION	<u>Leak Began</u>	1/1/1965

Activities Conducted to Date Based on GeoTracker T0603729309

Assessment last 5 years

Appears None

Remediation last 5 years


Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE T0603729309 as reported by regulatory agency



Review Conclusions T0603729309

Review indicates:

- Lead release (non-liquid?) Federal LUST case?
- Regulatory Activities indicates no work has occurred
- Cleanup Status History indicates: Site Assessment in 1992, Remediation in 1994 and Verification Monitoring as of 4/29/1994
- No reports or data in GeoTracker to review

Discussion:

- Any case information available?
- What media monitoring is being verified, ongoing?
- Actual source of lead (naturally occurring/construction fill?) → any significant risk and source at site?
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

TEXACO – KEEBLE, ROBERT (T0603786190)

8579 San Fernando Rd., Los Angeles, CA 90031



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1994 and present
- No local regulatory case worker assigned
- No apparent RP involvement
- No reports or data in GeoTracker
- · Site is a gas station

NOTE: Data queried from GeoTracker and reviewed in October 2010

Case Age: 17 years
Primary COC: Gasoline

RP Identified: Zimm Fuel & Tire Shop -

Unclaimed in GeoTracker

Potential Media Affected: Soil

Current land use: Gas Station (Timm

Fuel)

Well Network: N/A



CLEANUP OVERSIGHT AGENCIES LOS ANGELES, CITY OF (LEAD) - CASE #: XS0000993 CASEWORKER: TED - SUPERVISOR: NONE SPECIFIED LOS ANGELES RWQCB (REGION 4) CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE	FILTER: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	2/15/1994
LEAK ACTION	Leak Discovery	2/10/1994
LEAK ACTION	Look Rogan	1/1/1065

Activities Conducted to Date Based on GeoTracker T0603786190

Assessment last 5 years

Appears None

Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE T0603786190 as reported by regulatory agency TEXACO - KEEBLE, ROBERT (T0603786190) - (MAP) By 19 SAN H-ERNANDO RD LOS ANGELES CO 30031 LOS ANGELES CONTY LUST OLEANUP SITE Summary Cleanup Status History Regulatory Activitie Environmental Data (SS) Site Maps / Documents Community Involvement CLEANUP STATUS - community Community Involvement CRESCULTE POTENTIAL MEDIA AFFECTED SOIL Site History No site history available

Review Conclusions T0603786190

Review indicates:

- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Cleanup Status: Open Remediation as of 5/26/1994
- Site is currently an active gas station
- Regulatory lead information not complete in GT no local case worker information

Discussion:

- Any case information available?
- Has remediation been implemented, effectiveness?
- Assign a local case worker
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

TIERNO'S GENERAL FABRICATION (T0603743780)

1769 N. Glendale Blvd., Los Angeles, CA 90026



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1993 and present
- No local regulatory case worker assigned
- No apparent RP involvement
- No reports or data in GeoTracker

NOTE: Data gueried from GeoTracker and reviewed in October 2010

Case Age: 17 years Primary COC: Gasoline

RP Identified: Tierno, Nicholas (Tierno General Fabrication) - Unclaimed in

GeoTracker

Potential Media Affected: Soil

Current land use: Auto Service (T.N.T

Auto Parts)

Well Network: N/A



CLEANUP OVERSIGHT AGENCIES

LOS ANGELES, CITY OF (LEAD) - CASE #: XS0001092 CASEWORKER: TBD - SUPERVISOR: NONE SPECIFIED LOS ANGELES RWQCB (REGION 4) CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

7		
ACTIVITIES REPORT	ACTIVITY TYPE FILTER:	Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	<u>Leak Reported</u>	12/3/1993
LEAK ACTION	<u>Leak Discovery</u>	11/9/1993
LEAK ACTION	<u>Leak Began</u>	1/1/1965

Activities Conducted to Date Based on GeoTracker T0603743780

<u>Assessment last 5 years</u>

Appears None


Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years



Review Conclusions T0603743780

Review indicates:

- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Regulatory lead information not complete in GT no local case worker information
- Cleanup Status History indicates Site Assessment in 1994

Discussion:

- Any case information available?
- Any significant risk and source at site?
- Assign a local case worker
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

F & S Auto Care (T0603739581)

4155 W. Washington Blvd., Los Angeles, CA 90019



Case Age: 16 years **Primary COC:** Gasoline

RP Identified: California Target Enterprises,

Inc. - Unclaimed in GeoTracker Potential Media Affected: Soil

Current land use: Auto Service (Miju Motor)

Well Network: N/A



CLEANUP OVERSIGHT AGENCIES

LOS ANGELES, CITY OF (LEAD) - CASE #: XS0000986 CASEWORKER: TERRENCE PALMER - SUPERVISOR: NONE SPECIFIED LOS ANGELES RWQCB (REGION 4) CASEWORKER: YUE RONG -SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT ACTIVITY TYPE FILTER: Show All Activities ACTION TYPE **ACTION** ACTION DATE LEAK ACTION Leak Reported 6/8/1994 LEAK ACTION Leak Discovery 4/15/1994 LEAK ACTION Leak Began 1/1/1965

Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1994 and present
- Apparent lack of regulatory oversight and RP involvement
- No reports or data in GeoTracker

NOTE: Data queried from GeoTracker and reviewed in October 2010

Activities Conducted to Date Based on GeoTracker T0603739581

<u>Assessment last 5 years</u>

Appears None

Remediation last 5 years


Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

as reported by regulatory agency



Review Conclusions T0603739581

Review indicates:

- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Site currently appears to be an auto service center

Discussion:

- Any case information available?
- Any significant risk and source at the site?
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

NORMANDIE PLAZA (T0603755288)

1285 W. 190th St., Los Angeles, CA



Case Age: 16 years
Primary COC: Benzene

RP Identified: Chevron USA Products

Co. – Unclaimed in GeoTracker
Potential Media Affected: Soil
Current land use: Auto Service (BM

Mercedes BMW Volvo Jaguar Audi VW

Service Specialist)
Well Network: N/A



CLEANUP OVERSIGHT AGENCIES LOS ANGELES, CITY OF (LEAD) - CASE #: XS0001074 CASEWORKER: TERRENCE PALMER - SUPERVISOR: NONE SPECIFIED LOS ANGELES RWQCB (REGION 4) CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE I	FILTER: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	10/5/1994
LEAK ACTION	Leak Discovery	7/1/1989
LEAK ACTION	Leak Began	1/1/1965

Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1989 and present
- Apparent lack of regulatory oversight and RP involvement
- No reports or data in GeoTracker
- Site redeveloped?

NOTE: Data queried from GeoTracker and reviewed in October 2010

Activities Conducted to Date Based on GeoTracker T0603755288

Assessment last 5 years

Appears None

Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

as reported by regulatory agency



Review Conclusions T0603755288

Review indicates:

- Benzene release
- Regulatory Activities indicates no work has occurred
- Cleanup Status History indicates Site Assessment in 1994
- No reports or data in GeoTracker to review

Discussion:

- Any case information available?
- Current site use and benzene release → any significant risk and source at site?
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

NORRIS CANCER HOSPITAL (T0603700853)

1441 Eastlake Ave. Boyle Heights, CA 90033



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1994 and present
- No local regulatory case worker assigned
- No apparent RP involvement
- No reports or data in GeoTracker

NOTE: Data gueried from GeoTracker and reviewed in October 2010

Case Age: 16 years Primary COC: Diesel

RP Identified: University of Southern CA

Unclaimed in GeoTrackerPotential Media Affected: Soil

Current land use: Hospital (USC - Norris

Cancer Hospital)
Well Network: N/A



CLEANUP OVERSIGHT AGENCIES
LOS ANGELES, CITY OF (LEAD)
CASEWORKER: TBD - SUPERVISOR: NONE SPECIFIED
LOS ANGELES RWQCB (REGION 4) - CASE #: 900330343

ACTIVITIES REPORT	ACTIVITY TYPE FILTER:	Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	7/5/1994
LEAK ACTION	<u>Leak Discovery</u>	6/2/1994
LEAK ACTION	Leak Stopped	6/2/1994

Activities Conducted to Date Based on GeoTracker T0603700853

Assessment last 5 years

Appears None

Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE T0603700853 as reported by regulatory agency NORRIS CANCER HOSPITAL (T0603700853) - (MAP) 1441 EASTLAKE AVE BOYLE HEIGHTS (AS 90033 LOS ANGELES ROOG REGION 1- CASE # MO330045 LOS ANGELES COUNTY LUST CLEANUP STRE Summary Cleanup Status listery Regulatory Activities Environmental Data (TS) Site Rigay / Documents Community Involvement CLEANUP STATUS OPEN - SITE AS SESSIMENT AS OF 9114/1994 POTENTIAL CONTAMINANTS OF CONCERN DIESEL FILE LOCATION Site History No site history available

Review Conclusions T0603700853

Review indicates:

- Diesel fuel release
- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Site is currently an active Hospital
- Regulatory lead information not complete in GeoTracker no case worker or local case #

Discussion:

- Any case information available?
- Assign local case worker
- Site is an active hospital site → any significant risk at site?
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only" ?)

WASHINGTON MUTUAL BANK (T0603782010)

9401 N. Corbin Ave., Northridge, CA 91324



Case Age: 16 years
Primary COC: Diesel

RP Identified: Great Western Bank -

Unclaimed in GeoTracker

Potential Media Affected: Soil Current land use: Business Park

Well Network: N/A



CLEANUP OVERSIGHT AGENCIES

LOS ANGELES, CITY OF (LEAD) - CASE #: XS0001082

CASEWORKER: TERRENCE PALMER - SUPERVISOR: NONE SPECIFIED

LOS ANGELES RWQCB (REGION 4)

CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FIL	TER: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	6/20/1994
LEAK ACTION	Leak Discovery	5/25/1994
LEAK ACTION	Leak Began	1/1/1965

Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1994 and present
- Apparent lack of regulatory oversight and RP involvement
- No reports or data in GeoTracker

NOTE: Data queried from GeoTracker and reviewed in October 2010

Activities Conducted to Date Based on GeoTracker T0603782010

Assessment last 5 years

Appears None

Remediation last 5 years


Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

as reported by regulatory agency



Review Conclusions T0603782010

Review indicates:

- Diesel fuel release
- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Site is currently a business park (RP is a bank)

Discussion:

- Any case information available?
- Any significant risk and source at the site?
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

A-ABBEY METALS INTERNATIONAL (T0603774420)

1931 S. Mateo St., Los Angeles, CA 90021



Case Age: 16 years
Primary COC: Gasoline

RP Identified: A-Abbey Metals Intl. -

Unclaimed in GeoTracker

Potential Media Affected: Soil Current land use: Residential

Well Network: N/A



CLEANUP OVERSIGHT AGENCIES

LOS ANGELES, CITY OF (LEAD) - CASE #: XS0001069

CASEWORKER: 15D - SUPERVISOR: NONE SPECIFIED

LOS ANGELES RWQCB (REGION 4)

CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FI	ILTER: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	12/28/1994
LEAK ACTION	Leak Discovery	12/5/1994
LEAK ACTION	<u>Leak Began</u>	1/1/1965

Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1994 and present
- No local regulatory case worker assigned
- No apparent RP involvement
- No reports or data in GeoTracker
- Site redeveloped?

NOTE: Data queried from GeoTracker and reviewed in October 2010

Activities Conducted to Date Based on GeoTracker T0603774420

Assessment last 5 years

Appears None


Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years



Review Conclusions T0603774420

Review indicates:

- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Cleanup Status History indicates: Site Assessment in 1995 and Remediation as of 5/19/1995
- Site appears to be residential site has been redeveloped?
- Regulatory lead information not complete in GT no local case # or worker information

Discussion:

- Any case information available?
- Has remediation been implemented, effectiveness?
- Assign a local case worker
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

CALIFORNIA TARGET STATION #49 (T0603705678)

5492 E Huntington Dr., Los Angeles, CA 90032



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1994 and present
- Apparent lack of regulatory oversight and RP involvement
- No reports or data in GeoTracker

NOTE: Data queried from GeoTracker and reviewed in October 2010

Case Age: 16 years
Primary COC: Gasoline

RP Identified: Johnson, George -

Unclaimed in GeoTracker

Potential Media Affected: Soil
Current land use: Undetermined

Well Network: N/A



CLEANUP OVERSIGHT AGENCIES

LOS ANGELES, CITY OF (LEAD) - CASE #: XS0001138

CASEWORKER: NEAL REITZELL - SUPERVISOR: NONE SPECIFIED

LOS ANGELES RWQCB (REGION 4)

CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FI	LTER: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	1/12/1995
LEAK ACTION	Leak Discovery	12/22/1994
LEAK ACTION	<u>Leak Began</u>	1/1/1965

Activities Conducted to Date Based on GeoTracker T0603705678

Assessment last 5 years

Appears None

Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

as reported by regulatory agency



Review Conclusions T0603705678

Review indicates:


- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Cleanup Status History indicates Site Assessment in 1995 (no additional information available)
- Unclear current land use

Discussion:

- Any case information available?
- Any significant risk at site?
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

MENDOZA SERVICE INC (T0603741517)

866 Sunset Blvd., Los Angeles, CA 90028



Case Age: 16 years Primary COC: Xylene

RP Identified: Mendoza Service, Inc. -

Unclaimed in GeoTracker
Potential Media Affected: Soil
Current land use: Residential

Well Network: N/A



CLEANUP OVERSIGHT AGENCIES

LOS ANGELES, CITY OF (LEAD) - CASE #: XS0001064

CASEWORKER: TED - SUPERVISOR: NONE SPECIFIED

LOS ANGELES RWQCB (REGION 4)

CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FIL	LTER: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	12/8/1994
LEAK ACTION	Leak Discovery	11/11/1994
LEAK ACTION	Leak Began	1/1/1965

Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1994 and present
- No local regulatory case worker assigned
- No apparent RP involvement
- No reports or data in GeoTracker

NOTE: Data gueried from GeoTracker and reviewed in October 2010

Activities Conducted to Date Based on GeoTracker T0603741517

Assessment last 5 years

Appears None


Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years



Review Conclusions T0603741517

Review indicates:

- Xylene release
- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Regulatory lead information not complete in GT no local case worker information

Discussion:

- Any case information available?
- Any significant risk and source (xylene only?)
- Assign a local case worker
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

ARCO #5033 (T0603708034)

1151 S. Flower St., Los Angeles, CA



Case Age: 15 years
Primary COC: Gasoline

RP Identified: Arco Products Co. -

Unclaimed in GeoTracker

Potential Media Affected: Soil

Current land use: Parking Lot (Staples

Center Parking Lot)
Well Network: N/A

Cleanup Status History	
DATE	STATUS
6/3/1996	Open - Verification Monitoring
5/20/1996	Open - Site Assessment
1/17/1996	Open - Site Assessment
11/7/1995	Open - Site Assessment
8/31/1995	Open - Case Begin Date

1			
	CLEANUP OVERSIGHT AGENCIES		
	LOS ANGELES, CITY OF (LEAD) - CASE #: XS0001146		
	CASEWORKER: TERRENCE PALMER - SUPERVISOR: NONE SPECIFIED		
	LOS ANGELES RWQCB (REGION 4)		
	CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED		

ACTIVITIES REPORT	ACTIVITY TYPE F	ILTER: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	11/7/1995
LEAK ACTION	Leak Discovery	8/31/1995
LEAK ACTION	<u>Leak Began</u>	1/1/1965

Possible Reasons Why This Case Is So Old

- Appears limited activity between 1996 and present
- Apparent lack of regulatory oversight and RP involvement
- No reports or data in GeoTracker
- Site might have been redeveloped?

NOTE: Data queried from GeoTracker and reviewed in October 2010

Activities Conducted to Date Based on GeoTracker T0603708034

Assessment last 5 years

Appears None

Remediation last 5 years


Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE T0603708034 as reported by regulatory agency



Review Conclusions T0603708034

Review indicates:

- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Cleanup Status History indicates: Site Assessment in 1995 and 1996;
 and Verification Monitoring as of 6/3/1996
- Site might have been redeveloped into a parking lot

Discussion:

- Any case information available?
- Site appears to have been redeveloped → any significant risk at site?
- What monitored media is being verified?
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

AUTO PARK 18 (T0603759109)

145 N. Grand Ave., Los Angeles, CA 90015



Case Age: 15 years
Primary COC: Gasoline

RP Identified: Builders Sheet Metal -

Unclaimed in GeoTracker

Potential Media Affected: Soil Current land use: Arts and Culture

(Dorothy Chandler Pavilion)

Well Network: N/A



CLEANUP OVERSIGHT AGENCIES

LOS ANGELES, CITY OF (LEAD) - CASE #: XS0001048

CASEWORKER: TERRENCE PALMER - SUPERVISOR: NONE SPECIFIED
LOS ANGELES RWQCB (REGION 4)

CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE F	ILTER: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	10/25/1995
LEAK ACTION	Leak Discovery	5/10/1995
LEAK ACTION	<u>Leak Began</u>	1/1/1965

Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1995 and present
- Apparent lack of regulatory oversight and RP involvement
- No reports or data in GeoTracker

NOTE: Data queried from GeoTracker and reviewed in October 2010

Activities Conducted to Date Based on GeoTracker T0603759109

Assessment last 5 years

Appears None

Remediation last 5 years


Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE T0603759109 as reported by regulatory agency



Review Conclusions T0603759109

Review indicates:

- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Cleanup Status History indicates: Site Assessment in 1995 and 1996, and Remediation as of 3/19/1996
- Site currently appears to be a parking lot?

Discussion:

- Any case information available?
- Has remediation been implemented, effectiveness?
- Any significant risk at site?
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

GVD COMMERCIAL PROPERTIES (T0603702241)

18300 Vanowen St., Reseda, CA 91335



Case Age: 15 years

Primary COC: Other Solvent or Non-

Petroleum Hydrocarbon **RP Identified:** GVD -Unclaimed in GeoTracker

Potential Media Affected: Other GW (Uses Other Than Drinking Water) **Current land use:** Restaurant (Popeye's)

Well Network: N/A



CLEANUP OVERSIGHT AGENCIES
LOS ANGELES, CITY OF (LEAD)
CASEWORKER: TBD - SUPERVISOR: NONE SPECIFIED
LOS ANGELES RWQCB (REGION 4) - CASE #: 913350907
CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPO	ORT ACTIVITY TYPE	FILTER: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	7/1/1995

Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1995 and present
- No local regulatory case worker assigned
- No apparent RP involvement
- No reports or data in GeoTracker

NOTE: Data gueried from GeoTracker and reviewed in October 2010

Activities Conducted to Date Based on GeoTracker T0603702241

Assessment last 5 years

Appears None

Remediation last 5 years


Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE T0603702241 as reported by regulatory agency



Review Conclusions T0603702241

Review indicates:

- Other solvent or non-petroleum fuel release
- Regulatory Activities indicates no work has occurred
- Cleanup Status History indicates "Site Assessment" in 1996 (no additional information available)
- No reports or data in GeoTracker to review
- Regulatory lead information not complete in GT no local case # or worker

Discussion:

- Any case information available?
- Media affected is "Other GW" → is risk significant?
- Assign local case worker
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility

LA CO FD FIRE STATION #046 (T0603705142)

14425 Olive View Dr., Sylmar, CA 91342



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1995 and present
- No reports or data in GeoTracker
- No local regulatory case worker assigned
- No apparent RP identified
- Government site, funding issues?

NOTE: Data queried from GeoTracker and reviewed in October 2010

Case Age: 15 years
Primary COC: Aviation
RP Identified: "BLANK" –
Unclaimed in GeoTracker

Potential Media Affected: Soil Current land use: Municipal (Los Angeles County Fire Department)

Well Network: N/A



CLEANUP OVERSIGHT AGENCIES
LOS ANGELES, CITY OF (LEAD)
CASEWORKER: TBD - SUPERVISOR: NONE SPECIFIED
LOS ANGELES RWQCB (REGION 4) - CASE #: R-12544
CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPO	ORT ACTIVITY TYPE	FILTER: Show All Activities
ACTION TYPE	<u>ACTION</u>	ACTION DATE
LEAK ACTION	Leak Reported	11/7/1995

Activities Conducted to Date Based on GeoTracker T0603705142

Assessment last 5 years

Appears None

Remediation last 5 years


Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

as reported by regulatory agency



Review Conclusions T0603705142

Review indicates:

- Aviation fuel release
- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Regulatory lead information not complete in GT no local case # or worker

Discussion:

- Any case information available?
- Any significant risk at site?
- Assign local case worker
- Identify RP
- Next step → cleanup timeline or closure possibility ("soils only"?)

PAN AMERICAN WORLD AIRWAYS, INC (T0603727663)

6501 W. Imperial Hwy., El Segundo, CA 90045



Case Age: 15 years

Primary COC: Waste Oil / motor /

hydraulic / lubricating

RP Identified: Bureau of Eng, Dep. Of Airports – Unclaimed in GeoTracker Potential Media Affected: Soil

Current land use: Airline (Nippon Cargo

Airlines)

Well Network: N/A

Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1995 and present
- Apparent lack of regulatory oversight and RP involvement
- No reports or data in GeoTracker
- Site is an airport

NOTE: Data queried from GeoTracker and reviewed in October 2010



CLEANUP OVERSIGHT AGENCIES		
LOS ANGELES, CITY OF (LEAD) - CASE #: XS0001155		
CASEWORKER: TERRENCE PALMER - SUPERVISOR: NONE SPECIFIED		
LOS ANGELES RWQCB (REGION 4)		
CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED		

ACTIVITIES REPORT	ACTIVITY TYPE FILTER:	Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	6/21/1995
LEAK ACTION	<u>Leak Discovery</u>	6/1/1995
LEAK ACTION	<u>Leak Began</u>	1/1/1965

Activities Conducted to Date Based on GeoTracker T0603727663

Assessment last 5 years

Appears None

Remediation last 5 years


Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE T0603727663 as reported by regulatory agency



Review Conclusions T0603727663

Review indicates:

- Waste / motor / hydraulic / lubricating oil release
- Regulatory Activities indicates no work has occurred
- Cleanup Status: Open Remediation as of 8/7/1995
- No reports or data in GeoTracker to review

Discussion:

- Any case information available?
- Has remediation been implemented, effectiveness?
- Site is an airport → any significant risk and source at site?
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

PENHALL COMPANY (T0603743170)

11182 W. Penrose Ave., Los Angeles, CA 91352



Case Age: 15 years
Primary COC: Diesel
RP Identified: Penhall Co. –
Unclaimed in GeoTracker

Potential Media Affected: Soil

Current land use: Industrial (Kenwalt Die

Casting)

Well Network: N/A



CLEANUP OVERSIGHT AGENCIES
LOS ANGELES, CITY OF (LEAD) - CASE #: XS0001292
CASEWORKER: TERRENCE PALMER - SUPERVISOR: NONE SPECIFIED
LOS ANGELES RWQCB (REGION 4)
CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE F	ILTER: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	9/26/1995
LEAK ACTION	Leak Discovery	9/15/1995
LEAK ACTION	<u>Leak Began</u>	1/1/1965

Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1995 and present
- Apparent lack of regulatory oversight and RP involvement
- No reports or data in GeoTracker

NOTE: Data gueried from GeoTracker and reviewed in October 2010

Activities Conducted to Date Based on GeoTracker T0603743170

Assessment last 5 years

Appears None

Remediation last 5 years


Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

as reported by regulatory agency



Review Conclusions T0603743170

Review indicates:

- Diesel fuel release
- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Cleanup Status: Open Remediation as of 11/21/1995

Discussion:

- Any case information available?
- Has remediation been implemented, effectiveness?
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

STOLEN BASE CLEANERS (T0603700906)

1015 MLK Jr. Blvd., Los Angeles, CA 90037



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1995 and present
- Apparent lack of regulatory oversight and RP involvement
- No reports or data in GeoTracker

NOTE: Data queried from GeoTracker and reviewed in October 2010

Case Age: 15 years
Primary COC: Solvents

Unclaimed in GeoTracker
Potential Media Affected: Soil
Current land use: Commercial
(Exposition Marketplace)
Well Network: N/A

RP Identified: Denmarst Ltd -



CLEANUP OVERSIGHT AGENCIES LOS ANGELES, CITY OF (LEAD) CASEWORKER: TERRENCE PALMER - SUPERVISOR: NONE SPECIFIED LOS ANGELES RWQCB (REGION 4) - CASE #: 900370034 CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FI	LTER: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	10/19/1995
LEAK ACTION	Leak Discovery	10/19/1995

Activities Conducted to Date Based on GeoTracker T0603700906

Assessment last 5 years

Appears None

Remediation last 5 years


Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE T0603700906 as reported by regulatory agency



Review Conclusions T0603700906

Review indicates:

- Solvent release (UST site?)
- Regulatory Activities indicates no work has occurred
- Cleanup Status: Open Remediation as of 12/12/1996
- No reports or data in GeoTracker to review

Discussion:

- Any case information available?
- Has remediation been implemented, effectiveness?
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

STUDIO SERVICES INC (T0603781181)

14817 W. Bessemer St., Los Angeles, CA 91411



Case Age: 15 years
Primary COC: Gasoline

RP Identified: Studio Services, Inc. -

Unclaimed in GeoTracker

Potential Media Affected: Soil

Current land use: Commercial (Studio

Services)

Well Network: N/A



CLEANUP OVERSIGHT AGENCIES
LOS ANGELES, CITY OF (LEAD) - CASE #: XS0001163
CASEWORKER: TERRENCE PALMER - SUPERVISOR: NONE SPECIFIED
LOS ANGELES RWQCB (REGION 4)
CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FILTER:	Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	8/30/1995
LEAK ACTION	Leak Discovery	8/23/1995
LEAK ACTION	<u>Leak Began</u>	1/1/1965

Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1995 and present
- Apparent lack of regulatory oversight and RP involvement
- No reports or data in GeoTracker

NOTE: Data gueried from GeoTracker and reviewed in October 2010

Activities Conducted to Date Based on GeoTracker T0603781181

Assessment last 5 years

Appears None

Remediation last 5 years


Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE T0603781181 as reported by regulatory agency



Review Conclusions T0603781181

Review indicates:

- Regulatory Activities indicates no work has occurred
- Cleanup Status: Open Remediation as of 10/6/1995
- No reports or data in GeoTracker to review

Discussion:

- Any case information available?
- Has remediation been implemented, effectiveness?
- Any significant risk and source at site?
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

SUNSHINE TRUCK STOP INC. (T0603707597)

1800 E Pacific Cost Hwy., Wilmington, CA 90744



Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1995 and present
- Apparent lack of regulatory oversight and RP involvement
- No reports or data in GeoTracker

NOTE: Data queried from GeoTracker and reviewed in October 2010

Case Age: 15 years

Primary COC: Other Solvent or Non-Petroleum Hydrocarbon RP Identified: Telalyan, Mike – Unclaimed in GeoTracker

Potential Media Affected: Soil Current land use: Undetermined

Well Network: N/A



CLEANUP OVERSIGHT AGENCIES
LOS ANGELES, CITY OF (LEAD) - CASE #: XS0001162
CASEWORKER: TERRENCE PALMER - SUPERVISOR: NONE SPECIFIED
LOS ANGELES RWQCB (REGION 4)
CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPORT	ACTIVITY TYPE FILTER: Show All Activities	
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	7/31/1995
LEAK ACTION	Leak Discovery	7/21/1995
LEAK ACTION	<u>Leak Began</u>	1/1/1965

Activities Conducted to Date Based on GeoTracker T0603707597

Assessment last 5 years

Appears None

Remediation last 5 years


Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years

IMPEDIMENTS TO CLOSURE T0603707597 as reported by regulatory agency



Review Conclusions T0603707597

Review indicates:


- Other solvent or non-petroleum hydrocarbon release (Federal UST case?)
- Regulatory Activities indicates no work has occurred
- Cleanup Status History indicates Site Assessment in 1995 (no additional information available)
- No reports or data in GeoTracker to review

Discussion:

- Any case information available?
- Any significant risk at site?
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)

TUNE-UPS PLUS (T0603787881 & T0603725845)

7556 N. Balboa Blvd., Van Nuys, CA 91406



Unclaimed in GeoTracker Potential Media Affected: Soil

Current land use: Auto Service (Honda

Station)

Well Network: N/A



DUPLICATE: T0603725845

Possible Reasons Why This Case Is So Old

- Appears no cleanup activity between 1994 and present
- No local regulatory case worker assigned
- · No apparent RP involvement
- No reports or data in GeoTracker

NOTE: Data gueried from GeoTracker and reviewed in October 2010

CLEANUP OVERSIGHT AGENCIES LOS ANGELES, CITY OF (LEAD) - CASE #: XS0001068 CASEWORKER: TBD - SUPERVISOR: NONE SPECIFIED LOS ANGELES RWQCB (REGION 4) CASEWORKER: YUE RONG - SUPERVISOR: NONE SPECIFIED

ACTIVITIES REPOR	T ACTIVITY TYPE	FILTER: Show All Activities
ACTION TYPE	ACTION	ACTION DATE
LEAK ACTION	Leak Reported	11/23/1994
LEAK ACTION	Leak Discovery	11/9/1994
LEAK ACTION	<u>Leak Began</u>	1/1/1965

Activities Conducted to Date Based on GeoTracker T0603787881

<u>Assessment last 5 years</u>

Appears None


Remediation last 5 years

Appears None

Assessment older than 5 years

Appears None

Remediation older than 5 years



Review Conclusions T0603787881

Review indicates:

- Regulatory Activities indicates no work has occurred
- No reports or data in GeoTracker to review
- Cleanup Status History indicates: Site Assessment in 1995 and Remediation as of 3/1/1995
- Regulatory lead information not complete in GT no local case worker information

Discussion:

- Any case information available?
- Has remediation been implemented, effectiveness?
- Assign a local case worker
- RP and GeoTracker compliance
- Next step → cleanup timeline or closure possibility ("soils only"?)