

LEGEND

- Burial Trench
- Landfill Boundaries
- Facility and Zone 1 Boundary
- Perimeter Source Control Trench (PSCT)
- Plume Capture Collection Trench (PCT)
- Clay Barrier
- Creek
- Pond Outline
- RGPZ-15B — Lower HSU Piezometer
- RP-63C — Lower HSU Monitoring Well
- MET — Meteorological Station
- Gauged Measurement of DNAPL through March 2010
- Dissolved Concentrations of DNAPL Constituents greater than 1% of aqueous solubility
- Dissolved Concentrations of DNAPL Constituents greater than 10% of aqueous solubility
- Former Pond and Pad Subarea
- Historical Natural Drainage
- —?— Presence of DNAPL inferred by DNAPL at Landfill/Lower HSU contact

Plotted: 01-17-2011 11:31 AM By: pcdocs\tlaki
File#: P:\4088097619\Casmalia_RI_Report\CAD\...4088097619R006.dwg

NO.	DATE	REVISIONS	BY	CHK

DRAWN: PCB	PROJECT NO: 4088097619		
ENGINEER:	SCALE: 1"= 400'		
CHECKED: NAM	APPROVED: WJF		
DATE: 1/2011	DATE: 1/2011		

Final Remedial Investigation Report

Casmalia Resources Superfund Site
Casmalia, California

DNAPL in Lower HSU Observed or Inferred from Groudwater Concentrations Fall 2004 and Spring 2005 RI Sampling

FIGURE	5-34
SHEET:	1 OF 1
REVISION NUMBER:	0
DATE:	January 2011