

EXPLANATION

RIMW-8 Well Name

(-130) Projection Distance (negative numbers projected from west)

Water Table during March 2010

Burial Trench

Dissolved Concentrations of DNAPL Constituents greater than 1% of aqueous solubility

Dissolved Concentrations of DNAPL Constituents greater than 10% of aqueous solubility

Dissolved Concentrations of LNAPL Constituents greater than 1% of aqueous solubility

Observed LNAPL during Drilling (at depths observed)

Observed DNAPL during Groundwater Sampling

Observed LNAPL during Groundwater Sampling

See Figure 5-38 for cross-section Location.

Plotted: 01-17-2011 4:28 PM By: pcboudreau
Path: P:\4088097619_Casmalia_RI_Revision\CAD\ 4088097619078.dwg

NO.	DATE	REVISIONS	BY	CHK

DRAWN:	PCB	PROJECT NO:	4088097619
ENGINEER:		SCALE:	as shown
CHECKED:	NAM	APPROVED:	WJF
DATE:	1/2011	DATE:	1/2011

Final Remedial Investigation Report

Casmalia Resources Superfund Site
Casmalia, California

North-South Cross-Section
Burial Trench Area

FIGURE: **5-37**

SHEET: **1** OF **1**

REVISION NUMBER: 0

DATE: January 2011