



BROADBENT

1370 Ridgewood Drive, Suite 5, Chico, CA 95973

[T] 530-566-1400 [F] 530-566-1401

broadbentinc.com

CREATING SOLUTIONS. BUILDING TRUST.

April 26, 2022

Project No. 09-10-106

California Regional Water Quality Control Board
Central Valley Region
11020 Sun Center Drive, #200
Rancho Cordova, CA 95670-6114

Attn: Ms. Lani L. Andam, Water Resource Control Engineer

Re: Tentative Waste Discharge Requirements Comments
Pilot Travel Center No. 168
30035 County Road 8, Dunnigan, Yolo County, California
WDR Order No. 5-01-266

Dear Ms. Andam:

Broadbent & Associates, Inc. (Broadbent) has prepared this letter providing comments associated with review of the Tentative Waste Discharge Requirements permit associated with wastewater operations at Pilot Travel Center #168 in Dunnigan, Yolo County, California (Site or PTC 168).

[TENTATIVE] WASTE DISCHARGE REQUIREMENTS ORDER R5-2022-####

Introduction Item #3 (pdf page 8)

The Facility does not meet the conditions of WQ 2014-0153-DWQ because the Facility receives wash water generated by activities conducted at the former truck wash facility maintenance bays.

Comment: The truck wash has been converted into a truck care facility and all washing equipment has been removed. Wash water has not been discharged as wastewater since conversion in 2018.

Existing Facility and Discharge #11 (pdf page 9)

Wastewater from the travel center and stand-alone restaurant is pumped through a metering station and can be discharged into any one of the five ponds.

Comment: Wastewater from the travel center and stand-alone restaurant are pumped through separate metering stations prior to combined discharge into any one of the five ponds.

Existing Facility and Discharge #15 (pdf page 11)

WSW is the primary source water, which is approximately 520 ft deep and sealed to a depth of 200 ft below ground surface (bgs).

Comment: Well construction details should be reviewed for the WSW and TWW.

Existing Facility and Discharge #17 (pdf page 12)

Wastewater is primarily domestic waste from commercial sources, including kitchen waste and nondomestic flows from the truck service maintenance bay.

Comment: The majority of flow from the truck care facility are domestic waste from the toilet and sink.

Compliance History #21 (pdf page 13)

Comment: No further action has been granted for the Site's environmental case.

Pilot Travel Centers LLC appreciates the opportunity to provide comments during renewal of the Site's discharge permit process. Please do not hesitate to contact Broadbent at (530) 566-1400 if you should have further questions or require additional information.

Sincerely,
BROADBENT & ASSOCIATES, INC.



Aric C. Morton, P.G., C.E.M.
Principal Geologist

cc: Ms. Liz Peterson, Pilot Travel Centers LLC