

**California Regional Water Quality Control Board
North Coast Region**

Order Number R1-2004-0117

Rescission of Monitoring and Reporting Program No. 91-37

for

Garfield G. Sterner
Rohnert Park Towing
550 State Farm Drive
Rohnert Park, CA 94901

The Executive Officer of the California Regional Water Quality Control Board, North Coast Region (hereinafter the Regional Water Board) finds that:

1. On February 25, 1991 the Regional Water Board issued Monitoring and Reporting Program No. 91-37 to initiate quarterly monitoring and sampling of all wells installed as part of an investigation of a release from underground tanks at the Rohnert Park Towing facility located at 5500 State Farm Drive in Rohnert Park California.
2. Investigation and remediation of this property have been completed. No further monitoring or reporting will be required to assess the cleanup at the Rohnert Park Towing facility.

THEREFORE, IT IS HEREBY ORDERED that: Monitoring and Reporting Program No. 91-37 for Garfield G. Sterner, Rohnert Park Towing 5500 State Farm Drive, Rohnert Park, CA 94901 be rescinded.

Ordered by _____

Catherine E. Kuhlman
Executive Officer

December 22, 2004