

ERRATA

8:30 a.m., September 11, 2008  
North Coast Regional Water Board  
Hearing Room  
5550 Skylane Blvd., Suite A  
Santa Rosa, California

Item: 5 - Errata

Subject: Update of Monitoring in Freshwater Creek and Elk River

This errata corrects an error in the Executive Officer's Summary Report (EOSR) for this item dated September 2, 2008. The correction is to pool depth data presented in Figure 5 of the Executive Officer's Summary Report; the data corresponding to 2005-2006 was measured in meters and erroneously reported as feet. Figure 1, below, provides the corrected data and replaces Figure 5 (page 6) of the EOSR. Additionally, the 2007 data were recently submitted by PALCO and are included in Figure 1, below.




Figure 1. Average residual pool depth conditions in Elk River

Over the period of record, there is not an observable trend in the data. There were fluctuations between 2002-2004 at most stations. As of 2007, of the five stations measured, four either met or nearly met the target. The Mainstem station did not meet the target.