

**From:** Rachel West <rwest@mlj-llc.com>  
**To:** Chris Jimmerson <CJimmerson@waterboards.ca.gov>  
**CC:** Susan Fregien <sfregien@waterboards.ca.gov>  
**Date:** 1/19/2012 10:37 AM  
**Subject:** Re: ESJWQC Water Toxicity Exceedance Report-January 2012

Hello Chris,

Yes, I do recommend that you exchange the site name for Yori Grove Drain to Lateral 3 along East Taylor Rd. We are also in the process of updating all of our data and the Annual Monitoring Report to note the misnamed site and report all data collected from monitoring at that location as Lateral 3 along east Taylor Rd.

Please let me know if you have any other questions.

Thanks,  
Rachel

On Thu, Jan 19, 2012 at 10:24 AM, Chris Jimmerson <CJimmerson@waterboards.ca.gov> wrote:

> Rachel, would you recommend that I exchange the station named Yori Grove  
> Drain @ East Taylor Rd with Lateral 3 along East Taylor Rd in my records?  
> I keep an excel data spreadsheet and wonder if i should change the name for  
> all the Yori Grove Drain @ East Taylor Rd entries.  
>  
>  
> Chris Jimmerson  
> Environmental Scientist  
> Irrigated Lands Regulatory Program  
> Central Valley Water Board  
> 11020 Sun Center Drive, #200  
> Rancho Cordova, CA 95670  
> Phone 916-464-4859  
> Fax 916-464-4780  
> cjimmerson@waterboards.ca.gov  
>  
>  
>>> Rachel West <rwest@mlj-llc.com> 1/19/2012 8:54 AM >>>  
>  
> Dear Susan,  
>  
> As required in the Monitoring and Reporting Program (Order No.  
> R5-2008-0005) for Coalition Groups, an Exceedance Report is being submitted  
> to address the following issues: a) the exceedances, b) the follow-up  
> monitoring, and c) any analysis or other actions the Coalition Group may  
> take to address the exceedances.  
>  
> a.) On January 10, 2012, Normal Monitoring (NM) and Management Plan  
> Monitoring (MPM) were conducted in the ESJWQC region. Water was collected  
> for analysis of water column toxicity. Toxicity to \*Selenastrum  
> capricornutum \*occurred in the grab sample collected from Lateral 3 along  
> East Taylor Rd (misnamed as Yori Grove Drain @ East Taylor Rd during 2011  
> monitoring). See attached Table 1 for details on this exceedance. Site  
> pictures and flow data for all sites sampled during this event were  
> provided to the CVRWQCB by email on January 16, 2012 and are also available  
> on the MLJ-LLC Sharepoint website (  
> <http://sharepoint.mlj-llc.com/mlj-db/database/forms/allitems.aspx>).  
>  
> b.) Lateral 3 along East Taylor Rd was monitored for all Assessment  
> Monitoring constituents during the January sampling event. Assessment  
> Monitoring is scheduled to take place again at Lateral 3 along East Taylor  
> Rd on February 7, 2012. However, the Coalition has requested this site be  
> removed from its monitoring plan (request submitted on December 28, 2011),  
> if the request is approved before February 7, 2012, the Coalition will move  
> to the Levee Drain @ Carpenter Rd site subwatershed for 2012 through 2014  
> Assessment Monitoring in Zone 2.  
>  
> c.) Samples collected from this location (misnamed in 2011 as Yori Grove

> Drain @ East Taylor Rd) have tested toxic to \*Selenastrum capricornutum \*twice  
> prior to this event in June and September 2011. Since algae growth was  
> less than 50% compared to the control, a TIE has been initiated on the  
> January 10, 2012 samples from Lateral 3 along East Taylor Rd. When  
> results from the chemistry laboratory arrive the Coalition will report any  
> chemistry exceedances at that time. All new exceedances requiring  
> Management Plans as well as Management Plan Monitoring results will be  
> evaluated in the ESJWQC Annual Management Plan Update Report to be  
> submitted on April 1, 2013.

>  
> Mike Johnson

>  
>  
> Thanks,

> ~~~~~

> Rachel C. West  
> Environmental Scientist  
> Michael L. Johnson LLC  
> 632 Cantrill Drive  
> Davis, CA 95618

>  
> Tel: 530-756-5200  
> Fax: 530-756-5225  
> rwest@mlj-llc.com

>  
>  
>  
>

--

~~~~~

Rachel C. West  
Environmental Scientist  
Michael L. Johnson LLC  
632 Cantrill Drive  
Davis, CA 95618

Tel: 530-756-5200  
Fax: 530-756-5225  
rwest@mlj-llc.com