





WATEPUBLIC WORKS DEPARTMENT/ ECP CONTROL FIELDENGINEERING DIVISION 9485 AERO DRIVE, MS 18 2014 JAN 28 AM 11 San DIEGO, CA 92123 858-627-3200

TRANSMITTAL

Date: January 28, 2014

The attached Report is intended for:

То:	Wayne Chiu	From:	George Qsar
Company:	Regional Water Quality Control Board	Title:	Senior Civil Engineer
	2375 Northside Drive, Suite 100	8	
Phone #	858-627-3931	Phone #	858-627-3240

Subject: Response to Casa Mira View site conditions (WDID 9 37C321980)

Comments:

Wayne, Delivered herein is the Field Engineering Divisions response to the emails regarding the site inspection of Estates at Costa del Mar on January 7, 2014. Please contact me if you have any questions or would like to meet. Thank you.

George

THIS MESSAGE IS INTENDED ONLY FOR THE USE OF THE INDIVIDUAL OR ENTITY TO WHICH IT IS ADDRESSED, AND MAY CONTAIN INFORMATION THAT IS PRIVILEGED, CONFIDENTIAL AND EXEMPT FROM DISCLOSURE UNDER APPLICABLE LAW, RECEIPT BY AN UNINTENDED RECIPIENT DOES NOT CONSTITUTE A WAIVER OF ANY APPLICABLE PRIVILEGE.

If the reader of this message is not the intended recipient, or the employee or agent responsible for delivering the message to the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited.

If you have received this communication in error, please notify us immediately by telephone, and return the original message to us at the above address via the U.S. Postal Service.



THE CITY OF SAN DIEGO

January 27, 2014

Mr. Wayne Chiu Water Resources Control Engineer Surface Waters Basins Branch San Diego Regional Water Quality Control Board 2375 Northside Drive, Suite 100 San Diego, CA 92108-2700

Dear Wayne,

Subject: Response to the Estates at Costa del Mar (WDID 9 37C321980)

Site conditions on January 7th, 2014.

The City of San Diego Field Engineering Division (FED), Public Works Department is in receipt of the email sent January 14, 2014 regarding the Estates at Costa del Mar construction site. Thank you for contacting FED regarding this site.

Estates at Costa del Mar is a private development of approximately 10.88 acres and has total of 4 homes planned with an existing home on lot one. This is an inactive site, as no construction activities were noticed for the entire rainy season to date except for the installation of a brow ditch a few weeks ago. The grading, including retaining walls, have been completed quite a few years ago, no other construction activities were noticed except for some BMP maintenance and additions.

In addition to the rainy season alert letter that the FED sends out for all the projects before the beginning of the rainy season, the FED has been performing BMP site inspections on a regular basis for the perimeter of the project, the slopes and the access. (See BMP notices in Attachment #1). The FED BMP inspections, with notices issued, occurred on October 6, 17, and 28, November 3, 14, and 26, December 5, 18 and 23, 2013, January 2, and 16, 2014. In addition, the Resident Engineer (RE) sent a letter to the developer on October 9, 2013 for their noncompliance. (See Attachment #2). The RE and Supervising Engineer (SE) performed an inspection of the site on January 16, 2014. A letter was sent to the Engineer of Work, Mr. Myles Cooper (See Attachment #3), who we understand is handling the development since the owner is now deceased. The letter is requiring that the site be brought to the required standards by January 29th, 2014. Due to the property being placed in a Trust, and Mr. Cooper, who is listed as the QSP for this project, we will be contacting the bonding company to enforce the laws prevailing over this project if the deadline is not met.

On Monday, January 16, 2014, the RE and the SE performed a site inspection. Mr. Cooper was issued additional storm water notices and was directed to continue to improve the conditions of the site and to maintain storm water compliance at all times. The RE and SE are performing site inspections every other day and everyday if required for compliance. A site visit on January 24th, 2014, indicated much improvement over previous site visits. (See photos in Attachment #4).

Page 2 of 2 Estates at Costa del Mar BMP Inspection Field Engineering Division, Public Works January 2014

The FED provides the inspection of development projects that are subdivisions and/or have engineering permits for public improvements, as well as grading not associated with building permits. Grading that is entirely for building construction is inspected by the DBCS of the Development Service Department. An aspect of the inspection practice is ensuring the Storm Water Best Management Practices (BMP) are in compliance with the Municipal Storm Water Permit, Construction General Permit (CGP), the City's Storm Water Standard Manual and industry practices. The FED Resident Engineer is notified by the contractor that work will be occurring and requires inspection. The RE inspects the improvements and while on site inspects the BMP's. When the contractor does not require the RE for the typical inspections, the RE inspects the site for BMP's at regular intervals, prior to a rain event, after a rain event and more as needed. Most often, once the building construction begins the public improvements have been constructed and the infrastructure has been completed. For large sites the grading is usually phased and a portion of the site can have buildings under construction while other areas of the site have additional grading and some on-site public improvements. The areas under the engineering permit are inspected for adequate BMPs at required intervals or more as needed.

The Field Engineering Division is continuing to provide additional training and guidance on the importance of storm water compliance for the Resident Engineers and Supervising Engineers. Additionally, if the guidelines are not followed by the Resident Engineers, Supervising Engineers disciplinary actions may occur. The Field Engineering Division and Public Works Department takes the Storm Water Compliance very seriously and are committed to ensuring construction sites under their jurisdiction comply with all storm water requirements associated with the engineering permits, subdivision agreements, as well as capital improvement projects and building permits.

Thank you again for bringing this to our attention. We appreciate your time and efforts. If you have any questions, comments, or would like additional information, please contact George Qsar, Senior Civil Engineer at gqsar@sandiego.gov or 858-627-3240.

Respectfully,

Dave Zoumaras Deputy Director

Field Engineering Division

Attachments: 1 .FED Storm Water BMP Notices

Notice of Inadequate BMP's Letter, October 9th, 2013
 Notice of Inadequate BMP's Letter, January 16th, 2014

4. Photos Taken January 24, 2014

cc: James Nagelvoort, Director, Public Works Department

Kris McFadden, Deputy Director, Transportation Storm Water Department Sumer Hasenin, Senior Engineer, Transportation and Storm Water Department

ATTACHMENT #1

Estates at Costa Del Mar WDID 9 37C321980



STORM WATER POLLUTION PREVENTION INSPECTION

Public Works - Engineering and Capital Projects Field Engineering (858) 627-3200

DATE: 1/16/2014 12:00:00 AM

NAME: Bowers, Grant

	WEATHER: Sunny				
		NOTICE:	PRIORITY:	High	
PROJECT:	23421526 - The Estate	at Costa Del Mar			
CONTRACTOR:			PHONE:		
SITE CONTACT	Myles Cooper		PHONE:	858-277-0441	
OWNER:	Perl Family Trust				
PERMIT NUMBER		WORK ORDER 23421526	-		
	Arroyo Sorrento PI				
LOCATION:	Arroyo Sorrento Pl		 -	<u>.</u> .	
SITE STATUS:					
CORRECTIVE ACTIONS:	Existing BMP adequate BMP inadequate, adjust Maintain SWPP Docume Improve Erosion Contro Improve Sediment Cont Improve Perimeter Cont Improve Materials Hand Maintain Street Sweepin Maintain Construction A	tments needed ents of BMP trof BMP trof BMP			
COMMENTS	S:				
		ere are still slopes that need to nes have dirt in them that need t			

that additional straw mats and gravel were brought to the site. Additional slopes were covered and the entrance

FE-SWPP-IN-030812

was re-graveled.



STORM WATER POLLUTION PREVENTION INSPECTION

Public Works - Engineering and Capital Projects Field Engineering (858) 627-3200

DATE: 1/2/2014 4:00:00 PM

NAME: Bowers, Grant

	WEATHER: Sunny			
		NOTICE:	PRIORITY:	High
PROJECT:	23421526 - The Estate	at Costa Del Mar	••	
CONTRACTOR:			PHONE:	
SITE CONTACT	. =		PHONE:	858-277-044
	Perl Family Trust			
PERMIT NUMBER		WORK ORDER 23421526		
ADDRESS:	Arroyo Sorrento PI			
LOCATION:	Arroyo Sorrento Pl			
SITE STATUS:				
CORRECTIVE ACTIONS:	Existing BMP adequately BMP inadequate, adjustr Maintain SWPP Docume Improve Erosion Control Improve Sediment Control Improve Perimeter Control Improve Materials Handl Maintain Street Sweepin Maintain Construction A	ments needed nts I BMP rol BMP rol BMP ing		
COMMENT	S:			
A routine BMP inspection vare still broken gravel bags	was conducted on this day. It is being used and slopes that are	noted that new brow ditches we not completely covered. The	vere being ins perimeter fen	talled. There ice also is in

need of some maintenance.



STORM WATER POLLUTION PREVENTION INSPECTION

Public Works - Engineering and Capital Projects Field Engineering (858) 627-3200

DATE: 12/23/2013 12:00:00 AM

NAME: Rowers Grant

	NAME. Bowers,	Jiani	
	WEATHER: Sunny		
	NOTICE:	PRIORITY	High
PROJECT:	23421526 - The Estate at Costa Del Mar	-	
CONTRACTOR:		PHONE:	
SITE CONTACT	Myles Cooper	PHONE:	858-277-0441
OWNER:	Perl Family Trust		
PERMIT NUMBER	WORK ORDER 23421526	S 	
	Arroyo Sorrento PI		
LOCATION:	Arroyo Sorrento Pl		
SITE STATUS:			
CORRECTIVE ACTIONS:	Existing BMP adequately maintained BMP inadequate, adjustments needed Maintain SWPP Documents Improve Erosion Control BMP Improve Sediment Control BMP Improve Perimeter Control BMP Improve Materials Handling Maintain Street Sweeping Maintain Construction Access		
COMMENTS A routine BMP inspection was site and there are slopes as	S: vas conducted on this day. There are still gravel bags that r nd exposed dirt that needs cover. The perimeter fence is al	need replaceme so in need of ma	nt around the aintenance.
FE-SWPP-IN-030812			



STORM WATER POLLUTION PREVENTION INSPECTION

Public Works - Engineering and Capital Projects Field Engineering (858) 627-3200

DATE: 12/18/2013 4:00:00 PM

NAME: Bowers, Grant

WEATHER: Drizzle NOTICE: PRIORITY: High PROJECT: 23421526 - The Estate at Costa Del Mar PHONE: **CONTRACTOR: SITE CONTACT Myles Cooper** PHONE: 858-277-0441 **OWNER:** Perl Family Trust PERMIT NUMBER **WORK ORDER 23421526** ADDRESS: Arroyo Sorrento PI LOCATION: Arroyo Sorrento Pl SITE STATUS: Existing BMP adequately maintained BMP inadequate, adjustments needed Maintain SWPP Documents Improve Erosion Control BMP CORRECTIVE ACTIONS: | Improve Sediment Control BMP Improve Perimeter Control BMP Improve Materials Handling Maintain Street Sweeping

COMMENTS:

A rain event inspection was conducted on this day. Broken gravel bags need to be replaced and there are still some sloped areas that lack protection. It is noted that additional BMP materials have been brought to the site.

Maintain Construction Access



STORM WATER POLLUTION PREVENTION INSPECTION

Public Works - Engineering and Capital Projects Field Engineering (858) 627-3200

DATE: 12/5/2013 4:00:00 PM

NAME: Bowers, Grant

		WEATHER: O'cast		
		NOTICE:	PRIORITY:	: High
PROJECT:	23421526 - The Estate	at Costa Del Mar		
CONTRACTOR:			PHONE:	
SITE CONTACT	Myles Cooper		PHONE:	858-277-044
OWNER:	Perl Family Trust		-	
PERMIT NUMBER		WORK ORDER 23421526		_
ADDRESS:	Arroyo Sorrento PI			
LOCATION:	Arroyo Sorrento Pl			
SITE STATUS:				-
	Existing BMP adequately	y maintained		
		ments needed		
	☐ Maintain SWPP Docume	nts		

CORRECTIVE ACTIONS: | Improve Sediment Control BMP

☐ Improve Erosion Control BMP

☐ Improve Perimeter Control BMP

☐ Improve Materials Handling

☐ Maintain Street Sweeping

COMMENTS:

A rain event inspection was conducted on this day. There are still some slopes that are exposed and gravel bags that are broken. Minor dirt and rocks been tracked onto the street that should be swept. It is noted that more work has been done to cover expo



STORM WATER POLLUTION PREVENTION INSPECTION

Public Works - Engineering and Capital Projects Field Engineering (858) 627-3200

DATE: 11/26/2013 4:00:00 PM

NAME: Bowers, Grant

		WEATHER: Sunny	/
		NOTICE:	PRIORITY: High
PROJECT:	23421526 - The Estate at C	Costa Del Mar	
CONTRACTOR:			PHONE:
SITE CONTACT	Myles Cooper		PHONE: 858-277-0441
OWNER:	Perl Family Trust		
PERMIT NUMBER	 	ORK ORDER 234215	26
	Arroyo Sorrento Pl	·	
LOCATION:	Arroyo Sorrento Pl		
SITE STATUS:			
	Existing BMP adequately ma	intained	
	✓ BMP inadequate, adjustment		
	Maintain SWPP Documents		
	Improve Erosion Control BM	P	
CORRECTIVE ACTIONS:	•		
	Improve Perimeter Control B		
	☐ Improve Materials Handling		
	Maintain Street Sweeping		
	☐ Maintain Construction Acces	ss	
COMMENT	S:		
A routine BMP inspection v broken gravel bags that red	vas conducted on this day. It is note quire replacement and some slopes	d that additional slope that need protection.	es were covered. There are still
FE-SWPP-IN-030812			



STORM WATER POLLUTION PREVENTION INSPECTION

Public Works - Engineering and Capital Projects Field Engineering (858) 627-3200

DATE: 11/14/2013 4:00:00 PM

NAME: Bowers, Grant

		EATHER: Ptly Cldy	/	
		NOTICE:	PRIORITY	High
PROJECT:	23421526 - The Estate at Cos	ta Del Mar		
CONTRACTOR:			PHONE:	
SITE CONTACT	Myles Cooper		PHONE:	858-277-0441
OWNER:	Perl Family Trust			·
PERMIT NUMBER	WOR	CORDER 23421526		
ADDRESS:	Arroyo Sorrento Pl			
LOCATION:	Arroyo Sorrento Pl	<u></u>		
SITE STATUS:				
	Existing BMP adequately mainta	ained		
	✓ BMP inadequate, adjustments n	eeded		
	Maintain SWPP Documents			
	Improve Erosion Control BMP			
CORRECTIVE ACTIONS:	☐ Improve Sediment Control BMP			
	☐ Improve Perimeter Control BMP			
	Improve Materials Handling			
	Maintain Street Sweeping			
	Maintain Construction Access			
COMMENTS	· ·			
A routine BMP inspection waround the site. There are s	as conducted on this day. More gravel till some broken gravel bags that need	bags were replaced a replacement and slo	and more grave pes that should	el was spread d be covered.
FE-SWPP-IN-030812			 -	



STORM WATER POLLUTION PREVENTION INSPECTION

Public Works - Engineering and Capital Projects Field Engineering (858) 627-3200

DATE: 11/3/2013 4:00:00 PM

NAME: Bowers, Grant

		WEATHER: O'cast	
		NOTICE:	PRIORITY: High
PROJECT:	23421526 - The Estate	e at Costa Del Mar	
CONTRACTOR:	· · · · · · ·		PHONE:
SITE CONTACT	Myles Cooper		PHONE: 858-277-0441
OWNER:	Perl Family Trust		
PERMIT NUMBER		WORK ORDER 23421526	
	Arroyo Sorrento PI		
LOCATION:	Arroyo Sorrento Pl		
SITE STATUS:			
CORRECTIVE ACTIONS:	Existing BMP adequate BMP inadequate, adjus Maintain SWPP Docum Improve Erosion Contr Improve Sediment Con Improve Perimeter Con Improve Materials Hand Maintain Street Sweepi Maintain Construction	etments needed ents of BMP trof BMP etrof BMP dling	
COMMENTS	S:		
A routine inspection was coincluding new straw mats a gravel bags that need repla	nd gravel over the roads. The	ed there have been improvement ere are still some slopes that are	s to the existing BMPs unprotected and broken



STORM WATER POLLUTION PREVENTION INSPECTION

Public Works - Engineering and Capital Projects Field Engineering (858) 627-3200

DATE: 10/28/2013 5:00:00 PM

NAME: Bowers, Grant

	WEATHER:	Ptly Cldy
	NOTICE:	PRIORITY: High
PROJECT:	23421526 - The Estate at Costa Del Ma	ar
CONTRACTOR:		PHONE:
SITE CONTACT	Myles Cooper	PHONE: 858-277-0441
OWNER:	Perl Family Trust	
PERMIT NUMBER	WORK ORDER	23421526
ADDRESS:	Arroyo Sorrento Pl	
LOCATION:	Arroyo Sorrento Pl	
SITE STATUS:		
CORRECTIVE ACTIONS:	Existing BMP adequately maintained BMP inadequate, adjustments needed Maintain SWPP Documents Improve Erosion Control BMP Improve Sediment Control BMP Improve Perimeter Control BMP Improve Materials Handling Maintain Street Sweeping Maintain Construction Access	
COMMENT	S:	
A routine inspection was care slopes that are still unp	ompleted on this day. There were burms added to protected and gravel bags that need replacement.	the lots to help contain water. There



STORM WATER POLLUTION PREVENTION INSPECTION

Public Works - Engineering and Capital Projects Field Engineering (858) 627-3200

DATE: 10/17/2013 5:00:00 PM

NAME: Bowers, Grant

WEATHER: Ptly Cldy

		WEATHER: Ptly Clay		
		NOTICE:	PRIORITY:	High
PROJECT:	23421526 - The Estate at (Costa Del Mar		
CONTRACTOR:			PHONE:	
SITE CONTACT				858-277-0441
OWNER:	Perl Family Trust			
PERMIT NUMBER	AAG	JRK URDER 23421526		
ADDRESS:	Arroyo Sorrento PI			
LOCATION:	Arroyo Sorrento Pl			-
SITE STATUS:	Grading			
CORRECTIVE ACTIONS:	Existing BMP adequately may BMP inadequate, adjustment Maintain SWPP Documents Improve Erosion Control BM Improve Sediment Control BM Improve Perimeter Control Emprove Materials Handling Maintain Street Sweeping Maintain Construction Access	ts needed IP BMP BMP		
COMMENTS	S:			
A meeting was held to go o	ver the BMPs at this location. The	perimeter silt fence was be	eing repaired	and they

A meeting was held to go over the BMPs at this location. The perimeter silt fence was being repaired and they began to replace the old gravel bags. The contractor was instructed to cover up the remaining exposed slopes and fix the construction entrance.



STORM WATER POLLUTION PREVENTION INSPECTION

Public Works - Engineering and Capital Projects Field Engineering (858) 627-3200

DATE: 10/6/2013 5:00:00 PM

NAME: Bowers, Grant

WEATHER: Ptly Cldy

	WEAT	Puy Clay		
	NOT	ICE:	PRIORITY:	High
PROJECT:	23421526 - The Estate at Costa D	Del Mar		
CONTRACTOR:	.,		PHONE:	
SITE CONTACT	Myles Cooper		PHONE:	858-277-0441
OWNER:	Perl Family Trust			
PERMIT NUMBER	WORK OR	DER 23421526		-
ADDRESS:	Arroyo Sorrento PI			
LOCATION:	Arroyo Sorrento Pl			
SITE STATUS:	Grading			
	Existing BMP adequately maintained	d		
		ed		
	Maintain SWPP Documents			
	Improve Erosion Control BMP			
CORRECTIVE ACTIONS:	Improve Sediment Control BMP			
	Improve Perimeter Control BMP			
	☐ Improve Materials Handling			
	☐ Maintain Street Sweeping			
	Maintain Construction Access			
COMMENTS	S:			
A routine BMP inspection v replaced and the silt fence More precausions should b	ras conducted on this day. There are still m needs maintanence in some areas. The cor e taken in	ultiple broken gravenstruction entrance	el bags that h needs impro	naven't been evement.
FE-SWPP-IN-030812				

ATTACHMENT #2

Estates at Costa Del Mar WDID 9 37C321980



THE CITY OF SAN DIEGO

October 9, 2013

Perl Family Trust P.O. Box 5054 Beverly Hills, CA 90210

To Whom It May Concern:

Subject:

Estates at Costa Del Mar; Drawing# 32617-D, WO# 421526 - Notice of

Inadequate BMP's

This letter is to inform you that the current BMP's in place for The Estates at Costa Del Mar, located on 11650 Arroyo Sorrento Place are not in compliance with the State Construction General Permit (CGP), Order No. 2009-0009-DWQ, the Municipal Storm Water Permit Order No. R-2007-0001, the Standard Specifications for Public Works Sections 7-8.1, 7-8.6.1, 7-8.6.3 and 801, and the San Diego Municipal Code Section 43.03.

The current conditions of the subject project has a high risk of sediment onsite being carried into the street and surrounding canyon. More work is needed to bring the site up to the standards required from your permit.

Non compliance of BMP's to the maximum extent practical may result in an enforcement action by the City and/or the Regional Water Quality Control Board. This may include correction notices, violation notices, fines, stop work orders and/or occupancy holds.

Sincerely,

Grant Bowers,

Resident Engineer

P.S. Due to past letters being returned from the address provided from the plans this letter has been sent to you. If you're not the project manager of the subject project, please provide a current address of the responsible party.

cc: Grant Bowers, Resident Engineer, Field Engineering Division, M.S. 18 Fahmy Rekani, Area Supervisor, Field Engineering Division, M.S. 18

ATTACHMENT #3

Estates at Costa Del Mar WDID 9 37C321980



THE CITY OF SAN DIEGO

January 17, 2014

Myles Cooper 8369 Vickers St., St. C San Diego, CA 92110

To Whom It May Concern:

Subject:

Estates at Costa Del Mar; Drawing# 32617-D, WO# 421526 - Notice of

Inadequate BMP's

This letter is to inform you that the BMP's in place for The Estates at Costa Del Mar, located on 11650 Arroyo Sorrento Place are still not in compliance with the State Construction General Permit (CGP), Order No. 2009-0009-DWQ, the Municipal Storm Water Permit Order No. R-2007-0001, the Standard Specifications for Public Works Sections 7-8.1, 7-8.6.1, 7-8.6.3 and 801, and the San Diego Municipal Code Section 43.03.

Due to continued negligence of proper BMP practices and only partial compliance to suggested corrections, further action will be taken against this project. The current conditions of the subject project continue to have a high risk of sediment onsite being carried into the street and surrounding canyon. More work is needed to bring the site up to the standards required by your permit. If proper BMPs are not installed by Wednesday, January 29, 2014 then the bonding company will be contacted to enforce the laws prevailing over this project.

Sincerely,

Fahmy Rekani

Area Supervising Engineer Field Engineering Division

P.S. Due to past letters being returned from the address provided from the plans this letter has been sent to you. If you're not the project manager of the subject project, please provide a current address of the responsible party.


cc: George Qsar, Senior Civil Engineer, Public Works/Field Division, M.S.18
Grant Bowers, Resident Engineer, Public Works/Field Engineering Division, M.S. 18
Julie Ballesteros, Senior Civil Engineer, Development Services Dept., M.S. 501

ATTACHMENT #4

Estates at Costa Del Mar WDID 9 37C321980

Photos taken Friday, January 24th, 2014









Photos taken Friday, January 24th,2014

