

Attachment C

Attachment C – Aerial Photo 1971 and 2 June 2009 Photos

 <p>This is an aerial photograph from 1971 showing a landscape with several mine sites. Labels with arrows point to: Mine Excavation (top center), Central Mine (top right), West End Mine (left), Manzanita Mine (right), Cherry Hill Mine (bottom center), and Empire Mine (bottom right). A winding creek, Sulphur Creek, flows through the area.</p>	<p><b>Photo 1</b> This is aerial photo taken in April 1971 and was obtain from the County of Colusa. This photo shows earth moving or excavation at Manzanita and Central Mines, and excavation directly west of Central Mine. Also note directly south of Manzanita Mine, Sulphur Creek has at least been partially dammed. Several roads cross Sulphur Creek.</p>
 <p>A photograph showing a large, conical pile of brown, loose mining waste rock on a hillside. A dirt path or road leads up the slope. The date '06-02-09' is printed in the bottom right corner.</p>	<p>This picture shows a mining waste rock pile and one of the portals at the West End Mine. The waste rock pile is very loose material and is susceptible to slope sliding and erosion. Sulphur Creek is between the photographer and the waste pile. Photo was taken by Victor Izzo.</p>
 <p>A close-up photograph of angular, reddish-brown rock fragments on a creek bank. The date '06-02-09' is printed in the bottom right corner.</p>	<p>This is a picture of angular rock in the bank of Sulphur Creek. This appears to be mining waste rock because it is not typical stream flood plain deposit. This picture was taken directly south of Manzanita Mine. Photo was taken by Jeff Huggins</p>