

Rebuttal Evidence List			
Exhibit No.	Document Date	Document	Filename
35	11-Apr-1997	Design Report and Construction Documents. DM-9 and DM-11. B&J Drop Box Sanitary Landfill	Exhibit 35.pdf
36	17-Feb-1999	Design Report and Construction Documents. DM-11.2. B&J Drop Box Sanitary Landfill	Exhibit 36.pdf
37	1-Aug-2000	Design Report and Construction Documents. Disposal Module 5.1. B&J Sanitary Landfill	Exhibit 37.pdf
38	16-May-2003	DM-4.1 Base Liner Design Report and Construction Documents. Norcal Waste Systems Hay Road Landfill	Exhibit 38.pdf
39	24-Feb-2004	DM-5.2 Base Liner Design Report and Construction Documents. Norcal Waste Systems Hay Road Landfill	Exhibit 39.pdf
40	8-Sep-2004	Construction Quality Assurance Report. Disposal Module 5.2 Liner System. Norcal Waste Systems Hay Road Landfill	Exhibit 40.pdf
41	3-Apr-2006	DM4.2 Base Liner Design Report and Construction Documents. Norcal Waste Systems Hay Road Landfill	Exhibit 41.pdf
42	6-Sep-2006	Report of Construction Quality Control Disposal Module 4.2 Liner System. Norcal Waste Systems Hay Road Landfill	Exhibit 42.pdf
43	4-May-2007	Board Order No. R5-2007-0047, Waste Discharge Requirements for Western Placer Waste Management Authority, Western Regional Sanitary Landfill	Exhibit 43.pfd
44	30-Jul-2007	Joint Technical Document, Norcal Waste Systems, Hay Road Landfill	Exhibit 44.pdf
45	3-Mar-2008	DM-3.1 Base Liner Design Report and Construction Documents. Norcal Waste Systems Hay Road Landfill	Exhibit 45.pdf
46	1-Sep-2008	Construction Quality Assurance Report Disposal Module 3.1 Liner System. Norcal Waste Systems Hay Road Landfill	Exhibit 46.pdf
47	27-May-2010	Construction Quality Assurance Plan. Disposal Module 3.2 Liner System. Recology Hay Road Landfill	Exhibit 47.pdf
48	29-Jun-2010	Construction Quality Assurance Plan. Disposal Modules 3.2 & 3.3 Liner System. Recology Hay Road Landfill	Exhibit 48.pdf
49	29-Sep-2010	Construction Quality Assurance Report. Disposal Modules 3.2 & 3.3 Liner System. Recology Hay Road	Exhibit 49.pdf
50	12-Aug-2011	Notice of Violation, Site Inspection of Yuba Sutter Disposal, Inc., Landfill, Yuba County	Exhibit 50.pdf
51	14-Jun-2012	Construction Specifications Disposal Module 6 Base Liner System. Recology Hay Road	Exhibit 51.pdf
52	23-Aug-2012	Construction Quality Assurance Report. Disposal Module 6.1 Liner System. Recology Hay Road	Exhibit 52.pdf
53	6-Mar-2013	Inspection Report, Recology Yuba-Sutter Landfill, Marysville, Yuba County	Exhibit 53.pdf
54	29-Aug-2013	Cleanup and Abatement Order R5-2013-0704 , Recology Yuba-Sutter	Exhibit 54.pdf
55	10-Sep-2013	Construction Quality Assurance Report. Disposal Modules 4.3 & 6.2 Liner System. Recology Hay Road	Exhibit 55.pdf
56	4-Sep-2014	Inspection Report, Western Regional Sanitary Landfill, Placer County	Exhibit 56.pdf
57	11-Sep-2014	Notice of Violation and Inspection Report, Recology Hay Road, Solano County	Exhibit 57.pdf
58	11-Sep-2014	Attachment A to 3 September 2014 Inspection Report, Recology Hay Road, Solano County	Exhibit 58.MOV
		<i>Pursuant to the Hearing Procedures governing this matter, California Code of Regulations, title 23, section 648.3, and the 1 August 2013 Ruling on Objections to the Hearing Procedures, the following Exhibits are hereby submitted by reference.</i>	