

HOFSTETTER CAO R1-2010 0089
APPENDIX A



Photo 1 - Cut Made Through Bank of Russian River Down to Waterline



Photo 2 - Spoils from Cut Spread Over Large Portion of Yard



Photo 3 - Brush and Soil Pushed Over Bank of Russian River



Photo 4 - Soil Pushed Over Bank of Russian River