

| Station Name | Station Code | Sample Date | Collection Time | Group | Discharge, cfs | pH | SC, 700 μ S/cm | Comments |
|---------------------------------|--------------|-------------|-----------------|-----------------------------------|----------------|------|--------------------|---|
| Berenda Slough along Ave 18 1/2 | 545XSAAE | 11/13/2012 | 11:54 | Fall2, Management Plan Monitoring | NA | | | November Management Plan Monitoring for copper. Dry site, no samples collected. |
| Deadman Creek @ Hwy 59 | 535DMCAHF | 11/13/2012 | 10:50 | Fall2 | 1.09 | | | |
| Highline Canal @ Lombardy Rd | 535XHCALR | 11/13/2012 | 13:10 | Fall2, Non-Contiguous | 0 | 9.24 | | Non-contiguous waterbody. Discharge recorded as zero due to non-contiguous waterbody. |
| Levee Drain @ Carpenter Rd | 535XLDACR | 11/13/2012 | 11:00 | Fall2 | 0.2 | | 1810 | |
| McCoy Lateral @ Hwy 140 | 535XMLAHO | 11/13/2012 | 9:57 | Fall2 | NA | | | Dry site, no samples collected. |
| Rodden Creek @ Rodden Rd | 535XRCARD | 11/13/2012 | 8:57 | Fall2 | NA | | | Dry site, no samples collected. |

NA - Not applicable; see comments.