


## City of Orinda Trash Hot Spot Submittal

**Number of Hot Spots Required:** 1  
**Water Board Region:** Region 2: San Francisco

### Hot Spot 01:

**Site ID#:** ORI-01  
**Lat:** 37 ° 52' 54.6"  
**Long:** 122° 11' 12.5"  
**Watershed:** San Pablo  
**Waterbody:** San Pablo Creek  
 City ROW for Camino Pablo  
 Road and private property  
 (APNs 265-170-007 and  
 265-170-014)  
**Ownership:** City of Orinda and  
private  
**Jurisdiction(s):** private

**Map:**



Types of Trash Removed:	Percentage:
Plastic bags	5%
Bottles (plastic or glass)	1%
Aluminum cans	1%
Styrofoam (pieces or pellets)	1%
Other plastic products	5%
Paper and cardboard	10%
Cigarette butts	1%
Metal products	1%
Biohazards	1%
Construction debris	10%
Large items	56%
Miscellaneous items	5%
Fabric and cloth	1%
Glass pieces	1%
Gold or tennis balls	1%

### Volume of Trash Removed During Cleanup:

Size of trash bag (in gallons): 0.44 cubic yards  
 Total # of bags: 4  
 OR  
 Total Cubic Yards: 1.76

### Potential Trash Pathways/Sources:

litter, illegal dumping

### Photodocumentation (Before Cleanup)

ORI01\_100416\_AB\_mid-1

ORI01\_100416\_BC\_mid-1

### Photodocumentation (After Cleanup)

ORI01\_100417\_AB\_mid-2

ORI01\_100417\_BC\_mid-2

ORI01\_100416\_CD\_mid-1

ORI01\_100416\_DE\_midfromleftbank-1

ORI01\_100416\_F\_midfromleftbank\_1

ORI01\_100416\_FE\_mid-1 (City was unable to  
take photo at the EF transect because it was  
unsafe due to the dense vegetation)

ORI01\_100416\_FG\_mid-1

ORI01\_100416\_GH\_mid-1

ORI01\_100417\_CD\_mid-2

ORI01\_100417\_DE\_midfromleftbank-2

ORI01\_100419\_FE\_mid\_2 (City was unable  
to take photo at the EF transect because it  
was unsafe due to the dense vegetation)

ORI01\_100417\_FG\_mid\_2

ORI01\_100417\_GH\_mid\_2