

Figure B-17a

Summary Analytical Results
Inorganics Detected Above Screening Levels
Former Ponds and Pads Subarea

Final Remedial Investigation Report
Casmalia Resources Superfund Site
January 2011