

Extraction Well Hydrographs

Well Group E1

Final Remedial Investigation Report

Casmalia Resources Superfund Site

Casmalia, California

Figure:

F1-E1

DRAWN	JOB NUMBER	CHECKED	APPROVED	DATE
NAM	4088097619	WJF	WBC	1/2011