

Well RP-20B Hygrographs
Continuous Data Logger
Final Remedial Investigation Report
Casmalia Resources Superfund Site
Casmalia, California

Figure:

F1-T5

DRAWN	JOB NUMBER	CHECKED	APPROVED	DATE
NAM	4088097619	WJF	WBC	1/2011