


Well RP-54C Hygrographs
Continuous Data Logger
Final Remedial Investigation Report
Casmalia Resources Superfund Site
Casmalia, California

Figure:

**F1-T9**

| DRAWN | JOB NUMBER | CHECKED | APPROVED | DATE |
|---|---|---|---|---|
| NAM | 4088097619 | WJF | WBC | 1/2011 |