

FigureF3-30_L7.mxd

Hydraulic Conductivity Points and Polygons for Layer 7

Final Remedial Investigation Report
Casmalia Resources Superfund Site
Casmalia, California

FIGURE

F3-30

DRAWN	JOB NUMBER	APPROVED	CHECKED	DATE	REVISED DATE
TFC	0020784 00.01	BB		01/2011	