



* Approximate elevation based on angle borings drilled in April, 2001 and described in "Report of Findings", Pesticide/Solvent Landfill Low Area and Gallery well / Clay Barrier Investigation (Harding ESE, July 31, 2001). Uncertainty still remains regarding the exact location of the Clay Barrier.

- LEGEND:**
- DTP Depth to LNAPL
 - DTW Depth to Groundwater
 - DTD Depth to DNAPL
 - LNAPL Zone (March 2010)
 - DNAPL Zone (Oct 6, 2005 Conditions)

See Figure F-36 for cross-section locations

East-West Cross Section P/S Landfill - Gallery Well Area
Final Remedial Investigation Report
 Casmalia Resources Superfund Site
 Casmalia, California

DRAWN PCB	JOB NUMBER 4088097619	APPROVED NAM	DATE 1/2011	REVISED DATE
--------------	--------------------------	-----------------	----------------	--------------

Plotted: 01-10-2011 2:23 PM By: pcboudreau
 Path: P:\4088\097619_Casmalia_RI_Revision\CAD_4088097619014.dwg