

Seismic Line Location Map



EXPLANATION

Upper/Lower HSU Contact as Interpreted From Borehole and CPT Data

FIG-L-14.DWG 40.0
2010-12-13,11:07

NO.	DATE	REVISIONS	BY	CHK

DRAWN: Ntm	PROJECT NO: 4088097619		
ENGINEER:	SCALE: Check Graphic		
CHECKED: NAM	APPROVED: WJF		
DATE: 1/2011	DATE: 1/2011		

Final Remedial Investigation Report

Casmalia Resources Superfund Site
Casmalia, California

Seismic Refraction Results
Production Survey Line SL-6

FIGURE **L-14**
SHEET: OF
REVISION NUMBER: 0
DATE: January 2011