

Visible Emissions Surveillance Jack L. Spence Lime Removal, Woodland

Date	Time	Temp./Winds	Comments
4-2-12	10:30-10:50am	57F, NNW 5-8	Earthmovers and bull dozers were parked on facility. No activity other than one (1) water truck actively watering down the hill between site and Nelson Ranch. Water was also applied to lime pile in middle of property. No visible emission observed. No violations reported.
4-5-12	10:00-10:15am	55F, NNW 5 mph	No activity at site. No visible emissions. No track-out at entrance. No violations reported.
4-10-12	10:00 – 10:20am	60F, Calm, drizzle	Lots of activity at site. Met with Scott Cooper who is in charge of lime removal. The berm between the properties is no totally removed and lime is in large pile in middle of property. Water trucks were active. No visible emissions. No track-out.
4-19 12	9:30 – 9:45am	60°F NNW 3-5 mph	No activity at site. No visible emissions. No track-out at entrance.
4-26-12	1:40 – 1:55pm	62°F SW 14 mph gusts to 20mph	No activity at site. No visible emissions. No track-out at entrance.
05-01-12	11:00 – 11:20am	71°F NNW 5-8 mph	No activity at site. No visible emissions. No track-out at entrance.
5-21-12	11:15-11:25am	80°F SSW 5-7 mph	No activity at site. No visible emissions. No track-out at entrance.
6-4-12	11:00 – 11:10am	65°F SSW 5-8 mph	No activity at site. No visible emissions. No track-out at entrance.
6-15-12	8:00 – 8:25am	70°F NNW 1-5 mph	Site was active at time of surveillance. Spoke with water truck driver who stated that no hauling of lime to take place today only movement of lime from eastside to center of property. Two (2) water trucks actively watering haul roads and piles. Two(2) bull dozers and two(2) earth movers active. Visible emissions <20% opacity throughout property. No track out at entrance. Conditions of dust plan were met at time of inspection. No violations reported.
6-21-12	12:15 – 12:30pm	79°F SSW 6-10 gusts to 13 mph	Site was active at time of surveillance. Only movement of lime from eastside to center of property. No product removed. Two (2) water trucks actively watering haul roads and piles. Two (2) bull dozers and two(2) earth movers active. Visible emissions <20% opacity throughout property. No track out at entrance. Conditions of dust plan were met at time of

			inspection. No violations reported Note: Farm field just south of entrance to Nelson Ranch was being harvested. Dust was blowing across CR18C directly into Nelson ranch. Also, field to south and north of Nelson ranch had crop activity and blowing dust.
6-26-12	10:30 – 10:45am	68°F N 1-5 mph	Site was active. Only movement of lime from north side to center of property. Two (2) water trucks were active. Haul road (Rd 100B) was watered at time of surveillance. Bull dozer and earth mover were active. No material removed from property at time of surveillance. No violations issued at time of surveillance.
6-28-12	10:20 – 10:30am	79°F SSW 5 mph	Only one water truck was active on site watering down haul roads and lime pile. All other equipment including bull dozers and earth movers were idle and parked along one haul road. One bull dozer was loaded onto a trailer. No product was removed from site. No other activity. No visible emissions observed at time of surveillance.

Permit P-52-89(t1)

Scott Cooper, Manager XXXXXXXXXX

C:\Documents and Settings\bdoivi.YSAQMD\My Documents\Jack L. Spence Emission Complaints.docx