

RECEIVED

JUL 08 2015

FWQCB-CVR
FRESNO, CALIF.

Petro Resources, Inc.

1730 Art Street
Bakersfield, Ca 93312
661.213.4118

July 6, 2015

Certified: 7013 2250 0001 2099 6993

Mr. Ronald Holcomb
Central Valley Regional Water Quality Control Board
1685 E. Street
Fresno, CA 93706


Re: Transmittal -
Technical Reports - Directive Pursuant to Section 13267
Mahl Pond - Section 21, T30S, R29E
Bishop Pond - Section 22, T27S, R82E
Kern County

Dear Mr. Holcomb:

Petro Resources, Inc. is submitting the referenced Technical Reports pursuant to the Central Valley Regional Water Quality Board's (Board) Order dated April 21, 2015.

I trust that these reports are satisfactory and meets the Board's requirements. We look forward to your favorable response.

Sincerely,


Thomas W. Ladd
California Professional Geologist # 3568

Cc. File: Petro Resources, Inc.

Enclosures: Technical Reports
Mahl Lease
Bishop Lease

RECEIVED

JUL 08 2015

TECHNICAL REPORT
CALIFORNIA WATER CODE DIRECTIVE PURSUANT TO SECTION 13267
REGARDING PRODUCED WATER DISCHARGE
PETRO RESOURCES, INC.
MAHL LEASE
EDISON OIL FIELD - SECTION 21, T30S, R29E, MDB&M
July 6, 2015

Petro Resources (PRI) is the operator of oil wells located on the Mahl Lease in Section 21, T30S, R29E, Edison Oil Field, Kern County. PRI is submitting the following Technical Report pursuant to Central Valley Regional Water Quality Board's (Board) Order dated April 21, 2015.

Technical Report

A. Identification of any discharges of oil field produced waters to land, including but not limited to ponds, since April of 2014 that are not listed in Attachment A, or if there are no discharges then indicate so;

The Mahl lease has 1 pond historically used for emergency containment of production water. Since April of 2014, there has been no discharges of oil field produced water to land, to this pond or to any other land not listed in Attachment A of the Order. There are no other ponds or discharges of produced waters to land.

B. Collect representative samples of the fluid within each of the ponds. Samples must be analyzed in accordance with the water quality analysis and reporting requirements contained in Attachment B to this Order;

There is no fluid present in the pond. There are no discharges to the pond.

C. All available information for each pond(s), including dimensions (i.e., length, width, and depth), latitude and longitude, Assessor's parcel Numbers of the lease, duration of the discharge (in months), and a history of the volume of the wastewater discharge per year.

The available information of each pond is presented in the following table.

TABLE
POND DETAILS

Pond 1

APN	178-150-23-00-7
Latitude	35.305719
Longitude	-118.863154
Length	40
Width	20
Depth	15
Discharge	0

There are no discharges to the pond.

D. A location map that includes the following information:

- i. All ponds at the Facility
- ii. Include the boundary lines for all leases at the Facility, and
- iii. Legend with the name of the surface impoundments(s).

LOCATION MAPS: The following two figures depict the PRI Mahl lease and facility schematic of the pond.




Figure 1. Mahl lease




Figure 2. Facility Aerial View

CERTIFICATION STATEMENT

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Thomas W. Ladd

 Thomas W. Ladd
 California Professional Geologist #3568