

**Appendix I.3 – Attachment 2: Photographic Record
of Exempt Earthen Channel Segments**

GEOSYNTEC CONSULTANTS Photographic Record		
Client: South Orange County Copermittees		Project Number: SW0266
Site Name: Aliso Creek		Site Location: Orange County, CA
Photograph 1		
Date: 7 September 2016		
Direction:		
Comments:		
Photograph 2		
Date: 7 September 2016		
Direction:		
Comments:		

33.51051, -117.75286, -32.0m, 12°
 Sep 7, 2016 11:24:52 AM

33.51074, -117.75259, -54.0m, 339°
 Sep 7, 2016 11:31:42 AM

GEOSYNTEC CONSULTANTS
Photographic Record



Client: South Orange County Copermittees

Project Number: SW0266

Site Name: Aliso Creek

Site Location: Orange County, CA

Photograph 3

Date: 7 September 2016

Direction:

Comments:



33.51102, -117.7526, -27.0m, 186°
 Sep 7, 2016 11:34:30 AM

Photograph 4

Date: 7 September 2016

Direction:

Comments:



33.51101, -117.75255, -35.0m, 262°
 Sep 7, 2016 11:34:37 AM

GEOSYNTEC CONSULTANTS Photographic Record		
Client: South Orange County Copermittees		Project Number: SW0266
Site Name: Aliso Creek		Site Location: Orange County, CA
Photograph 5		
Date: 7 September 2016		
Direction:		
Comments:		
Photograph 6		
Date: 7 September 2016		
Direction:		
Comments:		

GEOSYNTEC CONSULTANTS Photographic Record		
Client: South Orange County Copermittees		Project Number: SW0266
Site Name: Laguna Canyon		Site Location: Orange County, CA
Photograph 1		
Date: 7 September 2016		
Direction:		
Comments:		
Photograph 2		
Date: 7 September 2016		
Direction:		
Comments:		

GEOSYNTEC CONSULTANTS Photographic Record		
Client: South Orange County Copermittees		Project Number: SW0266
Site Name: Laguna Canyon		Site Location: Orange County, CA
Photograph 3		
Date: 7 September 2016		
Direction:		
Comments:		
Photograph 4		
Date: 7 September 2016		
Direction:		
Comments:		

GEOSYNTEC CONSULTANTS Photographic Record		
Client: South Orange County Copermittees		Project Number: SW0266
Site Name: Laguna Canyon		Site Location: Orange County, CA
Photograph 5		
Date: 7 September 2016		
Direction:		
Comments:		
Photograph 6		
Date: 7 September 2016		
Direction:		
Comments:		

33.57335, -117.76267, 282°
 Sep 7, 2016 9:54:20 AM

33.57432, -117.76263, 170°
 Sep 7, 2016 10:09:45 AM

GEOSYNTEC CONSULTANTS
Photographic Record

Geosyntec
consultants

Client: South Orange County Copermittees **Project Number: SW0266**


Site Name: Laguna Canyon **Site Location: Orange County, CA**

Photograph 7

Date: 7 September 2016

Direction:

Comments:



Photograph 8

Date: 7 September 2016

Direction:

Comments:



GEOSYNTEC CONSULTANTS Photographic Record		
Client: South Orange County Copermittees		Project Number: SW0266
Site Name: Laguna Canyon		Site Location: Orange County, CA
Photograph 9		
Date: 7 September 2016		
Direction:		
Comments:		
Photograph 10		
Date: 7 September 2016		
Direction:		
Comments:		

Appendix I.3 – Attachment 2: Photographic Record of Exempt Earthen Channel Segments

GEOSYNTEC CONSULTANTS Photographic Record		
Client: South Orange County Copermittees		Project Number: SW0266
Site Name: North Creek		Site Location: Orange County, CA
Photograph 1		
Date: 7 September 2016		
Direction:		
Comments:		
Photograph 2		
Date: 7 September 2016		
Direction:		
Comments:		

33.46206, -117.68921, -33.0m, 3°
 Sep 7, 2016 12:32:37 PM

33.46206, -117.6892, -34.0m, 162°
 Sep 7, 2016 12:32:46 PM

GEOSYNTEC CONSULTANTS Photographic Record		
Client: South Orange County Copermittees		Project Number: SW0266
Site Name: North Creek		Site Location: Orange County, CA
Photograph 3		
Date: 7 September 2016		
Direction:		
Comments:		
Photograph 4		
Date: 7 September 2016		
Direction:		
Comments:		

33.46206, -117.6892, -34.0m, 7°
 Sep 7, 2016 12:32:51 PM

33.46207, -117.68921, -34.0m, 108°
 Sep 7, 2016 12:33:47 PM

GEOSYNTEC CONSULTANTS Photographic Record		
Client: South Orange County Copermittees		Project Number: SW0266
Site Name: North Creek		Site Location: Orange County, CA
Photograph 5		
Date: 7 September 2016		
Direction:		
Comments:		
		33.4625, -117.6891, -40.0m, 113° Sep 7, 2016 12:35:47 PM
Photograph 6		
Date: 7 September 2016		
Direction:		
Comments:		
		33.46284, -117.68886, -49.0m, 170° Sep 7, 2016 12:36:26 PM

GEOSYNTEC CONSULTANTS Photographic Record		
Client: South Orange County Copermittees		Project Number: SW0266
Site Name: North Creek		Site Location: Orange County, CA
Photograph 7		
Date: 7 September 2016		
Direction:		
Comments:		
Photograph 8		
Date: 7 September 2016		
Direction:		
Comments:		

GEOSYNTEC CONSULTANTS		
Photographic Record		
Client: South Orange County Copermittees		Project Number: SW0266
Site Name: North Creek		Site Location: Orange County, CA
Photograph 9		
Date: 7 September 2016		
Direction:		
Comments:		

GEOSYNTEC CONSULTANTS Photographic Record		
Client: South Orange County Copermittees		Project Number: SW0266
Site Name: Segunda Deschecha		Site Location: Orange County, CA
Photograph 1		
Date: 7 September 2016		
Direction:		
Comments:		
		33.40829, -117.599, 177° Sep 7, 2016 4:01:24 PM
Photograph 2		
Date: 7 September 2016		
Direction:		
Comments:		
		33.43886, -117.61998, 205° Sep 7, 2016 4:08:25 PM

GEOSYNTEC CONSULTANTS Photographic Record		
Client: South Orange County Copermittees		Project Number: SW0266
Site Name: Segunda Deschecha		Site Location: Orange County, CA
Photograph 3		
Date: 7 September 2016		
Direction:		
Comments:		
Photograph 4		
Date: 7 September 2016		
Direction:		
Comments:		

33.4426, -117.61676, -50.0m, 215°
Sep 7, 2016 4:20:17 PM

33.44171, -117.61762, -14.0m, 192°
Sep 7, 2016 4:26:08 PM

GEOSYNTEC CONSULTANTS Photographic Record		
Client: South Orange County Copermittees		Project Number: SW0266
Site Name: Segunda Deschecha		Site Location: Orange County, CA
Photograph 5	 <p style="text-align: right; font-size: small;">33.44162, -117.61779, -4.0m, 57° Sep 7, 2016 4:29:29 PM</p>	
Date: 7 September 2016		
Direction:		
Comments:		
Photograph 6		
Date: 7 September 2016		
Direction:		
Comments:		

GEOSYNTEC CONSULTANTS Photographic Record		
Client: South Orange County Copermittees		Project Number: SW0266
Site Name: Segunda Deschecha		Site Location: Orange County, CA
Photograph 7		
Date: 7 September 2016		
Direction:		
Comments:		
Photograph 8		
Date: 7 September 2016		
Direction:		
Comments:		

GEOSYNTEC CONSULTANTS Photographic Record		
Client: South Orange County Copermittees		Project Number: SW0266
Site Name: Trafalgar Channel		Site Location: Orange County, CA
Photograph 1		
Date: 7 September 2016		
Direction:		
Comments:		
Photograph 2		
Date: 7 September 2016		
Direction:		
Comments:		

33.41781, -117.61796, -21.0m, 13°
 Sep 7, 2016 5:12:08 PM

33.41764, -117.61783, -15.0m, 228°
 Sep 7, 2016 5:17:34 PM

GEOSYNTEC CONSULTANTS
Photographic Record



Client: South Orange County Copermittees

Project Number: SW0266

Site Name: Trafalgar Channel

Site Location: Orange County, CA

Photograph 3

Date: 7 September 2016

Direction:

Comments:



Photograph 4

Date: 7 September 2016

Direction:

Comments:



GEOSYNTEC CONSULTANTS Photographic Record		
Client: South Orange County Copermittees		Project Number: SW0266
Site Name: Trafalgar Channel		Site Location: Orange County, CA
Photograph 5		
Date: 7 September 2016		
Direction:		
Comments:		
Photograph 6		
Date: 7 September 2016		
Direction:		
Comments:		