

TABLE 4
 SUMMARY OF GROUND-WATER ANALYSES
 DETECTED VOLATILE ORGANIC COMPOUNDS
 San Marcos (Old) Landfill

WELL NUMBER	DATE OF SAMPLING	trans-1,2-Di-chloroethene ug/L	1,4-Dichloro-benzene ug/L	Vinyl chloride ug/L	Trichloro-ethene ug/L	Tetrachloro-ethene ug/L	Chloroform ug/L	Bromodichloro-methane ug/L	Dibromo-chloromethane ug/L	Bromoform ug/L
SM-1	01/07/91 04/11/91	ND ND	ND 1.7	7 8.5	0.9 0.8	1 1.3	ND ND	ND ND	ND ND	ND ND
SM-2	01/07/91 04/11/91	1 ND	1.8 2.3	ND ND	ND ND	ND ND	ND ND	ND ND	ND ND	ND ND
SM-3	01/07/91 04/11/91	0.9 0.6	3.4 2.6	12 9	1.6 0.9	ND ND	ND ND	ND ND	ND ND	ND ND
SM-4	01/07/91 04/11/91	ND ND	ND 0.9	ND ND	ND ND	ND ND	ND ND	ND ND	ND ND	ND ND
Field Blank	01/07/91 04/11/91	ND ND	ND ND	ND ND	ND ND	ND ND	ND 1.5	ND 2.7	ND 2.6	ND 0.6
Trip Blank	01/07/91 04/11/91	ND ND	ND ND	ND ND	ND ND	ND ND	ND ND	ND ND	ND ND	ND ND
Drinking Water Std.		10(a)	5(a)	0.5(a)	5(a)	5(a)	100(a)	100(a)	100(a)	100(a)
Detection Limit		0.5	0.5	0.5	0.5	0.5	0.5	0.5	0.5	0.5

(a) Primary Drinking Water Standard, Title 22, California Code of Regulations.
 ND-Not detected.
 24 additional compounds were not detected using method 601/BTEX testing program.