

California Regional Water Quality Control Board

San Diego Region

Over 50 Years Serving San Diego, Orange, and Riverside Counties
Recipient of the 2004 Environmental Award for Outstanding Achievement from USEPA



9174 Sky Park Court, Suite 100, San Diego, California 92123-4353 (858) 467-2952 • Fax (858) 571-6972 http:// www.waterboards.ca.gov/sandiego

April 10, 2008

Mr. K.A. Khan
Environmental Engineering Division
AC/S Environmental Security
U.S. Marine Corps Base
P.O. Box 555008
Camp Pendleton, CA 92055-5008

In reply refer to: Place ID – 248636

Dear Mr. K.A. Khan:

SUBJECT: REVIEW OF MONITORING REPORTS FOR ORDER NO. 98-04, WASTE DISCHARGE REQUIREMENTS FOR SEWAGE TREATMENT PLANT NO. 9 (LAS PULGAS), MARINE CORPS BASE CAMP PENDLETON


The Regional Board has completed review of the following monthly monitoring reports covering the reporting period from January 2007 through June 2007:

MONITORING REPORTS REVIEWED FOR ORDER NO. 98-04			
FREQENCY	PERIOD	REPORT DATE	DATE RECEIVED
Monthly:	July 2007	August 27, 2007	August 30, 2007
	August 2007	September 24, 2007	September 27, 2007
	September 2007	October 29, 2007	October 30, 2007
	October 2007	November 27, 2007	November 30, 2007
	November 2007	December 19, 2007	December 28, 2007
	December 2007	January 29, 2008	January 30, 2008
	January 2008	February 28, 2008	February 29, 2008
	February 2008	March 27, 2008	March 28, 2008
Annual:	2007	January 29, 2008	January 30, 2008

The following section contains the Regional Board violation identified from information provided in the monitoring reports cited above:

- Violations of Monitoring and Reporting Program, Section B.1
 - November 2007 Monthly Monitoring Report: The Monitoring and Reporting Program requires that analyses for BOD and total suspended solids be performed on composite samples. On November 14, 2007, BOD and total suspended solids analysis were reported for a "grab sample."

California Environmental Protection Agency



Mr. K.A. Khan, Environmental Security Order No. 98-04: STP Plant No. 9 (Las Pulgas) U.S. Marine Corps Base, Camp Pendleton

Pursuant to the CWC, the violations noted are subject to additional enforcement action(s) by the Regional Board including time schedule orders, cease and desist orders, cleanup and abatement orders, administrative civil liability, referral to the district attorney for criminal prosecution, or referral to the attorney general.

The heading portion of this letter includes a Regional Board code number noted after "In reply refer to:" In order to assist us in the processing of your correspondence please include this code number in the heading or subject line portion of all correspondence and reports to the Regional Board pertaining to this matter.

If you have any questions regarding the above, please contact Mr. Robert Pierce at (858) 627-3935 or rpierce@waterboards.ca.gov.

Respectfully.

JOHN R. ODERMATT, Senior Engineering Geologist

Northern San Diego Groundwater Unit

JRO;cqc:jlc

Reg Measure -142909 Party ID - 48506 Place ID - 248636 Person ID - 99783

Violations:

(1) 744984

Enforcement:

(SEL) 343725