



San Diego Regional Water Quality Control Board

November 6, 2014

Mr. Brett Hurst Hanson Aggregates – West Region P.O. Box 639069 San Diego, CA 92163 In reply refer to: 240909:RMitchell

Subject:

January-December 2011 Annual Monitoring Report, for Hanson Aggregates

Miramar Plant, San Diego, San Diego County

Mr. Hurst:

The above referenced document (2011 Annual Monitoring Report), was received by the California Regional Water Quality Control Board, San Diego Region (San Diego Water Board) on January 27, 2012. The 2011 Annual Monitoring Report is an annual assessment of the Hanson Aggregates Miramar Plant to evaluate groundwater and other on-site conditions to determine potential environmental impacts associated with the discharge of wastes to land.

The San Diego Water Board has reviewed the 2011 Annual Monitoring Report submitted in accordance with General Order No. 94-63 (the Order),¹ and has the following comment:

1. Pond Monthly Freeboard: The 2011 Annual Monitoring Report shows the minimum freeboard of 2 feet was not maintained during the months of March, May, August, November, and December. The San Diego Water Board acknowledges the violations of the Water Discharge Report were resulted from storm water events and unauthorized rinsing by truckers into the pond. The San Diego Water Board recognizes that Hanson Aggregates has placed a blockade to prevent any future unauthorized washing and to properly manage the pond volume to maintain a minimum freeboard of 2 feet, as specified in section B.5 of the Order.

The San Diego Water Board is implementing a Paperless Office system to reduce our paper use, increase efficiency, and provide a more effective way for our staff, the public and interested parties to view water quality documents in electronic form.

Please convert all regulatory documents, submissions, materials, and correspondence that you would normally submit to us as hard copies to a searchable Portable Document Format (PDF). Data may be submitted in Excel spreadsheets. Documents that are less than 50 MB should be emailed to SanDiego@waterboads.ca.gov. Documents that are 50 MB or larger should be transferred to a disk and mailed to the address listed below.

¹ Waste Discharge Requirements for Sim J. Harris Company Miramar Plant San Diego County. http://www.waterboards.ca.gov/sandiego/board decisions/adopted_orders/1990/94-63.pdf

California Regional Water Quality Control Board San Diego Region 2375 Northside Drive, Ste. 100 San Diego, California 92108

Please contact our office if you have any questions regarding this matter. In the subject line of any response, please include reference **240909:RMitchell**. Please contact Mr. Roger Mitchell at (619) 521-5898, or at roger.mitchell@waterboards.ca.gov if you have any questions or comments.

Respectfully,

John R. Odermatt, PG Senior Engineering Geologist Groundwater Protection Branch

holet

Tech Staff Info & Use	
Place ID	240909
Party ID	19795
Reg. Measure ID	142226