
San Diego Regional Water Quality Control Board

November 16, 2016

Mr. David Y Deem
Chief Plant Operator
Fallbrook Public Water District Plant 1
990 East Mission Road
Fallbrook, California, 92088

In reply refer to / attn:
224137:BBushnell

Subject: Review of Monitoring Reports for Order No. 91-39, Fallbrook Public Water District Plant 1

Mr. Deem


The California Regional Water Quality Control Board, San Diego Region (San Diego Water Board) has reviewed the monthly reports for January 2015 through September 2016 and the January-March 2015, April-June 2015, July-September 2015, October-December 2015, January-March 2016, April-June 2016, July-September 2016 quarterly recycled water users reports. The Fallbrook Public Water District (Discharger) submitted the monitoring reports as required by the Monitoring and Reporting Program No. 91-39.

The San Diego Water Board has the following comments on the reports referenced above.

1. On March 31, 2015 the average turbidity was reported at 2.68 NTU which exceeds the established limit for average turbidity set at 2.0 NTU.
2. During the week of August 16, 2016 through August 22, 2016 the Discharger failed to sample for Carbonaceous Biochemical Oxygen Demand (CBOD). Section B (Effluent Monitoring) of Monitoring and Reporting Program No. 91-39 requires CBOD to be sampled weekly and reported monthly.

In the subject line of any response, please include reference **224137:BBushnell**. Please contact Mr. Brandon Bushnell at 619-521-8044, or at brandon.bushnell@waterboards.ca.gov if you have any questions or comments.

Respectfully,



John R. Odermatt, P.G., Senior Engineering Geologist
Land Discharge Unit

JRO: ac: bb

Tech Staff Info & Use	
Place ID	224137
Reg. Measure ID	142623
SEL Reg. Measure ID	410160
Violation ID	1014382, 1014387