Department of Environmental Heath
Hazardous Materials Management Division
Riverside County LOP Cases

MTBE Discharges and Groundwater Detection

Period Ending June 30, 2003

Site ID	Site Name	Address	City	MTBE Discharge	MTBE GW Detection	Max MTBE GW TBE Conc.
200218249	Thatcher's Market	45140 Thatcher's Market	Aguanga	Yes	NT	
92994	El Cariso Country Store	32692 El Cariso Country Stc	Lake Elsinore	Yes	Yes	1,900.00
93232	Chevron #201241	40500 Chevron #201241	Murrieta	Yes	Yes	5,500.00
9915188	Stan's Service	41991 Stan's Service	Murrieta	Yes	ND	
200319346	Shell Murrieta	39614 Shell Murrieta	Murrieta	Yes	NT	
200016132	California Highway Patrol	27685 California Highway Pı	Temecula	Yes	Yes	1.30
200117527	Chevron #204029	31669 Chevron #204029	Temecula	Yes	Yes	43.00
200319348	Rancho Car Wash	27278 Rancho Car Wash	Temecula	Yes	ND	
96075	Honda Of Temecula	27500 Honda Of Temecula	Temecula	Yes	Yes	431.00
96259	Jefferson Street Chevron	27560 Jefferson Street Che	Temecula	Yes	Yes	76,400.00
200016646	Arco #5695	44239 Arco #5695	Temecula	Yes	Yes	4,400.00
94144	CDF Station #12	28330 CDF Station #12	Temecula	NT	NT	
200117875	Temecula Car Wash	29766 Temecula Car Wash	Temecula	Yes	NT	3.00
200118093	Texaco	29750 Texaco	Temecula	Yes	Yes	16.00
200319663	Arco #5500	41555 Arco #5500	Temecula	Yes	NT	
9915433	Inland Valley Reg Medica	36485 Inland Valley Reg Me	Wildomar	N	ND	
200319300	MWD Lake Skinner Work	33740 MWD Lake Skinner V	Winchester			
200319685	MWD Lake Skinner LS - '	33740 MWD Lake Skinner L	Winchester	N	N	
200319299	MWD Lake Skinner Work	33740 MWD Lake Skinner \	Winchester			

*Data represents highest MTBE concentrations detected, may be from prior quarters.

Number of Sites: 19

ND = Not detected
NT = Not tested
NRQ = Not required. Used for soil only cases which have not been required to install gw wells.