

# Site Photographs

Facilities Not Requiring Permit Coverage  
 San Leandro  
 Alameda County, California

Photograph Date: 2/8/2010 - 2/11/2010



2/9/10

Photograph 1 – Facility entrance sign to 1948 – 1958 Williams Street



2/9/10

Photograph 2 – Facility entrance sign to 1964 – 1976 Williams Street



2/9/10

Photograph 3 – General facility conditions at 1948 – 1958 and 1964 – 1976 Williams Street. No industrial materials, activities, or equipment exposed to storm water were observed.



2/11/10

Photograph 4 – Facility entrance sign to 2515 – 2533 Williams Street.

# Site Photographs

Facilities Not Requiring Permit Coverage  
San Leandro  
Alameda County, California

Photograph Date: 2/8/2010 - 2/11/2010



Photograph 5 – General facility conditions at 2515 – 2533 Williams Street. No industrial materials, activities, or equipment exposed to storm water were observed.



Photograph 6 – Facility entrance sign to 2535 – 2553 Williams Street.



Photograph 7 – General facility conditions at 2535 – 2553 Williams Street. No industrial materials, activities, or equipment exposed to storm water were observed.



Photograph 8 – Facility entrance sign to 1770 – 1786 Neptune Drive.

# Site Photographs

Facilities Not Requiring Permit Coverage  
San Leandro  
Alameda County, California

Photograph Date: 2/8/2010 - 2/11/2010




Photograph 9 – General facility conditions at 1770 – 1786 Neptune Drive. No industrial materials, activities, or equipment exposed to storm water were observed.



Photograph 10 – General facility conditions at 1770 – 1786 Neptune Drive. No industrial materials, activities, or equipment exposed to storm water were observed.



Photograph 11 – Facility sign for Crystal Communications, 1601 Neptune Drive.



Photograph 12 – General facility conditions for Crystal Communications. No industrial materials, activities, or equipment exposed to storm water were observed.

# Site Photographs

Facilities Not Requiring Permit Coverage  
San Leandro  
Alameda County, California

Photograph Date: 2/8/2010 - 2/11/2010



Photograph 13 – General facility conditions for Sunlink, 1650 Neptune Drive. No industrial materials, activities, or equipment exposed to storm water were observed.



Photograph 14 – Facility sign for Zablocki Printing Company, 1625 Neptune Drive.



Photograph 15 – Facility sign for Datapark Group and Inter Technomics, 1631 and 1635 Neptune Drive.



Photograph 16 – General facility conditions for Zablocki Printing, Datapark Group, and Inter Technomics. No industrial materials, activities, or equipment exposed to storm water were observed.

# Site Photographs

Facilities Not Requiring Permit Coverage  
San Leandro  
Alameda County, California

Photograph Date: 2/8/2010 - 2/11/2010



2/8/10

Photograph 17 – Entrance to American Truck & Fleet as seen from within facility.



2/8/10

Photograph 18 – Drums of waste oil stored next to covered area and not provided with containment.



2/8/10

Photograph 19 – Batteries stored without coverage or containment on east side of maintenance building.



2/8/10

Photograph 20 – Entrance to Saia Motor Freight Line facility. Note the obsolete vehicle maintenance building in southeast corner of facility.

# Site Photographs

Facilities Not Requiring Permit Coverage  
San Leandro  
Alameda County, California

Photograph Date: 2/8/2010 - 2/11/2010



Photograph 21 - Paradiso Mechanical at 2600 Williams Street. The SIC code for this facility (1799 - Special Trade Contractors) does not require coverage under the Permit.



Photograph 22 - Patent Construction Systems at 2575 Williams Street. The SIC code for this facility (7359 - Equipment Rental and Leasing) does not require coverage under the Permit.



Photograph 23 - Medallion at 2434 Polvorosa Drive. The SIC code for this facility (5023 - Home furnishings) does not require coverage under the Permit.



Photograph 24 - Nan Fang at 2100 Williams Street. The SIC code for this facility (5013 - Motor Vehicle Supplies and New Parts) does not require coverage under the Permit.

# Site Photographs

Facilities Not Requiring Permit Coverage  
San Leandro  
Alameda County, California

Photograph Date: 2/8/2010 - 2/11/2010



Photograph 25 – Additional view of Nan Fang facility shown in Photo 18.



Photograph 26 – Interstate Plastics at 2065 Williams Street. The SIC code for this facility (5099 – Durable Goods) does not require coverage under the Permit.